


Tornado Damage Path Detection — Random Forest Baseline Showcase

TOR5 (Dice/F1: 0.293)

TOR5 — Tornado Damage Path Prediction



Readable pixels (full scene): 236,817 Predicted damage: 175,120 NWS-labeled damage: 34,184
Precision: 0.175 Recall: 0.898 Dice/F1: 0.293 Readable in view: 92%
Note: cropped to NWS path/polygon extent (clipped to readable imagery). Random Forest baseline — trained only on readable BEFORE/AFTER windows.

TOR7 (Dice/F1: 0.000)

TOR7 — Tornado Damage Path Prediction



Readable pixels (full scene): 166,149 Predicted damage: 1,231 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 59%
Note: cropped to NWS path/polygon extent (clipped to readable imagery). Random Forest baseline — trained only on readable BEFORE/AFTER windows.

TOR10 (Dice/F1: 0.000)

TOR10 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,288 Predicted damage: 2,517 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 66%
Note: cropped to NWS path/polygon extent (clipped to readable imagery). Random Forest baseline — trained only on readable BEFORE/AFTER windows.

TOR11 (Dice/F1: 0.000)


TOR11 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,300 Predicted damage: 1,134 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 66%
Note: cropped to NWS path/polygon extent (clipped to readable imagery). Random Forest baseline — trained only on readable BEFORE/AFTER windows.

TOR12 (Dice/F1: 0.000)

TOR12 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,092 Predicted damage: 3,747 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 64%
Note: cropped to readable-data extent (NWS path crosses this scene but outside readable imagery). Random Forest baseline — trained only on readable

TOR13 (Dice/F1: 0.464)

TOR13 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,089 Predicted damage: 15,921 NWS-labeled damage: 11,041
Precision: 0.393 Recall: 0.566 Dice/F1: 0.464 Readable in view: 64%
Note: cropped to NWS path/polygon extent (clipped to readable imagery). Random Forest baseline — trained only on readable BEFORE/AFTER windows.

TOR15 (Dice/F1: 0.000)


TOR15 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,315 Predicted damage: 3,373 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 64%
Note: cropped to predicted-damage extent (no NWS geometry in scene). Random Forest baseline — trained only on readable BEFORE/AFTER windows.
No NWS path/polygon geometry intersects this raster's extent.

TOR16 (Dice/F1: 0.000)

TOR16 — Tornado Damage Path Prediction



Readable pixels (full scene): 56,180 Predicted damage: 73 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 36%
Note: cropped to predicted-damage extent (no NWS geometry in scene). Random Forest baseline — trained only on readable BEFORE/AFTER windows.
No NWS path/polygon geometry intersects this raster's extent.

TOR18 (Dice/F1: 0.000)


TOR18 — Tornado Damage Path Prediction



Readable pixels (full scene): 258,564 Predicted damage: 67 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 66%
Note: cropped to predicted-damage extent (no NWS geometry in scene). Random Forest baseline — trained only on readable BEFORE/AFTER windows.
No NWS path/polygon geometry intersects this raster's extent.

TOR24 (Dice/F1: 0.000)

TOR24 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,281 Predicted damage: 62 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 71%
Note: cropped to predicted-damage extent (no NWS geometry in scene). Random Forest baseline — trained only on readable BEFORE/AFTER windows.
No NWS path/polygon geometry intersects this raster's extent.

TOR61 (Dice/F1: 0.000)

TOR61 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,191 Predicted damage: 4,057 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 64%
Note: cropped to predicted-damage extent (no NWS geometry in scene). Random Forest baseline — trained only on readable BEFORE/AFTER windows.
No NWS path/polygon geometry intersects this raster's extent.

TOR62 (Dice/F1: 0.000)

TOR62 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,009 Predicted damage: 974 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 64%
Note: cropped to predicted-damage extent (no NWS geometry in scene). Random Forest baseline — trained only on readable BEFORE/AFTER windows.
No NWS path/polygon geometry intersects this raster's extent.

TOR66 (Dice/F1: 0.000)


TOR66 — Tornado Damage Path Prediction



Readable pixels (full scene): 196,271 Predicted damage: 72 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 65%
Note: cropped to predicted-damage extent (no NWS geometry in scene). Random Forest baseline — trained only on readable BEFORE/AFTER windows.
No NWS path/polygon geometry intersects this raster's extent.

TOR68 (Dice/F1: 0.000)

TOR68 — Tornado Damage Path Prediction



Readable pixels (full scene): 186,929 Predicted damage: 1 NWS-labeled damage: 0
Precision: 0.000 Recall: 0.000 Dice/F1: 0.000 Readable in view: 61%
Note: cropped to NWS path/polygon extent (clipped to readable imagery). Random Forest baseline — trained only on readable BEFORE/AFTER windows.