

Division

M - Corona Bakery Process

Analysis By:

Manager 1:

Ken Mickle

Manager 2:

Jack Mendoza

Date

Mar 06, 2019

Operation 1

Peking Noodle - L.A.

Attach Picture/Documentation



[IMG_0858.JPG](#)



[IMG_0851.JPG](#)



[IMG_0831.JPG](#)



[IMG_0847.JPG](#)



[IMG_0854.JPG](#)

Required and/or Recommended Personal Protective Gear

Reflective vest or uniform.

Slip resistant work shoes.

Work gloves.

Safety cones.

Safety glasses

Job Description

Exchanging empty compactor for a full compactor at customer site.

Potential Hazards

Heavy traffic on street where entry and exit point is located.

Low hanging electrical wires at entry/exit point

Heavy pedestrian, pallet jack, automobile and commercial vehicle traffic.

Compactor located on a slight downgrade.

Slip and/or trip hazard on wet, oily and uneven asphalt.

Crush hazard if compactor rolls down hill or truck cable fails.

Parked cars adjacent to loading /unloading area.

Electrical shock hazard when disconnecting/reconnecting compactor power

Possible hydraulic oil release when disconnecting/reconnecting hydraulic lines to compactor.

Possible crush/roll hazard when disconnecting stabilizing chain binder from compactor

Hazard Prevention

Use extreme caution when entering/exiting site due to heavy traffic flow

Make sure truck rails are completely lowered if having to pull into entry point during compactor exchange to avoid low electrical lines.

Follow approved SOP procedures at all times.

Keep all pedestrian, pallet jack, automobile and commercial traffic away from loading/unloading area at all times while transferring compactors

use safety cone and hazard lights at all times while transferring.

Be aware of surroundings at all times.

Make sure hydraulic hose connections are properly connected.

Use caution when connecting/disconnecting electrical power

Never stand in front or rear of unit during loading/unloading operation

Operation 2

continued

Attach Picture/Documentation



[IMG_0869.JPG](#)




[IMG_0865.JPG](#)



[IMG_0859.JPG](#)



[IMG_0862.JPG](#)



[IMG_0864.JPG](#)

Operation 3

continued

Attach Picture/Documentation



[IMG_0813.JPG](#)



[IMG_0820.JPG](#)



[IMG_0802.JPG](#)



[IMG_0801.JPG](#)



[IMG_0803.JPG](#)