National RV
NRVIA
Inspectors Association

# RV Inspection Report

## Prepared for: Dana Hext

**RV Location:**
9024 US Hwy 175, Athens, Tx 75751




## Inspection Date / RV Model:
## 2026-6-23 / 2025 Forest River Rockwood MiniLite 2515s

VIN: 4X4TRLB23SD461721

ProfessorJerryRV

**Jerry W. Malcolm**
**13016 Scofield Farms**
**Austin, Texas 78727**
**512-589-7372**


NRVIA
CERTIFIED RV
INSPECTOR

# Table of Contents

Cover Page ..... 1
Table of Contents ..... 3
Intro Page ..... 5
Life Safety Issue ..... 7
Major Issue ..... 9
Minor Issue ..... 11
1 Vehicle Information ..... 14
2 Hot Skin Test ..... 18
3 Roof Exterior ..... 19
4(A) Front Cap / Wall ..... 27
4(B) Curbside Sidewall ..... 28
4(C) Rear Cap / Wall ..... 30
4(D) Streetside Sidewall ..... 33
5(A) Main Entry Door (Kitchen) ..... 36
5(B) Second Entry Door (Bedroom) ..... 40
6 Awnings ..... 41
7(A) Streetside - Rear Slideout (Recliners) ..... 43
7(B) Streetside - Front Slideout (Closet) ..... 44
8(A) Curbside - Front Wheel Assembly ..... 45
8(B) Curbside - Rear Wheel Assembly ..... 47
8(C) Streetside - Rear Wheel Assembly ..... 49
8(D) Streetside - Front Wheel Assembly ..... 51
8(E) Spare Tire Assembly ..... 53
9 Hitch and Stabilizing System ..... 54
10 Running Gear ..... 57
11 12-Volt DC Chassis Lights ..... 60
13 Exterior Water Systems ..... 61
14 Propane Container(s), Lines and Connections ..... 67
15 LP System Leak Test ..... 69
16 Life Safety Components ..... 70
17 Electrical System 120-Volts AC and 12-Volts

DC ..... 74
18 Appliances: Kitchen ..... 82
19 Appliances: Other ..... 84
20(A) Front Air Conditioner (Zone 2 - Bedroom) ..... 85
20(B) Rear Air Conditioner (Zone 1 - Living Rm / Kitchen) ..... 88
21 Interior Water Systems ..... 89
22 Interior ..... 93
23 Furniture ..... 97
24(A) Living Room Television ..... 98
24(B) Radio / Stereo ..... 99
24(C) Backup Camera ..... 99
24(D) Front-Facing Camera ..... 100

| **Inspection Date / Year,Make,Model :** | **Time:** | **VIN Number:** |
|---|---|---|
| 2026-6-23 / 2025 Forest River Rockwood MiniLite 2515s | | 4X4TRLB23SD461721 |

| **RV Location:** | **Customer:** |
|---|---|
| 9024 US Hwy 175, Athens, Tx 75751 | Dana Hext |

**This time sensitive document was prepared for the client listed on the Cover Page of this report. Any reproduction, use, or resale of this document by individuals other than who is listed on the report cover page, or their assigns, is not supported by the inspector and company.**

**Comment Key or Definitions**

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this RV home. Any recommendations by the inspector to repair suggests further action by a qualified RV technician. All costs associated with repair or replacement of items and components identified in this report should be considered before purchasing this RV home..

**Acceptable (A)** = A visually observed item, component or unit and if no other comments were made then it appeared to be performing its intended function with little or no deterioration visible.

**Fair (F)**= The item or its components is not in need of immediate repair as it is performing its intended function but deterioration is visible. Some may elect to repair or replace this item now while others may wait.

**Poor (P)** = The item, component or unit is not functioning as intended and replacement is recommended, or needs further action by a qualified RV technician.

**Not Inspected (NI)**= The item, unit or component was not inspected, and no representations were made as to whether or not it was functioning as intended and a statement for the reason for not inspecting will be made.

**Not Present (NP)** = This item, component or unit is not in this RV.

**NRVIA Standards of Practice**

**Purpose, Scope and General Statements**

1 - The purpose of the Standards of Practice is to establish a uniform standard for the companies RV Inspector to inspect and report in an objective manner the conditions of a Recreational Vehicle and its components.

2 - The Standards describe the components, and systems included in an RV Inspection.

3 - The Standards apply to motorized and towable types of RVs as defined by the RV Industry.

4 - The Standards apply to a visual inspection of those areas, components and systems that are readily accessible to determine at the time of inspection that they are performing their intended function without regard to life expectancy.

5 - The purpose of the RV inspection is to identify visible and operational defects as permitted by the current conditions that in the judgment of the RV Inspector will adversely affect the function or integrity of the items, components and systems of the Recreational Vehicle.

6 - RV Inspections performed under the Standards of Practice are basically visual and rely upon the judgment, education and experience of the RV Inspector and are not intended to be technically exhaustive.

7 - RV inspections shall be performed on a calendar day which will allow compliance with the provisions of the NRVIA Standards of Practice.

8 - RV Inspections performed under the Standards shall not be construed as being a compliance inspection of any code, governmental regulation or manufacturer's installation instructions or procedures. In the event a law, statute or ordinance prohibits a procedure recommended in the Standards, the RV Inspector is relieved of the obligation to adhere to the prohibited part of the Standards.

9 - RV Inspections performed under the Standards are not an expressed, implied warranty or guarantee of adequacy, performance or useful life of any RV, any of its components or systems.

10 - Only those items specifically listed on the RV Inspection Report will be included in the RV Inspectors evaluation.

11 - The RV Inspector shall report any system or component included in the Standards of Practice which were present at the time of the RV Inspection but were NOT inspected and provide the reason they were not inspected.

**General Limitations and Exclusions**

1 - RV Inspections performed under the companies Standards of Practice exclude any items concealed or not readily accessible to the RV Inspector. The RV Inspector is not required to move furniture, personal or stored items. Lifting floor covering, accessing interior walls and ceilings in which could damage or destroy the components or systems being evaluated is not part of the RV Inspection.

2 - The determination of the presence of damage caused by insects or water is only to be evaluated by observation with a statement being rendered by RV Inspector that is to make the client aware of the issue.

3 - Excluded from the Standards of Practice is the determination of indoor air quality of the RV and it's consequence of physical damage, toxicity, odors, waste products and noxiousness.

4 - The RV Inspection and report are based upon the visual observation of the existing conditions of the RV at the time of the RV Inspection. The report is not intended to be or construed as a guarantee, warranty or any form of insurance. The RV Inspector will not be responsible for any repairs or replacement with regard to the RV or its contents.

5 - The RV Inspector is not required to enter any premises that visibly show a threat to the safety of the RV Inspector or others nor inspect any area or component that poses a danger to the RV Inspector or others.

6 - The NRVIA Certified RV Inspector inspected and reported on the RV items listed in this report and their condition during the RV Inspection. Any additional items of inspection were dependent upon any agreements that were made between the client and the RV Inspector.

| **Weather:** | **Type of Inspection:** | **Style of RV:** |
|---|---|---|
| Clear & Windy | Other | Travel Trailer |
| **RV Status:** | **Client Is Present:** | **Start Temperature:** |
| Occupied at the Time of the Inspection | Yes | 85 degrees |

# Life Safety Issue

National RV NRVIA Inspectors Association

**ProfessorJerryRV**

**Customer**
Dana Hext
**Inspection Date / Year,Make,Model:**
2026-6-23 / 2025 Forest River Rockwood MiniLite 2515s
**VIN Number:**
**4X4TRLB23SD461721**

**The following items indicate that the condition is a LIFE SAFETY ISSUE. It is recommended that a qualified RV technician correct the identified issue, and before the unit is occupied.**

## 8(A) . Curbside - Front Wheel Assembly

**8.2.A Tire Tread - Condition**

**Poor**
The curbside front tire tread depth is less than the recommended value. This is a LIFE SAFETY ISSUE. It is recommended that this be further evaluated by a qualified RV technician prior to towing.

## 8(B) . Curbside - Rear Wheel Assembly

**8.2.B Tire Tread - Condition**

**Poor**
The curbside rear tire tread depth is less than the recommended value. This is a LIFE SAFETY ISSUE. It is recommended that this be further evaluated by a qualified RV technician prior to towing.

## 8(C) . Streetside - Rear Wheel Assembly

**8.2.C Tire Tread - Condition**

**Poor**
The streetside rear tire tread depth is less than the recommended value. This is a LIFE SAFETY ISSUE. It is recommended that this be further evaluated by a qualified RV technician prior to towing.

## 8(D) . Streetside - Front Wheel Assembly

**8.2.D Tire Tread - Condition**

**Poor**
The streetside front tire tread depth is less than the recommended value. This is a LIFE SAFETY ISSUE. It is recommended that this be further evaluated by a qualified RV technician prior to towing.

## 8(E) . Spare Tire Assembly

**8.1.E Tire/Rim - Condition**

**Poor**

The spare tire pressure is below the recommended value. This is a LIFE SAFETY issue. It is recommended that this be further evaluated by a qualified RV technician prior to towing.

---

*Prepared Using HomeGauge http://www.HomeGauge.com* : Licensed To Jerry W. Malcolm

# Major Issue

National RV NRVIA Inspectors Association

**ProfessorJerryRV**

**Customer**
Dana Hext
**Inspection Date / Year,Make,Model:**
2026-6-23 / 2025 Forest River Rockwood MiniLite 2515s
**VIN Number:**
**4X4TRLB23SD461721**

**The following items indicate that the condition is a MAJOR ISSUE. It is recommended that a qualified RV technician correct the identified issue as needed.**

## 3. Roof Exterior

**3.1 Front Cap, Joints and Seals - Condition**

**Poor**

The streetside front cap seal has a protrusion. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.

## 4(D) . Streetside Sidewall

**4.0.D Sidewall - Condition**

**Poor**

There is extensive damage to the streetside side wall J skirt from halfway back to the slideout. The J skirt has been removed in that section and damage exists on the portion that is still present. It is recommended that this be further evaluated by a qualified RV technician.

## 5(A) . Main Entry Door (Kitchen)

**5.0.A Door - Condition**

**Poor**

The pull-up accordion shade in the main entry (kitchen) door will not remain closed. It is recommended that this be further evaluated by a qualified RV technician.

## 9. Hitch and Stabilizing System

**9.3 Travel Trailer - Stabilizers - Condition**

**Poor**

The streetside rear stabilizer is not operational. It is currently in the retracted state. It is recommended that this be further evaluated by a qualified RV technician.

## 17. Electrical System 120-Volts AC and 12-Volts DC

### 17.31 Power Converter - Operation - Minimum 0.5 Volt DC Drop

**Poor**

The power converter voltage difference is 0.3 volt DC drop. This is less than the recommended 0.5 volt DC drop. It is recommended that this be further evaluated by a qualified RV technician.

## 21. Interior Water Systems

### 21.8 Toilet - Bowl Holds Water

**Poor**

The bowl does not hold water. It is recommended that this be evaluated by a qualified RV technician.

## 22. Interior

### 22.1 System Controls / Switches - Operation

**Poor**

On the interior system control panel, the Bluetooth button does not light up when pressed. It is recommended that this be further evaluated by a qualified RV technician.

---

*Prepared Using HomeGauge http://www.HomeGauge.com* : Licensed To Jerry W. Malcolm

# Minor Issue

**ProfessorJerryRV**

**Customer**
Dana Hext
**Inspection Date / Year,Make,Model:**
2026-6-23 / 2025 Forest River Rockwood MiniLite 2515s
**VIN Number:**
**4X4TRLB23SD461721**

**The following items indicate that the condition is a MINOR ISSUE. It is recommended that a qualified RV technician correct the identified issue as needed.**

## 4(A) . Front Cap / Wall

**4.1.A Paint and/or Decals - Condition**

**Fair**

(1) There are some chips in the front cap wall paint and decals. It is recommended that this be further evaluated by a qualified RV technician.

## 4(B) . Curbside Sidewall

**4.3.B Cargo/Access Doors - Condition**

**Fair**

There are scratches on the curbside side wall cargo door. It is recommended that this be further evaluated by a qualified RV technician.

## 4(C) . Rear Cap / Wall

**4.1.C Paint and/or Decals - Condition**

**Fair**

(1) There is sealant overflow on the rear cap streetside about halfway up and again closer to the top. It is recommended that this be further evaluated by a qualified RV technician.

(2) There are scuff marks on the rear cap streetside. It is recommended that this be further evaluated by a qualified RV technician.

## 4(D) . Streetside Sidewall

**4.3.D Cargo/Access Doors - Condition**

**Fair**

The streetside side wall cargo access door has scratches. It is recommended that this be further evaluated by a qualified RV technician.

## 5(A) . Main Entry Door (Kitchen)

**5.1.A Door - Operation**

**Fair**

The main entry door squeaks when opening. It is recommended that this be further evaluated by a qualified RV technician.

## 6. Awnings

**6.2 Fabric - Condition**

**Fair**

(1) The awning has three tears close to the wall above the bedroom door. It is recommended that this be further evaluated by a certified RV technician.

(2) The awning has a tear close to the wall near the rear cap. It is recommended that this be further evaluated by a certified RV technician.

## 9. Hitch and Stabilizing System

**9.0 Travel Trailer - Tongue Jack - Condition**

**Fair**

The light switch on the motorized tongue jack is not present. It is recommended that this be further evaluated by a qualified RV technician.

## 13. Exterior Water Systems

**13.0 City Water - Connection - Condition**

**Fair**

The city water inlet connection screen has some debris on it. It is recommended that this be further evaluated by a qualified RV technician.

**13.12 Black Water Tank #1 - Condition**

**Fair**

The black tank flush inlet's washer is present, but is missing the filter screen. It is recommended that this be further evaluated by a qualified RV technician.

**13.13 Black Water Tank #1 - Valve Operation and Condition**

**Fair**

The black water tank valve is tight. It is recommended that this be further evaluated by a qualified RV technician.

**13.25 Gray Water Tank #1 - Valve Operation and Condition**

**Fair**

The gray water tank #1 valve is tight. It is recommended that this be further evaluated by a qualified RV technician.

**13.31 Gray Water Tank #2 - Valve Operation and Condition**

**Fair**

The gray water tank #2 valve is tight. It is recommended that this be further evaluated by a qualified

RV technician.

## 21. Interior Water Systems

### 21.7 Toilet - Operation and Condition

**Fair**

There is discoloration in the bowl near some of the water inlets. It is recommended that this be evaluated by a qualified RV technician.

## 22. Interior

### 22.36 Interior Doors - Condition

**Fair**

There are scrapes at the bottom, bathroom-side, of the sliding doors between the bathroom and bedroom. It is recommended that this be further evaluated by a qualified RV technician.

---

*Prepared Using HomeGauge http://www.HomeGauge.com* : Licensed To Jerry W. Malcolm

# 1. Vehicle Information

## Styles & Materials

**VIN:**
Photo Included
VIN : 4X4TRLB23SD461721

**VIN Location:**
Streetside Front

**Gross Vehicle Weight Rating (GVWR):**
From Data Plate
Specify in lbs or kg : 3484 lbs

**RV - Manufacturer Name and Location:**
Forest River / Wakarusa, IN

**RV - Date of Manufacturer:**
August
Year : 2024

**RV - Brand:**
Manufacturer's Brand Name
Brand Name : Rockwood

**RV - Model Number / Floor Plan Number:**
RV Model
Model Number : 2515s

**RVIA Seal Number:**
Located by Entrance Door
Seal Number : B2388061

**State Inspection Sticker Current:**
Not Required


**State License Plate Current:**
Yes
State and Plate Number : B74-6223

## Items

**1.0 VIN / VIN Data Plate Photo**


Yes

(1) Overview




VIN Data Plate

(2) Overview




Tire Data Plate

**1.1 RVIA Seal Photo**

Yes

Overview




RVIA Seal

**1.5 State License Plate Photo**

Yes

Overview





License Plate

**1.7 Build Sheet Photo**

Yes

Overview



| Plant 10B Appliance Information Sheet | | DATE RECORDED | UNIT SERIAL# |
|---|---|---|---|
| | | 8/20/2024 | RLD461721 |
| | MANUFACTURER | MODEL# | SERIAL # |
| Frames | LCI | 2515S | S012218392 |
| Axles | Dexter | 3500# | 611629341 |
| | | | 611629341 |
| Water Heater | Suburban | SW6DELC | 2431014502 |
| Water Pump | SEAFLO | SFDP1-030-045-33 | DP33240601611012 |
| Toilet | Thetford | 42070 | 43290673 |
| One Control | LCI | Unity X270D 2023018428 | 30606H2222400147 |
| Transfer switch | Arterra | EM-15 | 09W228600817 |
| | | EM-15 | 09W228600785 |
| Inverter | | WF-5318 | AC08T23C610823 |
| Converter | Cheng | WF-8955-AD-WEGO | AC04W243604945 |
| Air Conditioner | Coleman | 48000 Series MACH 3 Softstart | 240201577 |
| | | 48000 Series MACH 3 Softstart | 240201576 |
| Solar Panel | Go Power | GP-PV-200M | 200-0004411-202405 |
| Solar Panel #2 | | GP-PV-200M | |
| Solar Panel #3 | | GP-PV-200M | |
| Solar-Control | Go Power | GP-SB-PWM-30-BT | 01802410273 |
| Refrigerator | Dometic | DM2872LB4 | 240401333 |
| | Dometic | DM2872RB4 | |
| | Magic Chef | MCDCR10DSBMFB | |
| Awning | Lippert | V000614365 | RPO-12729511 |
| Slide topper | Lippert | V000430180 | RPO- |
| Slide topper | Lippert | V000432280 | RPO- |
| Tire | GOODYEAR | ST205.75R14D | DOT 1PJKCA51V 2124 |
| | GOODYEAR | ST205.75R14D | DOT 1PJKCA51V 2124 |
| | GOODYEAR | ST205.75R14D | DOT 1PJKCA51V 2124 |
| | GOODYEAR | ST205.75R14D | DOT 1PJKCA51V 2224 |
| Spare Tire | TAMARACK | ST205.75R14D | DOT 00K JTYLCT 2124 |
| Furnace | Suburban | NT 20SQ | |
| | | SF 20VHQ | |
| | | SF-35VHQ | 2432003974 |
| Fireplace | Covenant | WD914-26LT | |
| Outside Refer | GE | GME04GGKBBB | |
| | Everchill | BC-46-E | |
| Microwave | Magic Chef | MCG992ARS | 24050501262 |
| Range/Oven | Magic Chef | MCFR21TTB2 | 05245024389 |
| Range Outside | Suburban | SDN2U | |
| E Center TV | Connex | CX32A24ETVDCS | 0624-077-0061 |
| Bedroom TV | Connex | CX27A23DCS | |
| Entry Door | Global | Key-A-Like | 361 |
| RVIA | | | B238061 |

Build Sheet


### 1.8 Manuals

Yes

Overview




Manuals




Manuals

## 2. Hot Skin Test

**NOTE: Hot Skin is when stray or leak voltage from the 120 voltage AC system is somehow redirected from its normally safe path to some metal component(s) of your RV.**

**NOTE: Most hot skin issues may not be a direct short of power to ground but rather a high resistive short. In many cases, they may not trip the circuit breakers or blow fuses. However, the frame, chassis, copper tubing and metal trim pieces on the coach can conduct voltage.**

**NOTE: Any reading below 5 volts is considered safe. Conversely, any reading above 5 volts can be dangerous.**

## Items

**2.0 Hot Skin Test - Frame and Running Gear Voltage**
Acceptable

**2.1 Hot Skin Test - Exterior Wall Surface Voltage**
Acceptable

**2.2 Hot Skin Test - Door Handles and Frames Voltage**
Acceptable

**2.3 Hot Skin Test - Window Frames and Trim Voltage**
Acceptable

**2.4 Hot Skin Test - Other Voltage**
Acceptable

# 3. Roof Exterior

**NOTE: Lap sealant should appear soft, pliable and rubbery. If the lap sealant around roof edges, skylights, vents and appliances looks cracked, brittle, loose or turned up at the edges, it is very possible that this could allow water intrusion which can become a major issue.**

**NOTE: It is recommended that the roof and seams be checked, at a minimum, every 6 months and repaired whenever necessary to prevent water intrusion.**

## Styles & Materials

**Roof Type:**
TPO (Rubber)

**Areas of Possible Water Intrusion:**
Yes

**Roof Ladder Type:**
Mounted

**Number of Solar Panels:**
One

## Items

**3.0 Roof - Condition**
Acceptable
(1) Overview




Roof Overview Rear to Front




Roof Overview Front to Rear

(2) Repair work has been performed on the streetside from the middle to the front.



Roof Streetside Middle




Roof Streetside Middle

**3.1 Front Cap, Joints and Seals - Condition**

Poor

The streetside front cap seal has a protrusion. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



Front Cap Streetside



Streetside Front Cap Seal

**3.2 Trim Rail (Curbside) - Condition**

Acceptable

**3.3 Rear Cap, Joints and Seals - Condition**

Acceptable

**3.4 Trim Rail (Streetside) - Condition**

Acceptable

**3.5 Vents - Manual Crank (14 x 14) - Condition**

Acceptable

Overview




Vent Fan with Exterior Shroud Attached




Vent Fan Cover Open



Vent Cover with Exterior Shroud Removed Showing Shroud Cotter Pins

**3.6 Vents - Powered (14 x 14) - Condition**

Acceptable

**3.7 Exterior Vent Covers - Condition**

Acceptable

**3.8 Plumbing Vent Covers - Condition**

Acceptable

**3.10 Skylights - Condition**

Acceptable

Overview



Skylight

**3.11 Front Air Conditioner - Shroud**

Acceptable

**3.12 Front Air Conditioner - Exterior Coils**

Acceptable

**3.15 Rear Air Conditioner - Shroud**

Acceptable

**3.16 Rear Air Conditioner - Exterior Coils**

Acceptable

**3.22 Solar Panels - Condition**

Acceptable

Overview



Solar Panel

**3.23 Ladder - Condition**

Acceptable

## 4(A) . Front Cap / Wall

### Styles & Materials

**Exterior Wall - Construction Type:**
Molded Fiberglass Cap

**Exterior Wall - Surface Type:**
Paint with Decals

**Any Damage or Discoloration or Delamination?:**
No

**Windows:**
Glass with No Frame

**Cargo / Access Door - Type:**
None

### Items


**4.0.A Sidewall - Condition**

Acceptable

**4.1.A Paint and/or Decals - Condition**

Fair

(1) There are some chips in the front cap wall paint and decals. It is recommended that this be further evaluated by a qualified RV technician.



Front Cap

(2) On the front cap on the top curve, the decals have a slight amount of streaking. It is recommended that this be further evaluated by a qualified RV technician.




Front Cap

**4.2.A Windows - Condition**

Acceptable

## 4(B) . Curbside Sidewall

### Styles & Materials

**Exterior Wall - Construction Type:**
Hung Fiberglass Panel

**Exterior Wall - Surface Type:**
Paint with Decals

**Any Damage or Discoloration or Delamination?:**
No

**Windows:**
Glass with No Frame

**Cargo / Access Door - Type:**
Door(s) with Keyed Lock

### Items

**4.0.B Sidewall - Condition**

Acceptable

**4.1.B Paint and/or Decals - Condition**

Acceptable

**4.2.B Windows - Condition**

Acceptable

**4.3.B Cargo/Access Doors - Condition**

Fair

There are scratches on the curbside side wall cargo door. It is recommended that this be further evaluated by a qualified RV technician.



Curbside Cargo Access Door

**4.4.B Cargo Interior Compartment - Condition**

Not Inspected

The curbside cargo interior compartment is not accessible



Curbside Cargo Compartment

**4.5.B Cargo Interior Compartment Lights - Operation**

Acceptable

# 4(C) . Rear Cap / Wall

## Styles & Materials

**Exterior Wall - Construction Type:**
Hung Fiberglass Panel

**Exterior Wall - Surface Type:**
Paint with Decals

**Any Damage or Discoloration or Delamination?:**
No

**Windows:**
Glass with No Frame

**Cargo / Access Door - Type:**
None

## Items

**4.0.C Sidewall - Condition**

Acceptable

(2) There are some black marks behind the ladder on the left side just to the left of the window on the rear cap. It is recommended that this be further evaluated by a qualified RV technician.





Rear Cap

**4.1.C Paint and/or Decals - Condition**

Fair

(1) There is sealant overflow on the rear cap streetside about halfway up and again closer to the top. It is recommended that this be further evaluated by a qualified RV technician.



Rear Cap Streetside



Rear Cap Streetside

(2) There are scuff marks on the rear cap streetside. It is recommended that this be further evaluated by a qualified RV technician.



Rear Cap Streetside

**4.2.C Windows - Condition**

Acceptable

## 4(D) . Streetside Sidewall

### Styles & Materials

**Exterior Wall - Construction Type:**
Hung Fiberglass Panel

**Exterior Wall - Surface Type:**
Paint with Decals

**Any Damage or Discoloration or Delamination?:**
No

**Windows:**
Glass with No Frame


**Cargo / Access Door - Type:**
Door(s) with Keyed Lock

## Items

### 4.0.D Sidewall - Condition

Poor

There is extensive damage to the streetside side wall J skirt from halfway back to the slideout. The J skirt has been removed in that section and damage exists on the portion that is still present. It is recommended that this be further evaluated by a qualified RV technician.



Area With Missing Streetside J Skirt




Streetside J Skirt

### 4.1.D Paint and/or Decals - Condition

Acceptable

**4.2.D Windows - Condition**

Acceptable

**4.3.D Cargo/Access Doors - Condition**

Fair

The streetside side wall cargo access door has scratches. It is recommended that this be further evaluated by a qualified RV technician.



Streetside Cargo Door

**4.4.D Cargo Interior Compartment - Condition**

Not Inspected

The streetside cargo interior compartment is not accessible.



Streetside Cargo Interior

**4.5.D Cargo Interior Compartment Lights - Operation**

Acceptable

## 5(A) . Main Entry Door (Kitchen)

### Styles & Materials

**Entrance Door - Type:**
Fiberglass

**Step System - Type:**
Manual

**Number of Steps:**
Three

**Grab Bar - Type:**
D-Ring Handle

### Items

**5.0.A Door - Condition**

Poor

The pull-up accordion shade in the main entry (kitchen) door will not remain closed. It is recommended that this be further evaluated by a qualified RV technician.



Main Entry Door (Kitchen) Shade

**5.1.A Door - Operation**

Fair

The main entry door squeaks when opening. It is recommended that this be further evaluated by a qualified RV technician.




Main Entry Door (Kitchen)




Main Entry Door (Kitchen)

**5.2.A Screen Door - Condition**
Acceptable

**5.3.A Screen Door - Operation**
Acceptable

**5.4.A Keyed Door Lock - Operation**
Acceptable

**5.5.A Keyed Door Lock - Deadbolt Operation**
Acceptable

**5.6.A Keyless Entry - Door Lock Function**
Acceptable

Overview




Main Entry Door Keyless Lock

**5.7.A Steps - Condition**
Acceptable

**5.8.A Steps - Operation**
Acceptable

**5.9.A Grab Bar - Condition**
Acceptable

**5.10.A Grab Bar - Operation**
Acceptable

## 5(B) . Second Entry Door (Bedroom)

### Styles & Materials

**Entrance Door - Type:**
Fiberglass

**Step System - Type:**
Manual

**Number of Steps:**
Three

**Grab Bar - Type:**
D-Ring Handle

### Items

**5.0.B Door - Condition**
Acceptable

**5.1.B Door - Operation**
Acceptable

**5.2.B Screen Door - Condition**
Acceptable

**5.3.B Screen Door - Operation**
Acceptable

**5.4.B Keyed Door Lock - Operation**
Acceptable

**5.5.B Keyed Door Lock - Deadbolt Operation**
Acceptable

**5.7.B Steps - Condition**
Acceptable

**5.8.B Steps - Operation**
Acceptable

**5.9.B Grab Bar - Condition**
Acceptable

**5.10.B Grab Bar - Operation**
Acceptable

## 6. Awnings

### Styles & Materials

**Awning - Brand:**
Solera

**Awning - Type:**
Electric

**Awning - Material:**
Vinyl

**Awning - Metal Cover:**
No

**Awning - Length:**
18 Feet


### Items

**6.0 Awning - Operation**
Acceptable

**6.1 Frame and Latching Mechanism - Operation**
Acceptable

**6.2 Fabric - Condition**
Fair

(1) The awning has three tears close to the wall above the bedroom door. It is recommended that this be further evaluated by a certified RV technician.



Awning View From Roof

(2) The awning has a tear close to the wall near the rear cap. It is recommended that this be further evaluated by a certified RV technician.



Awning View From Roof

**6.3 Awning Lights - Condition**

Acceptable

## 7(A) . Streetside - Rear Slideout (Recliners)

### Styles & Materials

**Slideout Roof Type:**
Fiberglass

**Slideout Drive System:**
Electric Motor / Gear and Rack System

### Items

**7.0.A Slideout - Operation**

Acceptable

**7.1.A Slideout - Alignment**

Acceptable

**7.2.A Slideout - Roof**
Acceptable

**7.3.A Slideout - Sidewall**
Acceptable

**7.4.A Slideout - T-Molding Trim**
Acceptable

**7.5.A Seals, Sweeps and Gaskets**
Acceptable

**7.6.A Slideout - Override System**
Acceptable

**7.7.A Slideout Rail - Gear Rack System**
Acceptable

**7.8.A Wiring Harness under Slideout**
Acceptable

**7.9.A 12-Volt DC Control and Switches**
Acceptable

## 7(B) . Streetside - Front Slideout (Closet)

### Styles & Materials

**Slideout Roof Type:**
Fiberglass

**Slideout Drive System:**
Lippert Schwintek / In-wall Electric Motor

### Items

**7.0.B Slideout - Operation**
Acceptable

**7.1.B Slideout - Alignment**
Acceptable

**7.2.B Slideout - Roof**
Acceptable

**7.3.B Slideout - Sidewall**
Acceptable

**7.4.B Slideout - T-Molding Trim**
Acceptable

**7.5.B Seals, Sweeps and Gaskets**
Acceptable

**7.6.B Slideout - Override System**
Acceptable

**7.7.B Slideout Rail - Gear Rack System**
Acceptable

**7.8.B Wiring Harness under Slideout**
Acceptable

**7.9.B 12-Volt DC Control and Switches**
Acceptable

# 8(A) . Curbside - Front Wheel Assembly

**NOTE: The National Transportation Safety Board (NTSB) and some tire manufacturers are recommending that all tires older than six years should be replaced, regardless of their condition.**

## Styles & Materials

**Tire Brand:**
Goodyear

**Tire Size:**
205/75R14
Other
Size : ST205/75R14

**DOT Date:**
Visually Verified
DOT Date Code (WWYY) : 2224

**Load Capacity:**
Single Tire Rating
lbs or kg : 2040 lbs

**Load Range:**
D

**Tire - Maximum Cold Inflation Pressure:**
65 PSI

**Tire - RV Manufacturer's Recommended Inflation Pressure:**
65 PSI

**Tire - Current Air Pressure:**
Tire Gauge Reading
PSI : 61.4

## Items

**8.0.A Tire - Age**
Acceptable

**8.1.A Tire/Rim - Condition**
Acceptable

**8.2.A Tire Tread - Condition**
Poor

The curbside front tire tread depth is less than the recommended value. This is a LIFE SAFETY ISSUE. It is recommended that this be further evaluated by a qualified RV technician prior to towing.



Curbside Front Tire



Curbside Front Tire



Curbside Front Tire



Curbside Front Tire

**8.4.A Tire Pressure Monitor System**

Yes

## 8(B) . Curbside - Rear Wheel Assembly

### Styles & Materials

**Tire Brand:**
Goodyear

**Tire Size:**
Other
Size : ST205/75R14

**DOT Date:**
Visually Verified
DOT Date Code (WWYY) : 2224

**Load Capacity:**
Single Tire Rating
lbs or kg : 2040 lbs

**Load Range:**
D

**Tire - Maximum Cold Inflation Pressure:**
65 PSI

**Tire - RV Manufacturer's Recommended Inflation Pressure:**
65 PSI

**Tire - Current Air Pressure:**
Tire Gauge Reading
PSI : 61.2

### Items

**8.0.B Tire - Age**

Acceptable

**8.1.B Tire/Rim - Condition**

Acceptable


**8.2.B Tire Tread - Condition**

Poor

The curbside rear tire tread depth is less than the recommended value. This is a LIFE SAFETY ISSUE. It is recommended that this be further evaluated by a qualified RV technician prior to towing.



Curbside Rear Tire




Curbside Rear Tire



Curbside Rear Tire



Curbside Rear Tire

**8.4.B Tire Pressure Monitor System**

Yes

## 8(C) . Streetside - Rear Wheel Assembly

### Styles & Materials

**Tire Brand:**
Goodyear

**Tire Size:**
Other
Size : ST205/75R14

**DOT Date:**
Visually Verified
DOT Date Code (WWYY) : 2224

**Load Capacity:**
Single Tire Rating
lbs or kg : 2040 lbs

**Load Range:**
D

**Tire - Maximum Cold Inflation Pressure:**
65 PSI

**Tire - RV Manufacturer's Recommended Inflation Pressure:**
65 PSI

**Tire - Current Air Pressure:**
Tire Gauge Reading
PSI : 64.1

### Items

**8.0.C Tire - Age**

Acceptable

**8.1.C Tire/Rim - Condition**

Acceptable

**8.2.C Tire Tread - Condition**

Poor

The streetside rear tire tread depth is less than the recommended value. This is a LIFE SAFETY ISSUE. It is recommended that this be further evaluated by a qualified RV technician prior to towing.




Streetside Rear Tire




Streetside Rear Tire



Streetside Rear Tire

**8.3.C Valve Extensions - Condition**

Not Present

**8.4.C Tire Pressure Monitor System**
Yes

## 8(D) . Streetside - Front Wheel Assembly

### Styles & Materials

**Tire Brand:**
Goodyear

**Tire Size:**
Other
Size : ST205/75R14

**DOT Date:**
Visually Verified
DOT Date Code (WWYY) : 2224

**Load Capacity:**
Single Tire Rating
lbs or kg : 2040 lbs

**Load Range:**
D

**Tire - Maximum Cold Inflation Pressure:**
65 PSI

**Tire - RV Manufacturer's Recommended Inflation Pressure:**
65 PSI

**Tire - Current Air Pressure:**
Tire Gauge Reading
PSI : 58.0

### Items

**8.0.D Tire - Age**
Acceptable

**8.1.D Tire/Rim - Condition**
Acceptable

**8.2.D Tire Tread - Condition**
Poor

The streetside front tire tread depth is less than the recommended value. This is a LIFE SAFETY ISSUE. It is recommended that this be further evaluated by a qualified RV technician prior to towing.




Streetside Front Tire



Streetside Front Tire



Streetside Front Tire



Streetside Front Tire

**8.4.D Tire Pressure Monitor System**

Yes

## 8(E) . Spare Tire Assembly

### Styles & Materials

**Tire Brand:**
Other
Brand : Tamarack

**Tire Size:**
Other
Size : ST205/75R14

**DOT Date:**
Visually Verified
DOT Date Code (WWYY) : 2124

**Load Capacity:**
Single Tire Rating
lbs or kg : 2040 lbs

**Load Range:**
D

**Tire - Maximum Cold Inflation Pressure:**
65 PSI

**Tire - RV Manufacturer's Recommended Inflation Pressure:**
65 PSI

**Tire - Current Air Pressure:**
Tire Gauge Reading
PSI : 49.0

### Items

**8.0.E Tire - Age**

Acceptable

**8.1.E Tire/Rim - Condition**

Poor

The spare tire pressure is below the recommended value. This is a LIFE SAFETY issue. It is recommended that this be further evaluated by a qualified RV technician prior to towing.

**8.2.E Tire Tread - Condition**

Acceptable

Overview



Spare Tire

**8.3.E Valve Extensions - Condition**

Acceptable

**8.4.E Tire Pressure Monitor System**

No

## 9. Hitch and Stabilizing System

### Styles & Materials

**Travel Trailer - Tongue Jack:**
Electric

**Travel Trailer - Stabilizer:**
Electric

**Travel Trailer - Weight Distribution System:**
Yes

**Travel Trailer - Sway Control System:**
Yes

### Items

**9.0 Travel Trailer - Tongue Jack - Condition**

Fair

The light switch on the motorized tongue jack is not present. It is recommended that this be further evaluated by a qualified RV technician.



Tongue Jack

**9.1 Travel Trailer - Coupler - Operation**

Acceptable

**9.2 Travel Trailer - Safety Chains - Condition**

Acceptable


**9.3 Travel Trailer - Stabilizers - Condition**

Poor

The streetside rear stabilizer is not operational. It is currently in the retracted state. It is recommended that this be further evaluated by a qualified RV technician.



Correctly Extended Curbside Rear Stabilizer for Reference



Streetside Rear Stabilizer



Streetside Rear Stabilizer

## 10. Running Gear

**NOTE: Due to the lack of clearance under the RV and safety concerns, the inspector will conduct the following visual inspections from the outer perimeter of the RV.**

### Styles & Materials

**Axle - Type:**
Torsion Axle

**Axle - Quantity:**
Two

**Front Axle Weight Rating:**
lbs
Weight Rating : 3500

**Rear Axle Weight Rating:**
lbs
Weight Rating : 3500

**Brake Type:**
Electric

**Suspension Bolts - Type:**
Not Present

**Underbelly - Type:**
Enclosed

## Items

**10.0 Frame - Condition**

Acceptable

Overview



Frame Overview Back to Front



Frame Overview Front to Back

**10.1 Frame - Visible Signs of Rust**
Acceptable

**10.2 Frame - Visible Signs of Bent or Damaged Components**
Acceptable

**10.3 Frame - Visible Signs of Oil Stains**
Acceptable

**10.4 Running Gear (Axles, Springs, Other Components) - Condition**
Acceptable

**10.5 Running Gear - Scraping or Drag Damage**
Acceptable

**10.6 Axle - Visible Signs of Rust**
Acceptable

**10.7 Axle - Visible Signs of Bent or Damaged Components**
Acceptable

**10.8 Axle - Visible Signs of Oil Stains**
Acceptable

**10.16 Underbelly - Condition**
Acceptable

**10.17 Rear Hitch Receiver - Condition**
Acceptable

## 11. 12-Volt DC Chassis Lights

**NOTE: The inspector has verified all the items in this section are functional.**

**The inspector tested the Breakaway switch by pulling the break away cable and checked DC amperage at the Breakaway switch. However, this does not indicate that the brakes engaged at all wheel assemblies. It is recommended that the trailer be attached to a tow vehicle and with the Breakaway switch engaged, test resistance to movement. The best way to be sure this system is functioning is to have the wheels pulled and the brakes be evaluated by a qualified RV technician.**

### Styles & Materials

**Chassis Light Bulbs - Type:**
LED

**Trailer Brake Amp Draw:**
Amps
DC Amps : 12.5 A

### Items

**11.0 Breakaway Switch**
Acceptable

**11.1 7-Pin Cord - Condition**
Acceptable

**11.2 Trailer Brakes**
Acceptable

**11.3 Clearance Lights - Front**
Acceptable

**11.4 Clearance Lights - Rear**
Acceptable

**11.5 Marker Lights - Streetside**
Acceptable

**11.6 Marker Lights - Curbside**
Acceptable

**11.7 Turn and Brake Light - Left**
Acceptable

**11.8 Turn and Brake Light - Right**
Acceptable

**11.9 Tail Lights**
Acceptable

**11.13 Hitch Lights**
Acceptable

**11.14 Porch Lights**
Acceptable

## 13. Exterior Water Systems

**NOTE: Due to the inability to determine the age and quality of the water in the fresh water tank, the tank should be drained and sanitized before refilling for use.**

**NOTE: Due to the types of materials and waste used in the tanks and depending on previous maintenance, fresh and waste monitor sensor probes may perform inaccurately between applications due to build up.**

**NOTE: The onboard in-line water filter will be visually inspected but the canister assembly will not be removed to verify the presence of a filter or to determine its condition at the time of the inspection.**

### Styles & Materials

**Black Water Tank #1 - Valve Type:**
Manual Pull T-Handle

**Black Tank #1 - Flush - Present and Labeled:**
Yes

**Gray Water Tank #1 - Valve Type:**
Manual Pull T-Handle

**Gray Water Tank #2 - Valve Type:**
Manual Pull T-Handle

### Items

**13.0 City Water - Connection - Condition**

Fair

The city water inlet connection screen has some debris on it. It is recommended that this be further evaluated by a qualified RV technician.




City Water Inlet

**13.1 City Water - System Holds Pressure**

Acceptable

**13.2 City Water - Pressure Regulator Available**

Not Present

**13.3 City Water - Food Grade Hose Available for Test**

Acceptable

**13.4 Outside Shower - Operation and Condition**

Acceptable

**13.5 On-Board Water Filtration System**

Not Present

**13.6 On-Board Water System - Tank, Water Pump and Fixtures for Tank Fill Condition**
Acceptable

**13.7 On-Board Water System - Tested Fresh Water Fill**
Acceptable

**13.8 On-Board Water System - Operation**
Acceptable

**13.9 On-Board Water System - Pump Creates and Holds Pressure**
Acceptable

**13.10 In-Line Check Valve - Operation**
Acceptable

**13.11 Waste Water - Sewer / Hose Fittings**
Acceptable

**13.12 Black Water Tank #1 - Condition**
Fair

The black tank flush inlet's washer is present, but is missing the filter screen. It is recommended that this be further evaluated by a qualified RV technician.




Black Tank Flush Water Inlet

**13.13 Black Water Tank #1 - Valve Operation and Condition**

Fair

The black water tank valve is tight. It is recommended that this be further evaluated by a qualified RV technician.



Black Water Tank Valve

**13.14 Black Water Tank #1 - Tank or Valve or Line Leaks**

Acceptable

**13.15 Black Water Tank #1 - Drain Cap Condition**

Acceptable

**13.16 Black Water Tank #1 - Drain Cap in Place**

Acceptable

**13.17 Black Water Tank #1 - Drain Cap Holds Waste Water Back**

Acceptable


**13.24 Gray Water Tank #1 - Condition**

Acceptable

**13.25 Gray Water Tank #1 - Valve Operation and Condition**

Fair

The gray water tank #1 valve is tight. It is recommended that this be further evaluated by a qualified RV technician.



Gray Tank #1 Valve

**13.26 Gray Water Tank #1 - Tank or Valve or Line Leaks**

Acceptable

**13.27 Gray Water Tank #1 - Drain Cap Condition**

Acceptable

**13.28 Gray Water Tank #1 - Drain Cap in Place**

Acceptable

**13.29 Gray Water Tank #1 - Drain Cap Holds Waste Water Back**

Acceptable


**13.30 Gray Water Tank #2 - Condition**

Acceptable

**13.31 Gray Water Tank #2 - Valve Operation and Condition**

Fair

The gray water tank #2 valve is tight. It is recommended that this be further evaluated by a qualified RV technician.



Gray Tank #2 Valve

**13.32 Gray Water Tank #2 - Tank or Valve or Line Leaks**

Acceptable

**13.33 Gray Water Tank #2 - Drain Cap Condition**

Acceptable

**13.34 Gray Water Tank #2 - Drain Cap in Place**

Acceptable

## 14. Propane Container(s), Lines and Connections

### Styles & Materials

**DOT - Cylinder Location:**
Tongue

**DOT - Cylinder Arrangement:**
Dual

**DOT - Regulator Type:**
Dual Input - Auto Change Over

**DOT #1 - Cylinder Size:**
30 LBS

**DOT #1 - Date of Manufacture:**
2023

**DOT #2 - Cylinder Size:**
30 LBS


**DOT #2 - Date of Manufacture:**
2023

### Items


**14.7 DOT Cylinder(s) - Condition**

Acceptable

Overview




Streetside Propane Tank




Curbside Propane Tank

**14.8 DOT Cylinder #1 - Rust or Damage**

Acceptable

**14.9 DOT Cylinder #1 - Regulator Vents Downward**

Acceptable

**14.10 DOT Cylinder #2 - Rust or Damage**

Acceptable

**14.11 DOT Cylinder #2 - Regulator Vents Downward**

Acceptable

**14.17 DOT Cylinder(s) - Hoses and Regulators - Condition**

Acceptable

## 15. LP System Leak Test

### Styles & Materials

| LP System - Leak Test - Start Time: | LP System - Leak Test - End Time: | LP System - Leak Test - Did Pressure Change During Test: |
|---|---|---|
| AM<br>Time : 8:30 | AM<br>Time : 8:37 | No |

### Items


**15.0 LP System Leak Test**

Acceptable

Overview




Liquid Propane System Leak Test Start




Liquid Propane System Leak Test Complete

## 16. Life Safety Components

**NOTE: Liquid Propane gas detectors have an estimated service life of five years after which time it is recommended they be replaced.**

**NOTE: Carbon Monoxide detectors have an estimated service life of five years after which time it is recommended they be replaced.**

**NOTE: Smoke Detectors have an estimated service life of five to ten years after which time it is recommended they be replaced.**

### Styles & Materials

**Combination LP/CO Detector - Brand:**
RV Safe

**Combination LP/CO Detector - Date:**
Two Years Old

**Combination LP/CO Detector - Test Method:**
Tested by Spraying LP
Tested By Pushing Button

**Combination LP/CO Detector - Alarm During Test:**
Yes, When Button Pressed
Yes, With CO Test Spray

**Smoke Detector - Brand:**
Unknown

**Smoke Detector - Date:**
Less Than One Year Old

**Smoke Detector - Test Method:**

**Smoke Detector - Alarm During Test:**

**Fire Extinguisher - Brand:**
Unknown

Tested By Pushing Button
Yes, When Button Pressed

**Fire Extinguisher - Size:**
1A-10B:C - Minimum 1A-10B:C Required

**Fire Extinguisher - Meets Minimum Size Requirement:**
Yes

**Fire Extinguisher - Mounted Within 24 Inches of Entrance Door:**
Yes

**Fire Extinguisher - Secured in Bracket:**
Yes

**Fire Extinguisher - Gauge Indicates Charged State:**
Yes

## Items

### 16.2 Combination Propane (LP) / Carbon Monoxide (CO) Detector Condition and Operation

Acceptable

Overview





Combination LP/CO Detector

### 16.3 Smoke Detector - Condition and Operation

Acceptable

Overview





Smoke Detector

**16.5 Fire Extinguisher - Condition**

Acceptable

Overview




Fire Extinguisher



Fire Extinguisher

## 17. Electrical System 120-Volts AC and 12-Volts DC

### Styles & Materials

**Power Source:**
30 Amp Plug - 120 VAC - 3,600 Watts

**Power Converter - AC Power On:**
Operational Test
DC Voltage : 14.16

**Power Converter - AC Power Off:**
Operational Test
DC Voltage : 13.86

**Inverter - Brand:**
Other
Brand: : LanderPow

**Inverter - Model Number:**
Not Visible

**Inverter - Serial Number:**
Not Visible

**Inverter - Voltage Output:**
Measured Under 50% Load
Voltage Reading in AC Volts : 118.4

**Inverter - Frequency Output:**
Measured Under 50% Load
Frequency Reading in Hertz : 60.42

**12-Volt DC House Battery Disconnect Switch Present:**
Yes


**12 Volt DC House Battery - Location:**
Trailer Tongue

### Items

**17.0 Polarity / Voltage Test - Exterior Receptacles**

Acceptable

Overview




Electrical Panel - Consumer Access Area




Electrical Panel - Consumer Access Area



Electrical Panel - Qualified Technician Access Only Area

**17.1 Polarity / Voltage Test - Storage Bay Receptacles**
Acceptable

**17.3 Polarity / Voltage Test - Kitchen Receptacles**
Acceptable

**17.4 Polarity / Voltage Test - Living Room Receptacles**
Not Inspected

**17.5 Polarity / Voltage Test - Dining Area Receptacles**
Acceptable

**17.6 Polarity / Voltage Test - Bedroom Receptacles**
Acceptable

**17.7 Polarity / Voltage Test - Bath and Toilet Area Receptacles**
Acceptable

**17.8 Polarity / Voltage Test - Receptacles Behind all Electronics and Appliances**
Acceptable

**17.9 Voltage Test - 12-Volt DC Power Outlet(s) - Condition and Operation**
Acceptable

**17.10 Voltage Test - USB Ports - Condition and Operation**
Acceptable

**17.11 GFCI Trip Testing - Exterior Receptacles**
Acceptable

**17.13 GFCI Trip Testing - Kitchen Receptacles**
Acceptable

**17.14 GFCI Trip Testing - Bathroom Receptacles**
Acceptable

**17.15 GFCI Trip Testing - Bedroom Receptacle**
Acceptable

**17.16 GFCI Trip Testing - All Receptacles Behind Electronics and Appliances**
Acceptable

**17.17 GFCI Trip Testing - Circuit Breaker in Panel Box**
Not Present

**17.18 Power Cord - Condition**
Acceptable

**17.19 Electrical Panel Box - Condition**
Acceptable

**17.20 Electrical Panel Box - Wiring Secure**
Acceptable

**17.21 Electrical Panel Box - Signs of Repair or Service**
No

**17.22 Electrical Panel Box - Circuit Breakers in Place**
Yes

**17.23 Electrical Panel Box - Wiring with Signs of Discoloration from Heat**
No

**17.24 Electrical Panel Box - All White, Black, and Ground Wires Kept Separate**
Yes

**17.25 12 Volt DC Fuse Panel - Condition**
Acceptable


**17.26 12 Volt DC Fuse Panel - Wires and Terminals Tight**
Yes

**17.27 12 Volt DC Fuse Panel - Fuse Connections - Condition**
Acceptable

**17.28 12 Volt DC Fuses - Condition**
Acceptable

**17.29 Power Converter - AC On**
Acceptable

Overview




Power Converter - AC On Battery Voltage

**17.30 Power Converter - AC Off**

Acceptable

Overview




Power Converter - AC Off Battery Voltage

**17.31 Power Converter - Operation - Minimum 0.5 Volt DC Drop**

Poor

The power converter voltage difference is 0.3 volt DC drop. This is less than the recommended 0.5 volt DC drop. It is recommended that this be further evaluated by a qualified RV technician.




Battery Voltage With Converter (AC) Operating




Battery Voltage With Converter (AC) Not Operating

**17.32 12 Volt DC House Battery(s) - Condition**

Acceptable

**17.33 12 Volt DC House Battery Box(es) - Condition**

Acceptable

**17.34 12 Volt DC House Battery Box(es) - Vented and Secured**

Acceptable

**17.35 12-Volt DC House Battery(s) - Matched for Size and Age**

Acceptable

**17.36 12-Volt DC House Battery(s) - Cables and Terminals - Condition**

Acceptable

**17.37 12-Volt DC House Battery(s) - Positive and Negative Cables Matched for Load**

Acceptable

**17.38 12-Volt DC House Battery(s) - Have They Been Maintained?**

Acceptable

**17.39 12-Volt DC House Battery(s) - Operational**

Acceptable

**17.40 Inverter - Condition**

Acceptable

**17.41 Inverter - Cables, Wiring and Fuses - Condition**

Acceptable

**17.53 Cable and Satellite TV Hookup Visually Acceptable**

Acceptable

# 18. Appliances: Kitchen

**NOTE: Refrigerators need to be on for a minimum of 12 hours to be at full cooling condition. This inspection may not reveal a problem if during the inspection the refrigerator was not on for the minimum recommended time.**

## Styles & Materials

**Refrigerator - Brand:**
Magic Chef

**Refrigerator - Type:**
Residential Style - 12 VDC Compressor

**Refrigerator - Cooling Source(s):**
12 Volts DC

**Refrigerator - User Control Panel Location:**
Interior Wall in Refrigerator

**Refrigerator - Has Unit been Running 12 + Hours:**
Yes

**Refrigerator - Thermistor Sensor Type:**
Not Present

**Refrigerator - Vent Panels - Location:**
Not Present - Residential Style Refrigerator

**Refrigerator - Current Temperature:**
Degrees F
Degrees : 48

**Refrigerator - Freezer - Current Temperature:**
Degrees F
Degrees : 31

**Cooktop - Brand:**
Magic Chef

**Cooktop - Regulator Installed on Propane Line:**
Not Visible - Sealed Unit

**Cooktop - Burner Ignition Source:**
Auto Piezo Ignition - Push Button Creates a Repetitive Spark

**Oven - Brand:**
Magic Chef

**Oven - Burner Ignition Source:**
Auto Piezo Ignition - Push Button Creates a Repetitive Spark

**Cooktop Exhaust Vent - Part of Microwave:**
No

**Cooktop Exhaust Vent - Venting Type:**
Vents to Exterior

**Microwave - Brand:**
Magic Chef

**Microwave - Type:**
Microwave Only

**Microwave - Output Wattage Rating:**
900 Watts

**Microwave - Temperature of Water after 60 Seconds:**
Degrees F
Degrees : 121

**Microwave - Rack and Turntables are Installed:**
Yes

## Items

**18.2 Refrigerator - Exterior - Dauber Screens Installed**
No

**18.5 Refrigerator - Condition**
Acceptable

**18.6 Refrigerator - User Control Panel**
Acceptable

**18.7 Refrigerator - Front Side Door Panels**
Acceptable

**18.8 Refrigerator - Front Side Door Frame**
Acceptable

**18.9 Refrigerator - Front Side Door Seals**
Acceptable

**18.10 Refrigerator - Door Latch Secure**
Acceptable

**18.11 Refrigerator - Inside Light - Operation**
Acceptable

**18.13 Refrigerator - Inside Walls**
Acceptable

**18.14 Refrigerator - Shelves / Door Racks**
Acceptable

**18.15 Refrigerator - Crisper Trays and Drawers**
Acceptable

**18.16 Refrigerator - Odor Detectable**
No

**18.17 Refrigerator - Water & Ice Dispenser - Condition and Operation**
Not Present

**18.18 Refrigerator - Ice Maker - Operation**
Not Present

**18.19 Refrigerator - Freezer - Inside Walls**
Acceptable

**18.20 Refrigerator - Freezer - Shelves / Door Racks**
Acceptable

**18.21 Refrigerator - Freezer - Odor Detectable**
No

**18.22 Cooktop - Condition**
Acceptable

**18.23 Cooktop - Condition of Knobs / Controls**
Acceptable

**18.24 Cooktop - Burner Grate / Cover Condition**
Acceptable

**18.25 Cooktop - Color of Burner Flame**
Acceptable

**18.26 Cooktop - All Burners Operate**
Acceptable

**18.27 Cooktop - Rubber Grommets for Stovetop Grate**
Acceptable

**18.29 Oven - Condition**
Acceptable

**18.30 Oven - Racks Condition**
Acceptable

**18.31 Oven - Burner Lights**
Acceptable

**18.32 Oven - Color of Burner Flame**
Acceptable

**18.33 Oven - Verified Temperature of 350 Degrees F**
Acceptable

**18.34 Cooktop Exhaust Vent - Condition**
Acceptable

**18.35 Cooktop Exhaust Vent - Fan Speeds and Vent Condition**
Acceptable

**18.36 Cooktop Exhaust Vent - Filter and Lighting Condition**
Acceptable

**18.37 Microwave - Condition**
Acceptable

## 19. Appliances: Other

**NOTE: Mud Dauber screens are stainless steel screens and springs that are designed to keep mud daubers, wasps and spiders from nesting in the appliances. Verify the appliance manufacturers approve of their use prior to installation.**

### Styles & Materials

**Water Heater - Brand:**
Suburban

**Water Heater - Type:**
Tank Type

**Water Heater - Heat Source(s):**
Propane and Electric

**Water Heater - Type of Ignition:**
Direct Spark Ignition (DSI)

**Water Heater - Water Output Temperature:**
Degrees F
Degrees : 121

**Water Heater - Bypass Valves in Correct Position:**
Yes

**Furnace #1 - Brand:**
Suburban

### Items

**19.0 Water Heater - Condition**
Acceptable

**19.1 Water Heater - Operates on all Sources**
Acceptable

**19.2 Water Heater - Exterior - Condition of Burner Assembly Area**
Acceptable

**19.3 Water Heater - Exterior - Rubber Grommet Around Gas Line Sealed**
Acceptable

**19.4 Water Heater - Exterior - Dauber Screens Installed**
No

**19.5 Water Heater - Exterior - Leaks at Pressure Relief Valve**
No

**19.6 Water Heater - Exterior - Proper Drain Plug Installed**
Yes

**19.7 Furnace #1 - Operation**
Acceptable

**19.8 Furnace #1 - Floor Vents Blocked or Covered**
Acceptable

**19.9 Furnace #1 - Warm Air Discharge out of Vents**
Acceptable

**19.10 Furnace #1 - Return Air Blocked**
No

**19.11 Furnace #1 - Exterior - Air Intake / Exhaust Area Condition**
Acceptable

**19.12 Furnace #1 - Exterior - Dauber Screens Installed**
Yes

# 20(A) . Front Air Conditioner (Zone 2 - Bedroom)

**NOTE: The Delta-T average acceptable performance range is 14 to 22 degrees F (8 to 12 degrees C). In high humidity areas the range may be lower, 12 to 16 degrees F (12 to 16 degrees C) and in desert areas, it may be higher, 23 to 26 degrees F (13 to 15 degrees C).**

## Styles & Materials

**Air Conditioner - Brand:**
Coleman

**Air Conditioner - Thermostatic Controls:**
Zoned


**Air Conditioner - Options:**
Air Conditioner Only

**Air Conditioner - Delta-T:**
Degrees F
Degrees : 20


## Items

**20.0.A Air Conditioner - Condition**
Acceptable


Overview




Air Conditioner Air Intake Temperature




Air Conditioner Cool Air Output Temperature




Air Conditioner Cool Air Output Temperature

**20.1.A Air Conditioner - Filter Condition**

Acceptable

**20.2.A Air Conditioner - Plenum - Condition**

Acceptable

**20.3.A Air Conditioner - Exhaust Condition**

Acceptable

**20.4.A Air Conditioner - Heat Mode - Operation**

Not Present

## 20(B) . Rear Air Conditioner (Zone 1 - Living Rm / Kitchen)

### Styles & Materials

**Air Conditioner - Brand:**
Coleman
Model # / Serial # : 16

**Air Conditioner - Delta-T:**
Degrees F
Degrees : 16

**Air Conditioner - Thermostatic Controls:**
Zoned


**Air Conditioner - Options:**
Air Conditioner

### Items


**20.0.B Air Conditioner - Condition**

Acceptable

Overview




Air Conditioner Cool Air Output Temperature



Air Conditioner Air Intake Temperature

**20.1.B Air Conditioner - Filter Condition**

Acceptable

**20.2.B Air Conditioner - Plenum - Condition**

Acceptable

**20.3.B Air Conditioner - Exhaust Condition**

Acceptable

**20.4.B Air Conditioner - Heat Mode - Operation**

Not Present

## 21. Interior Water Systems

### Styles & Materials

**Kitchen Sink - Style:**
Single Bowl

**Kitchen Sink - Type:**
Stainless

**Toilet - Brand:**
Dometic
Model / Serial # : Model 310

**Toilet - Bowl - Type:**
Ceramic

**Toilet - Flush - Type:**
Foot Flush

**Bathroom Sink - Style:**
Single Bowl

**Bathroom Sink - Type:**
Plastic

**Shower / Tub - Style:**
Shower Stall

**Shower / Tub - Enclosure Type:**
Glass Doors

**Battery Monitor Reading:**
Charged

**Fresh Water Tank Reading:**
Owner asked to not empty or fill the tank

**Black Water Tank #1 Reading:**
1/3

**Gray Water Tank #1**
**Reading:**
Empty

**Gray Water Tank #2 / Galley**
**Reading:**
Empty

## Items

**21.0 Kitchen Faucet - Operation and Condition**
Acceptable

**21.1 Kitchen Faucet - Hot and Cold Water Available**
Yes

**21.2 Kitchen Faucet - Leaks at Stem**
No

**21.3 Kitchen Sink - Condition**
Acceptable


**21.4 Kitchen Sink - Sink(s) Holds Water**
Acceptable

**21.5 Kitchen Sink - P-Trap Holds Water**
Acceptable

**21.6 Kitchen Sink - Under Sink Condition**
Acceptable

**21.7 Toilet - Operation and Condition**
Fair

There is discoloration in the bowl near some of the water inlets. It is recommended that this be evaluated by a qualified RV technician.



Toilet Bowl

**21.8 Toilet - Bowl Holds Water**

Poor

The bowl does not hold water. It is recommended that this be evaluated by a qualified RV technician.



Toilet Bowl

**21.9 Toilet - Mounting Problems**

No

**21.10 Toilet - Water Leaks**

No

**21.11 Toilet - Indication of Previous Damage or Repair**

No

**21.17 Shower / Tub - Condition**

Acceptable

**21.18 Shower / Tub - Operation**

Acceptable

**21.19 Shower / Tub - Hot and Cold Water Available**

Acceptable

**21.20 Shower / Tub - Stains, Chemical Buildup in Stall / Tub**

No

**21.21 Shower / Tub - Discoloration**

No

**21.22 Shower / Tub - Water Damage or Leaks**

No

**21.23 Shower / Tub - Glass Doors - Operation**

Acceptable

**21.24 Shower / Tub - Door and Frame and Seals Condition**
Acceptable

**21.25 Shower / Tub - Door Latch - Operation**
Acceptable

**21.27 Shower / Tub - Soap Dish in Place**
Acceptable

**21.28 Shower / Tub - Towel Racks in Place**
Not Present

**21.29 Bathroom Faucet - Operation and Condition**
Acceptable

**21.30 Bathroom Faucet - Hot and Cold Water Available**
Acceptable

**21.31 Bathroom Faucet - Leaks at Stem**
No

**21.32 Bathroom Sink - Condition**
Acceptable

**21.33 Bathroom Sink - Sink(s) Holds Water**
Acceptable

**21.34 Bathroom Sink - P-Trap Holds Water**
Acceptable

**21.35 Bathroom Sink - Under Sink Condition**
Acceptable

**21.43 Battery / Waste / Water Monitor Panel - Condition**
Acceptable

## 22. Interior

### Styles & Materials

**Ceiling Vents - Type:**
Manual Crank Vent - 12V Fan

**System Controls / Switches - Type:**
Other
Type : WeRV Panel (with Bluetooth)

**Lights - Light Bulb - Type:**
LED

**Cabinets / Pantries - Types of Hinges:**
Hidden

**Window Coverings / Blinds - Type:**
Single Roller - not attached at bottom

**Flooring - Type:**
Plank

### Items

**22.0 Interior - Condition**
Acceptable

Overview



Overview of Interior - Front to Back



Overview of Interior - Back to Front

**22.1 System Controls / Switches - Operation**

Poor

On the interior system control panel, the Bluetooth button does not light up when pressed. It is recommended that this be further evaluated by a qualified RV technician.

**22.2 System Controls / Switches - Condition**

Acceptable

**22.3 Ceiling - Condition**

Acceptable

**22.4 Ceiling - Panels Loose**

No

**22.5 Ceiling - Discoloration or Stains**

No

**22.6 Ceiling - Damaged Ceiling Panels**

No

**22.7 Ceiling - Trim Work Missing or Damaged**

No

**22.8 Ceiling Vents and Skylights - Condition**

Acceptable

**22.9 Ceiling Vents and Skylights - Thermostatic Controls and Switches Work**

Not Present

**22.10 Ceiling Vents and Skylights - Trim Ring Around Vents and Skylights**

No

**22.11 Ceiling Vents and Skylights - Stains Around Roof Vents and Skylights**

No

**22.12 Ceiling Vents - Manual - Operation**
Acceptable

**22.13 Ceiling Vents - 12-Volt DC Fans - Operation**
Acceptable

**22.14 Ceiling Vents - 120-Volt AC Fans - Operation**
Not Present

**22.18 Lights and Light Fixtures - Condition**
Acceptable

**22.19 Lights and Light Fixtures - 12-Volt DC Lights - Operation**
Acceptable

**22.20 Lights and Light Fixtures - 120-Volt AC Lights - Operation**
Not Present

**22.21 Lights and Light Fixtures - Wall Mounted Light Fixtures - Operation**
Acceptable

**22.22 Lights and Light Fixtures - Rope Lights - Operation**
Not Present

**22.23 Lights and Light Fixtures - Spot Lights - Operation**
Not Present

**22.24 Lights and Light Fixtures - Floor Lights - Operation**
Not Present

**22.25 Lights and Light Fixtures - Entry Lights inside RV - Operation**
Not Present

**22.26 Lights and Light Fixtures - Missing or Broken Lenses**
No

**22.27 Lights and Light Fixtures - Missing Shades or Broken Covers**
No

**22.28 Walls - Condition**
Acceptable

**22.29 Walls - Panels Loose**
No

**22.30 Walls - Damaged Wall Panels**
No

**22.31 Walls - Panels Discolored or Stained**
No

**22.32 Walls - Soft Spots**
No

**22.33 Walls - Trim Work - Condition**
Acceptable

**22.34 Walls - Damage Repairs Performed**
No

**22.35 Walls - Holes or Wall Repairs**
Acceptable

**22.36 Interior Doors - Condition**
Fair
There are scrapes at the bottom, bathroom-side, of the sliding doors between the bathroom and

bedroom. It is recommended that this be further evaluated by a qualified RV technician.



Bedroom Door - Bathroom Side

**22.37 Interior Doors - Operation**

Acceptable

**22.38 Privacy Curtains / Screens - Condition**

Not Present

**22.39 Privacy Curtains / Screens - Operation**

Not Present

**22.40 Cabinets / Pantries - Condition**

Acceptable

**22.41 Cabinets / Pantries - Operation**

Acceptable

**22.42 Cabinets / Pantries - Door Damage / Scratches**

Yes

**22.43 Cabinets / Pantries - Wood Rot or Broken**

No

**22.44 Cabinets / Pantries - Drawer Damage / Scratches**

No

**22.45 Cabinets / Pantries - Countertop Damage / Scratches**

No

**22.46 Windows - Condition**

Acceptable

**22.47 Windows - Operation**

Acceptable

**22.48 Windows - Screens - Condition**

Acceptable

**22.49 Windows - Emergency Exit Windows - Operation**

Acceptable

**22.50 Windows - Emergency Exit Windows - Installed**
Yes

**22.51 Windows - Window Coverings / Blinds - Operation**
Acceptable

**22.52 Windows - Window Coverings / Blinds - Condition**
Acceptable

**22.53 Flooring - Condition**
Acceptable

**22.58 Flooring - Plank - Condition**
Acceptable

**22.59 Flooring - Floor Panels Loose**
No

**22.60 Flooring - Floor Covering Discolored or Stained**
No

**22.61 Flooring - Water Damage**
No

**22.64 Flooring - Soft Spots in Floor**
No

**22.65 Flooring - Previous Repairs Performed**
No

## 23. Furniture

### Styles & Materials

**Mattress - Type:**
Other
Type: : Brooklyn Bedding 12" Thick (2025)

**Closets / Cabinets / Dressers - Types of Hinges:**
Hidden

**Theater Seating - Type:**
Back Recline
Leg Recline

### Items

**23.0 Chairs - Condition**
Acceptable

**23.1 Chairs - Fabric Tears or Separation**
No

**23.2 Chairs - Fabric Discolored or Stains**
No

**23.3 Chairs - Signs of Excess Wear**
No

**23.4 Chairs - Water Damage**
No

**23.11 Theater Seating - Condition**
Acceptable

**23.12 Theater Seating - Operation**
Acceptable

**23.13 Dinette or Table and Chairs - Condition**
Acceptable

**23.14 Dinette or Table and Chairs - Operation**
Acceptable

**23.15 Dinette or Table and Chairs - Fabric Tears or Separation**
No

**23.16 Dinette or Table and Chairs - Fabric Discolored or Stains**
No

**23.17 Dinette or Table and Chairs - Signs of Excess Wear**
No

**23.18 Dinette or Table and Chairs - Water Damage**
No

**23.19 Dinette or Table and Chairs - Previous Repairs Performed**
No

**23.20 Bed(s) - Condition**
Acceptable

**23.21 Bed(s) - Fabric Tears or Separation**
No

**23.22 Bed(s) - Fabric Discolored or Stains**
No

**23.23 Bed(s) - Signs of Excess Wear**
No

**23.24 Bed(s) - Bed Covers Present**
Yes

**23.25 Bed(s) - Covers Match Decor**
No

**23.26 Closets / Cabinets / Dressers - Condition**
Acceptable

**23.27 Closets / Cabinets / Dressers - Operation**
Acceptable

**23.28 Closets / Cabinets / Dressers - Door Damage or Scratches**
No

**23.29 Closets / Cabinets / Dressers - Counter Top Damage or Scratches**
No

**23.30 Closets / Cabinets / Dressers - Wood Rot or Broken**
No

**23.31 Closets / Cabinets / Dressers - Drawer Damage or Scratches**
No

**23.32 Closets Doors / Cabinets Door / Drawers - Pull-Out - Condition**
Acceptable

**23.33 Closets Doors / Cabinets Door / Drawers - Pull-Out - Operation**
Acceptable

**23.34 Closets Doors / Cabinets Door / Drawers - Previous Repairs Performed**
No

## 24(A) . Living Room Television

## Styles & Materials

**Unit Brand:**
Other
Model # / Serial # : Connexx

## Items

**24.0.A Unit Works Properly**
Acceptable

**24.1.A Unit Cleaned and Maintained**
Yes

**24.2.A Unit Properly Mounted and Secured**
Yes

**24.3.A Unit Remote Controls Operational**
Yes

**24.4.A Antenna - Power Booster Operational**
Not Present

**24.5.A Antenna - Picks Up Local Channels**
Not Present

# 24(B) . Radio / Stereo

## Styles & Materials

**Unit Brand:**
Other
Model # / Serial # : Connexx

## Items

**24.0.B Unit Works Properly**
Yes

**24.1.B Unit Cleaned and Maintained**
Yes

**24.2.B Unit Properly Mounted and Secured**
Yes

**24.3.B Unit Remote Controls Operational**
Yes

# 24(C) . Backup Camera

## Styles & Materials

**Unit Brand:**
Other
Model # / Serial # : Vekooto

## Items

**24.0.C Unit Works Properly**
Acceptable

**24.1.C Unit Cleaned and Maintained**
Acceptable

**24.2.C Unit Properly Mounted and Secured**
Acceptable

**24.3.C Unit Remote Controls Operational**
Not Present

# 24(D) . Front-Facing Camera

## Styles & Materials

**Unit Brand:**
Other
Model # / Serial # : Vekooto

## Items

**24.0.D Unit Works Properly**
Acceptable

**24.1.D Unit Cleaned and Maintained**
Acceptable

**24.2.D Unit Properly Mounted and Secured**
Acceptable

**24.3.D Unit Remote Controls Operational**
Not Present