

SATQUERY AI — EARTH OBSERVATION REPORT


Remote Sensing Inspection & Telemetry

Report ID:	2f378b54d323475b	Generated:	2026-09-07T18:30:47
Confidence:	High (0.87)	Imagery Count:	2 scene(s)
Visual Query:	Perform bi-temporal change detection and identify any new logistics warehouse construction or altered waterfront infrastructure.	Evidence Type:	change_overlay

Executive Summary & Findings

Significant large-scale development has occurred within the port area, specifically in the upper-right quadrant. A substantial portion of existing waterfront infrastructure and adjacent water has been transformed into a new, expansive construction site, indicative of major port expansion or logistics facility development.

Visual Evidence Grounding



Multi-Angle Satellite Telemetry

Scene Overview	The geographic footprint encompasses a dense urban environment centered around a large, active commercial port. T1 (Baseline) shows a well-established port with numerous berths, container yards, and associated infrastructure. T2 (Monitoring) reveals a dramatic alteration where a large, uniform gray area now covers a significant section of the port, indicating a major construction or redevelopment project that has replaced previous structures and water bodies.
Land Cover (LULC)	Existing Port Infrastructure/Water to New Construction/Developed Area: ~7.6%, Stable Built-up/Paved/Water: ~92.4%.

Key Features	• Large-scale new construction/redevelopment covering existing port infrastructure and water in the upper-right quadrant. • Extensive infill and surface alteration within the primary port basin (upper-right quadrant). • Potential new logistics hub or expanded terminal facility (upper-right quadrant).
Spatial Patterns	The change manifests as a single, contiguous, large-scale infill and redevelopment project within the existing port boundaries, specifically expanding into a previously active water basin and replacing existing structures. This suggests a strategic expansion rather than peripheral growth.
Spectral Indicators	A pronounced spectral shift is observed from the varied reflectance of existing port infrastructure (concrete, asphalt, metal, water) to a uniform, bright gray signature characteristic of a large-scale construction site or newly developed surface. This indicates a complete overhaul of the surface material and topography within the affected area.
Risk & Exposure	Potential concerns include significant alteration of marine habitats due to infill, increased runoff and potential for water quality degradation during and after construction, and the long-term environmental impact of expanded industrial port operations.

Execution Trace & Telemetry Audit

Stage	Status	Detail	Latency
Compatibility Check	OK	Validated 2 image(s) for intent: change_detection	0.0ms
Routing	OK	Intent: change_detection → Selected Specialist: Change Detection	0.0ms
Analyzing	OK	Processed by Siamese DL Engine (Siamese CNN (ONNX)) + Gemini 2.5 Flash	19140.0ms
Building Evidence	OK	Rendered bi-temporal comparative panel with DL contours: [54.7, 19.7,	255.0ms
Confidence Scoring	OK	Raw: 0.87 → High (0.87)	0.0ms