Early Cretaceous Conomita outcrop: structural analysis of syn-sedimentary gravity-driven deformations (NE Venezuela)


By Dr. Carlos Giraldo


Dedicated to my venezuelan colleagues and in particular to: **Emira** Cabrera, **Oliver** Macsotay,

J.F. Ortega and M. Alberdi



Northern Venezuela Geology and outcrop location





Location of Conomita fold

Base

<u>Stop # 5</u>: 1993 Field-trip to Mountain front, East Venezuela "Excursion al Frente de Montaña, Venezuela Oriental (CORPOVEN, PDVSA)"

Cabrera, E., Giraldo, C., Macsotay, O., Ortega, J.F. and M. Alberdi (INTEVEP)

Approx. 30 m Conomita fold qoT


Puerto La Cruz Cumaná Outcrop is covered by vegetation (see next slide) Playa Conomita beach (Google earth)

Barranquin Formation (Early Cretaceous)


Dr. Carlos Giraldo / Early Cretaceous Conomita outcrop structural analysis / NE Venezuela June 2020

Stop # 5: Field-trip "Excursion al Frente de Montaña, Venezuela Oriental (CORPOVEN, PDVSA),1993"


Authors: Cabrera, E., Giraldo, C., Macsotay, O., Ortega, J.F. and M. Alberdi (INTEVEP)




Approximate location of Conomita fold outcrop (see previous slide)



Outcrop analysis (Cabrera et al., 1993)



Syn-sedimentary gravity-driven deformations predated Miocene tectonics phase



Units 1 & 2 :listric faulting in opposite directions likely due to instabilities during sedimentation. Unit 3:Conomita fold appears to be a slump feature generated during "syn-kinematics" Unit 4. Unit 5 post-dates Conomita slump.

Comments

- An updated analysis of Conomita Fold outcrop (Barranquin Fm.) was performed using an image of field-trip guide-book organized by PDVSA in 1993: Excursion al Frente de Montaña, Venezuela Oriental (Stop # 5).
- "Remote" structural analysis carried-out along this outcrop reveals the existence of several deformation episodes related to gravity-driven processes. Conomita fold appears to be a slump feature generated in a deltaic setting.
- Early Cretaceous rocks were strongly tilted during Miocene-Recent tectonics phase contemporaneously to El Pilar right-lateral strike slip fault.
- A more exhaustive structural analysis should take into account the original thicknesses of para-sequences described throughout the outcrop. A valid restoration study needs to consider the original thicknesses prior to compaction because deformations occurred during early stage of Barranquin Formation sedimentation.
- This outcrop could be used eventually as an analog structure for hydrocarbon reservoirs and fault-seal analysis exercise.
- Conomita slump was also described in:Cabrera, E., Campos, V., Chigne, N., Hernandez, Fr. Galea, O. Macsotay and V. Vivas, 1988 Excursion al Frente de Montaña, Venezuela oriental, III Simposio Bolivariano de Cuencas Subandinas, Caracas, 51pp.