

AI Vehicle Damage Full Report


Claim ID: KHALID-202605-0014 Report ID: RPT-202605-PPTCWL Generated: 5/20/2026, 4:51:02 PM

Assessment Type: Client vehicle only

Uploaded By: marwanationwideassist@outlook.com • File Name: AI Report • Source: Claim Portal

Images with AI Detection

9 images • Uploaded



● High Severity (23) ● Medium Severity (3) ● Low Severity (0)

Damage Summary

Damage Side	Area of Damage	Type of Damage	Severity	Confidence	Points	Suggested Repair
Offside Front	Wheel	Damage	Medium	97%	1	Inspect
Front	Windshield	Shattered	High	88%	1	Replace glass
Front	Bumper	Broken	High	84%	1	Replace part
Offside Front	Door	Broken	High	80%	1	Replace part
Front	Headlight	Broken	High	77%	1	Replace part
Offside Front	Wheel	Damage	High	99%	1	Inspect
Front	Bumper	Broken	High	97%	1	Replace part
Offside Front	Door	Broken	High	93%	1	Replace part
Front	Windshield	Shattered	High	93%	1	Replace glass
Front	Headlight	Broken	High	85%	1	Replace part
Offside Front	Wheel	Damage	High	99%	1	Inspect
Offside Front	Door	Broken	High	97%	1	Replace part
Front	Bumper	Broken	High	92%	1	Replace part
Front	Windshield	Shattered	High	80%	1	Replace glass
Offside Front	Mirror	Broken	High	68%	1	Replace part
Front	Headlight	Broken	High	64%	1	Replace part
Offside Front	Door	Broken	High	68%	1	Replace part
Offside Front	Door	Broken	High	96%	1	Replace part
Rear	Bumper	Broken	High	78%	1	Replace part
Front	Headlight	Broken	High	88%	1	Replace part
Front	Bumper	Crash	High	87%	1	Replace or major repair
Front	Bumper	Crash	High	84%	1	Replace or major repair
Front	Bumper	Crash	High	83%	1	Replace or major repair
Rear	Trunk	Dent	Medium	91%	1	Repair & paint
Rear	Taillight	Broken	High	88%	1	Replace part
Rear	Bumper	Dent	Medium	79%	1	Repair & paint

Damage By Severity

26 Total Damages	23 High Severity	3 Medium Severity	0 Low Severity
---------------------	---------------------	----------------------	-------------------

Damage By Location

13 Front	4 Rear	0 Roof
0 Nearside Front	0 Nearside Middle	0 Nearside Rear
9 Offside Front	0 Offside Middle	0 Offside Rear

Audit Trail

Done By	Action	Timestamp
marwanationwideassist@outlook.com	Generated Collective AI Report	5/20/2026, 4:51:02 PM