

May 18,2023

From: Jesus Zelaya

This report is a follow up to the safety inspection completed on May 18,2023. The purpose of the inspection was to identify potential safety hazards and/or OSHA violations. Attached is a list of observations and recommendations based on the conditions present at the time of my visit. Please review the report and verify that all potential hazards are corrected. If you have any questions or require additional information after reviewing this report, please don't hesitate to contact me.

Sincerely,

Jesus Zelaya LF Jennings, Inc. Safety Department (703) 336-2023 jesus.zelaya@lfjennings.net



May 18,2023

WESTWOOD SHOPPING CENTER

Reported by: Jesus Zelaya

On-site Supervisor: Chris Spinks



None

Ground level this was a fall hazard now is protected with a fence a prevent a person to fall





None

Here are working with a machine and there is cables above we talked to fore about over head power line also the sign is there





None

Excavation needs to barricade to prevent a person to fall they did the correction adding caution tape around








None

Level 2 in every stair they paint walls and all fire extinguishers were removed but today we installed back





None

Level 2 by the shaft we found this wall opening and was not safe . We did the correction and a piece plywood to prevent a fall







None

Level 2 working on housekeeping which is very safe they are cleaning to prevent dust they are using compound and







None

Unsafe work practice window installer was working on ladder very unsafe we talk to the guy and he went to get a bigger ladder



observation
None
observation
None