


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-01-18**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	E-49500	East bank	24.4548, 89.8263	56%	+820 m	latest pass shows rising (more open water than 12 days ago)
2	W-82300	West bank	24.1468, 89.6762	56%	+440 m	latest pass shows rising (more open water than 12 days ago)
3	E-33500	East bank	24.5955, 89.8146	41%	+220 m	latest pass shows rising (more open water than 12 days ago)
4	E-49700	East bank	24.4531, 89.8256	38%	+500 m	latest pass shows rising (more open water than 12 days ago)
5	E-49900	East bank	24.4513, 89.8250	38%	+330 m	latest pass shows rising (more open water than 12 days ago)
6	E-50100	East bank	24.4496, 89.8244	38%	+220 m	latest pass shows rising (more open water than 12 days ago)
7	W-10300	West bank	24.7593, 89.6128	38%	+160 m	latest pass shows rising (more open water than 12 days ago)
8	W-28300	West bank	24.6058, 89.6600	38%	+60 m	latest pass shows rising (more open water than 12 days ago)
9	E-33300	East bank	24.5972, 89.8140	38%	+200 m	latest pass shows rising (more open water than 12 days ago)
10	W-82700	West bank	24.1435, 89.6747	38%	+50 m	Bank retreated 10 m in the last 4 weeks; latest pass shows a further 50 m (unconfirmed); Past-year history raises risk
11	W-72100	West bank	24.2338, 89.7074	38%	+60 m	latest pass shows a further 60 m (unconfirmed); River is rising (more open water than 12 days ago)
12	E-59100	East bank	24.3716, 89.8085	38%	+2630 m	latest pass shows a further 2,630 m (unconfirmed); Bank sits on an outer bend / in a recess
13	W-82100	West bank	24.1485, 89.6770	38%	+30 m	latest pass shows a further 30 m (unconfirmed); Past-year history raises risk
14	E-59300	East bank	24.3698, 89.8087	38%	+2320 m	latest pass shows a further 2,320 m (unconfirmed); Bank sits on an outer bend / in a recess
15	E-59500	East bank	24.3680, 89.8088	38%	+2050 m	latest pass shows a further 2,050 m (unconfirmed); Bank sits on an outer bend / in a recess
16	E-39500	East bank	24.5434, 89.8306	38%	-280 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
17	E-18500	East bank	24.7037, 89.7451	38%	+180 m	latest pass shows a further 180 m (unconfirmed); River is rising (more open water than 12 days ago)
18	E-56300	East bank	24.3967, 89.8053	38%	+140 m	latest pass shows a further 140 m (unconfirmed); River is rising (more open water than 12 days ago)
19	E-41900	East bank	24.5223, 89.8360	38%	-530 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
20	W-51900	West bank	24.4087, 89.7376	38%	-330 m	River is rising (more open water than 12 days ago); Little recent retreat, but the recent pattern still raises risk



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.