


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-02-11**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reas	Top-20 segments (red)
1	E-49500	East bank	24.4548, 89.8263	38%	-230 m	River is falling aftr last 4 weeks	
2	E-59100	East bank	24.3716, 89.8085	38%	+50 m	latest pass shows an outer bend / in	
3	E-48700	East bank	24.4616, 89.8287	38%	-380 m	Little recent retreæ River is falling aftr	
4	E-49300	East bank	24.4565, 89.8269	38%	-90 m	River is falling aftr recent pattern still	
5	E-48900	East bank	24.4599, 89.8281	38%	-40 m	River is falling aftr in a recess	
6	E-63700	East bank	24.3303, 89.8121	38%	-40 m	River is falling aftr	
7	E-43100	East bank	24.5115, 89.8368	38%	-10 m	River is falling aftr recent pattern still	
8	E-49700	East bank	24.4531, 89.8256	38%	-330 m	River is falling aftr recent pattern still	
9	E-50300	East bank	24.4479, 89.8237	38%	+0 m	River is falling aftr recent pattern still	
10	E-49900	East bank	24.4513, 89.8250	38%	-120 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk	
11	E-13100	East bank	24.7503, 89.7343	38%	-20 m	River is falling after high water; Bank sits on an outer bend / in a recess	
12	E-48300	East bank	24.4651, 89.8298	38%	-70 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk	
13	E-34100	East bank	24.5903, 89.8164	32%	-40 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk	
14	E-48500	East bank	24.4634, 89.8293	32%	-190 m	Little recent retreat, but the recent pattern still raises risk; River is falling after high water	
15	E-49100	East bank	24.4582, 89.8275	30%	-90 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk	
16	E-42900	East bank	24.5133, 89.8368	30%	-110 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk	
17	W-81700	West bank	24.1518, 89.6786	30%	-410 m	Past-year history raises risk; Little recent retreat, but the recent pattern still raises risk	
18	E-57100	East bank	24.3895, 89.8058	30%	+40 m	latest pass shows a further 40 m (unconfirmed); Bank sits on an outer bend / in a recess	
19	E-56500	East bank	24.3949, 89.8053	29%	-40 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk	
20	E-12900	East bank	24.7520, 89.7338	29%	+20 m	Bank sits on an outer bend / in a recess; latest pass shows a further 20 m (unconfirmed)	

Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.