


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-05-06**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reasons)
1	E-40500	East bank	24.5346, 89.8331	100%	-960 m	Little recent retreat; River stage is typical
2	W-67900	West bank	24.2717, 89.7066	89%	-170 m	River stage is typical about -3.3 m above
3	W-71500	West bank	24.2392, 89.7077	89%	+140 m	latest pass shows is typical of high-erosion
4	W-67700	West bank	24.2734, 89.7069	89%	-110 m	River stage is typical about -4.8 m above
5	W-68500	West bank	24.2663, 89.7061	89%	-10 m	River stage is typical about -2.2 m above
6	E-40300	East bank	24.5364, 89.8326	89%	-840 m	Little recent retreat; River stage is typical
7	W-11300	West bank	24.7505, 89.6150	83%	-600 m	River stage is typical retreat, but the recent pattern still raises risk
8	W-67500	West bank	24.2752, 89.7072	83%	-130 m	River stage is typical about -4.4 m above
9	W-46900	West bank	24.4489, 89.7184	83%	-1160 m	River stage is typical retreat, but the recent pattern still raises risk
10	W-48900	West bank	24.4312, 89.7213	83%	-1440 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
11	E-40700	East bank	24.5329, 89.8336	83%	-1190 m	Little recent retreat, but the recent pattern still raises risk; River stage is typical of high-erosion periods
12	W-48700	West bank	24.4329, 89.7207	83%	-1430 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
13	W-50500	West bank	24.4187, 89.7292	83%	-2160 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
14	E-06500	East bank	24.8002, 89.6997	83%	-1770 m	River stage is typical of high-erosion periods; Bank retreated 645 m in the last 4 weeks
15	W-49100	West bank	24.4295, 89.7221	83%	-1440 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
16	W-67300	West bank	24.2770, 89.7077	83%	-50 m	River stage is typical of high-erosion periods; Bank height about -2.8 m above the river (DEM)
17	W-11500	West bank	24.7487, 89.6155	83%	-700 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
18	W-48300	West bank	24.4364, 89.7196	83%	-1440 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
19	W-68100	West bank	24.2699, 89.7063	83%	-10 m	River stage is typical of high-erosion periods; Bank height about -0.7 m above the river (DEM)
20	E-39700	East bank	24.5416, 89.8311	83%	-990 m	Little recent retreat, but the recent pattern still raises risk; River stage is typical of high-erosion periods



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.