


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-09-27**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reas	Top-20 segments (red) 
1	W-43500	West bank	24.4782, 89.7100	32%	+40 m	latest pass shows falling after high v	
2	E-70900	East bank	24.2670, 89.8010	29%	-30 m	River is falling aft in a recess	
3	W-46900	West bank	24.4489, 89.7184	29%	+10 m	River is falling aft recent pattern still	
4	W-54900	West bank	24.3840, 89.7380	25%	-3470 m	Bank sits on an oi but the recent pat	
5	W-50100	West bank	24.4217, 89.7269	25%	+120 m	latest pass shows falling after high v	
6	W-55100	West bank	24.3825, 89.7369	18%	-3450 m	Bank sits on an oi but the recent pat	
7	E-58300	East bank	24.3788, 89.8076	18%	-2560 m	River is falling aft	
8	E-58700	East bank	24.3752, 89.8081	18%	-3890 m	River is falling aft recent pattern still	
9	E-01500	East bank	24.8339, 89.6672	18%	—	Bank sits on an oi but the recent pat	
10	W-80500	West bank	24.1615, 89.6839	18%	+0 m	Little recent retreat, but the recent pattern still raises risk; Bank height about 0.1 m above the river (DEM)	
11	W-53500	West bank	24.3955, 89.7432	18%	-4190 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk	
12	E-58500	East bank	24.3770, 89.8078	18%	-2690 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk	
13	E-57500	East bank	24.3859, 89.8064	18%	-60 m	River is falling after high water; Past-year history raises risk	
14	W-53900	West bank	24.3920, 89.7425	18%	-4050 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk	
15	W-53700	West bank	24.3937, 89.7429	18%	-4090 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk	
16	E-01700	East bank	24.8323, 89.6681	18%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk	
17	W-54700	West bank	24.3855, 89.7391	18%	-3210 m	Little recent retreat, but the recent pattern still raises risk; Bank sits on an outer bend / in a recess	
18	E-57900	East bank	24.3824, 89.8070	18%	-1920 m	River is falling after high water; Bank sits on an outer bend / in a recess	
19	W-53300	West bank	24.3973, 89.7431	18%	-4090 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk	
20	E-75900	East bank	24.2221, 89.8035	11%	-10 m	Bank sits on an outer bend / in a recess; River is falling after high water	

Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.