


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-10-09**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	E-70900	East bank	24.2670, 89.8010	29%	+20 m	River is falling after 20 m (unconfirmed)
2	E-57300	East bank	24.3877, 89.8061	29%	-90 m	River is falling after in a recess
3	E-57500	East bank	24.3859, 89.8064	25%	-90 m	River is falling after in a recess
4	E-71100	East bank	24.2652, 89.8012	25%	-50 m	River is falling after in a recess
5	W-43500	West bank	24.4782, 89.7100	18%	-50 m	River is falling after in a recess
6	W-46900	West bank	24.4489, 89.7184	18%	-10 m	River is falling after recent pattern still
7	W-55100	West bank	24.3825, 89.7369	18%	+0 m	Bank sits on an outer bend / in a recess; Bank height about -2.2 m above the river (DEM)
8	E-60300	East bank	24.3608, 89.8092	18%	+0 m	Bank sits on an outer bend / in a recess; Bank height about -2.2 m above the river (DEM)
9	W-75900	West bank	24.2006, 89.6986	11%	+40 m	Bank retreated 50 m further 40 m (unconfirmed); nearby segments are active
10	W-46300	West bank	24.4543, 89.7182	11%	+20 m	latest pass shows a further 20 m (unconfirmed); River is falling after high water
11	W-53500	West bank	24.3955, 89.7432	11%	+0 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
12	W-53900	West bank	24.3920, 89.7425	11%	-10 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
13	W-55300	West bank	24.3810, 89.7357	11%	+0 m	Bank sits on an outer bend / in a recess; Bank height about -7.0 m above the river (DEM)
14	E-75900	East bank	24.2221, 89.8035	11%	+0 m	Bank sits on an outer bend / in a recess; River is falling after high water
15	W-70700	West bank	24.2465, 89.7074	11%	+40 m	latest pass shows a further 40 m (unconfirmed); Bank height about -0.6 m above the river (DEM)
16	W-53700	West bank	24.3937, 89.7429	11%	+0 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
17	W-51700	West bank	24.4102, 89.7365	11%	+0 m	Bank sits on an outer bend / in a recess; Nearby segments are active
18	W-80500	West bank	24.1615, 89.6839	10%	-20 m	Little recent retreat, but the recent pattern still raises risk; Bank height about 0.3 m above the river (DEM)
19	E-59100	East bank	24.3716, 89.8085	10%	+2670 m	Bank sits on an outer bend / in a recess; latest pass shows a further 2,670 m (unconfirmed)
20	W-52900	West bank	24.4009, 89.7423	10%	+60 m	latest pass shows a further 60 m (unconfirmed); Nearby segments are active



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.