


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-11-02**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reas	Top-20 segments (red) 
1	E-71100	East bank	24.2652, 89.8012	38%	+80 m	latest pass shows falling after high v	
2	E-01500	East bank	24.8339, 89.6672	25%	—	Bank sits on an oi but the recent pat	
3	E-01300	East bank	24.8356, 89.6664	25%	—	Bank sits on an oi but the recent pat	
4	E-86700	East bank	24.1452, 89.8670	25%	+30 m	Bank sits on an oi m in the last 12 w (unconfirmed)	
5	E-77700	East bank	24.2073, 89.8108	18%	+50 m	Bank sits on an oi further 50 m (unco	
6	E-01700	East bank	24.8323, 89.6681	18%	—	Bank sits on an oi but the recent pat	
7	E-86500	East bank	24.1466, 89.8657	18%	+30 m	Bank sits on an oi m in the last 4 we (unconfirmed)	
8	W-54500	West bank	24.3870, 89.7401	18%	+780 m	latest pass shows falling after high v	
9	E-75900	East bank	24.2221, 89.8035	18%	+0 m	Bank sits on an outer bend / in a recess; River is falling after high water	
10	W-54300	West bank	24.3886, 89.7410	11%	+1000 m	latest pass shows a further 1,000 m (unconfirmed); Bank sits on an outer bend / in a recess	
11	E-01100	East bank	24.8373, 89.6657	11%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk	
12	W-54100	West bank	24.3903, 89.7418	11%	+1030 m	latest pass shows a further 1,030 m (unconfirmed); Bank sits on an outer bend / in a recess	
13	E-77500	East bank	24.2089, 89.8098	10%	+0 m	Bank sits on an outer bend / in a recess; Bank height about -4.6 m above the river (DEM)	
14	E-70900	East bank	24.2670, 89.8010	10%	+0 m	Bank sits on an outer bend / in a recess; Past-year history raises risk	
15	E-77900	East bank	24.2058, 89.8118	10%	+10 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk	
16	E-01900	East bank	24.8307, 89.6691	10%	—	Bank sits on an outer bend / in a recess; Bank height about -1.6 m above the river (DEM)	
17	E-57700	East bank	24.3841, 89.8067	7%	+40 m	Bank retreated 30 m in the last 4 weeks; latest pass shows a further 40 m (unconfirmed); Past-year history raises risk	
18	E-50100	East bank	24.4496, 89.8244	7%	-10 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk	
19	E-75700	East bank	24.2238, 89.8030	7%	+20 m	Bank sits on an outer bend / in a recess; Bank height about -4.5 m above the river (DEM)	
20	E-76100	East bank	24.2204, 89.8041	7%	+10 m	Bank sits on an outer bend / in a recess; River is falling after high water	

Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for ‘it eroded recently’ (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.