


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2022-12-08**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	E-57500	East bank	24.3859, 89.8064	38%	+210 m	latest pass shows rising (more open water than 12 days ago)
2	E-57300	East bank	24.3877, 89.8061	38%	+360 m	latest pass shows rising (more open water than 12 days ago)
3	E-34300	East bank	24.5886, 89.8170	38%	+70 m	latest pass shows rising (more open water than 12 days ago)
4	E-64100	East bank	24.3267, 89.8126	38%	+120 m	latest pass shows rising (more open water than 12 days ago)
5	E-39900	East bank	24.5399, 89.8316	32%	+620 m	latest pass shows rising (more open water than 12 days ago)
6	W-82300	West bank	24.1468, 89.6762	32%	+210 m	latest pass shows rising (more open water than 12 days ago)
7	W-82100	West bank	24.1485, 89.6770	30%	+60 m	latest pass shows rising (more open water than 12 days ago)
8	W-81100	West bank	24.1566, 89.6812	30%	+60 m	latest pass shows rising (more open water than 12 days ago)
9	W-11700	West bank	24.7470, 89.6160	30%	+150 m	latest pass shows rising (more open water than 12 days ago)
10	E-65300	East bank	24.3159, 89.8130	29%	+60 m	latest pass shows a further 60 m (unconfirmed); River is rising (more open water than 12 days ago)
11	E-34100	East bank	24.5903, 89.8164	29%	+80 m	latest pass shows a further 80 m (unconfirmed); River is rising (more open water than 12 days ago)
12	W-80900	West bank	24.1582, 89.6821	29%	+240 m	latest pass shows a further 240 m (unconfirmed); River is rising (more open water than 12 days ago)
13	E-50100	East bank	24.4496, 89.8244	29%	+100 m	latest pass shows a further 100 m (unconfirmed); River is rising (more open water than 12 days ago)
14	W-71300	West bank	24.2411, 89.7077	29%	+90 m	latest pass shows a further 90 m (unconfirmed); River is rising (more open water than 12 days ago)
15	E-28700	East bank	24.6379, 89.8073	29%	+90 m	latest pass shows a further 90 m (unconfirmed); River is rising (more open water than 12 days ago)
16	E-28500	East bank	24.6397, 89.8073	29%	+190 m	latest pass shows a further 190 m (unconfirmed); River is rising (more open water than 12 days ago)
17	E-11300	East bank	24.7653, 89.7277	29%	+230 m	latest pass shows a further 230 m (unconfirmed); Bank height about -7.1 m above the river (DEM)
18	W-82500	West bank	24.1452, 89.6754	29%	+30 m	latest pass shows a further 30 m (unconfirmed); River is rising (more open water than 12 days ago)
19	W-55300	West bank	24.3810, 89.7357	29%	+470 m	Bank retreated 100 m in the last 4 weeks; latest pass shows a further 470 m (unconfirmed); Bank sits on an outer bend / in a recess
20	E-59500	East bank	24.3680, 89.8088	29%	+40 m	latest pass shows a further 40 m (unconfirmed); River is rising (more open water than 12 days ago)



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.