


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2023-01-01**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reasons)
1	W-55500	West bank	24.3795, 89.7346	56%	+150 m	Bank retreated 10 m in the last 4 weeks; latest pass shows a further 150 m (unconfirmed); River stage is typical of high-erosion periods
2	E-34300	East bank	24.5886, 89.8170	56%	+130 m	Bank retreated 65 m in the last 4 weeks; latest pass shows a further 130 m (unconfirmed); River stage is typical of high-erosion periods
3	E-28900	East bank	24.6361, 89.8072	56%	-860 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
4	W-83300	West bank	24.1384, 89.6728	38%	-920 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
5	E-33900	East bank	24.5921, 89.8158	38%	+120 m	Bank retreated 60 m in the last 4 weeks; latest pass shows a further 120 m (unconfirmed); River stage is typical of high-erosion periods
6	W-51900	West bank	24.4087, 89.7376	38%	+380 m	Bank retreated 12 m in the last 4 weeks; latest pass shows a further 380 m (unconfirmed); River stage is typical of high-erosion periods
7	E-34100	East bank	24.5903, 89.8164	38%	+80 m	Bank retreated 40 m in the last 4 weeks; latest pass shows a further 80 m (unconfirmed); River stage is typical of high-erosion periods
8	W-84700	West bank	24.1260, 89.6700	38%	-640 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
9	W-43100	West bank	24.4814, 89.7082	38%	-420 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
10	E-74100	East bank	24.2382, 89.8022	38%	-1370 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
11	E-72500	East bank	24.2526, 89.8026	38%	-1920 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
12	E-72300	East bank	24.2544, 89.8024	38%	-2020 m	Little recent retreat, but the recent pattern still raises risk; River stage is typical of high-erosion periods
13	E-72100	East bank	24.2562, 89.8023	38%	-2080 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
14	E-29100	East bank	24.6343, 89.8072	38%	-170 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
15	W-28100	West bank	24.6076, 89.6600	38%	-200 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
16	W-83500	West bank	24.1367, 89.6722	38%	-620 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
17	E-47700	East bank	24.4704, 89.8311	38%	-340 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
18	W-80500	West bank	24.1615, 89.6839	38%	-110 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
19	W-82900	West bank	24.1418, 89.6740	38%	-400 m	River stage is typical of high-erosion periods; Little recent retreat, but the recent pattern still raises risk
20	W-71100	West bank	24.2429, 89.7076	38%	+60 m	Bank retreated 20 m in the last 4 weeks; latest pass shows a further 60 m (unconfirmed); River stage is typical of high-erosion periods



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.