


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2023-10-04**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	W-54700	West bank	24.3855, 89.7391	38%	+20 m	River is rising (model pass shows a further retreat)
2	W-47100	West bank	24.4471, 89.7184	38%	+670 m	latest pass shows rising (more open water than 12 days ago)
3	W-46900	West bank	24.4489, 89.7184	30%	+40 m	River is rising (model pass shows a further retreat on an outer bend)
4	W-47700	West bank	24.4417, 89.7187	29%	+1070 m	River is rising (model pass shows a further retreat)
5	E-12300	East bank	24.7572, 89.7320	29%	+30 m	latest pass shows rising (more open water than 12 days ago)
6	W-54500	West bank	24.3870, 89.7401	29%	+10 m	River is rising (model recent retreat, but the recent pattern still raises risk)
7	W-47300	West bank	24.4453, 89.7185	25%	+740 m	latest pass shows rising (more open water than 12 days ago); history raises risk
8	W-47500	West bank	24.4435, 89.7186	18%	+990 m	latest pass shows rising (more open water than 12 days ago)
9	E-12700	East bank	24.7537, 89.7333	18%	-20 m	River is rising (model pass shows a further retreat on an outer bend / in a recess)
10	W-54100	West bank	24.3903, 89.7418	18%	+0 m	Little recent retreat, but the recent pattern still raises risk; Bank sits on an outer bend / in a recess
11	E-12500	East bank	24.7555, 89.7326	18%	+0 m	River is rising (more open water than 12 days ago); Bank sits on an outer bend / in a recess
12	E-12100	East bank	24.7588, 89.7312	18%	-50 m	River is rising (more open water than 12 days ago); Little recent retreat, but the recent pattern still raises risk
13	W-55300	West bank	24.3810, 89.7357	18%	-40 m	Little recent retreat, but the recent pattern still raises risk; Bank height about -7.3 m above the river (DEM)
14	W-53900	West bank	24.3920, 89.7425	18%	-30 m	Little recent retreat, but the recent pattern still raises risk; Bank sits on an outer bend / in a recess
15	E-57300	East bank	24.3877, 89.8061	11%	+370 m	latest pass shows a further 370 m (unconfirmed); Past-year history raises risk
16	E-76100	East bank	24.2204, 89.8041	11%	+0 m	Bank sits on an outer bend / in a recess; River is rising (more open water than 12 days ago)
17	W-70500	West bank	24.2483, 89.7073	11%	+40 m	latest pass shows a further 40 m (unconfirmed); River is rising (more open water than 12 days ago)
18	E-05500	East bank	24.8068, 89.6930	11%	+80 m	latest pass shows a further 80 m (unconfirmed); Bank height about 1.5 m above the river (DEM)
19	E-75900	East bank	24.2221, 89.8035	11%	+0 m	Bank sits on an outer bend / in a recess; Bank height about 0.7 m above the river (DEM)
20	E-77900	East bank	24.2058, 89.8118	11%	-10 m	Bank sits on an outer bend / in a recess; River is rising (more open water than 12 days ago)



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.