


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2023-11-09**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	E-01300	East bank	24.8356, 89.6664	38%	—	River stage is typical of high-erosion periods; latest pass shows a further 130 m (unconfirmed); Bank sits on an outer bend / in a recess
2	W-54500	West bank	24.3870, 89.7401	32%	+130 m	Bank retreated 65 m in the last 4 weeks; latest pass shows a further 130 m (unconfirmed); River stage is typical of high-erosion periods
3	W-48900	West bank	24.4312, 89.7213	29%	+450 m	Bank retreated 22 m in the last 4 weeks; latest pass shows a further 450 m (unconfirmed); River stage is typical of high-erosion periods
4	W-48700	West bank	24.4329, 89.7207	29%	+390 m	Bank retreated 19 m in the last 4 weeks; latest pass shows a further 390 m (unconfirmed); River stage is typical of high-erosion periods
5	W-54700	West bank	24.3855, 89.7391	29%	-20 m	River stage is typical of high-erosion periods; latest pass shows a further 20 m (unconfirmed); Bank sits on an outer bend / in a recess
6	E-01100	East bank	24.8373, 89.6657	29%	—	River stage is typical of high-erosion periods; latest pass shows a further 520 m (unconfirmed); Bank sits on an outer bend / in a recess
7	E-01900	East bank	24.8307, 89.6691	29%	+520 m	Bank retreated 23 m in the last 4 weeks; latest pass shows a further 520 m (unconfirmed); Bank sits on an outer bend / in a recess
8	W-48500	West bank	24.4346, 89.7201	25%	+360 m	Bank retreated 180 m in the last 4 weeks; latest pass shows a further 360 m (unconfirmed); River stage is typical of high-erosion periods
9	W-48300	West bank	24.4364, 89.7196	25%	+380 m	Bank retreated 190 m in the last 4 weeks; latest pass shows a further 380 m (unconfirmed); River stage is typical of high-erosion periods
10	W-53900	West bank	24.3920, 89.7425	25%	+10 m	Little recent retreat, but the recent pattern still raises risk; Bank sits on an outer bend / in a recess
11	E-75700	East bank	24.2238, 89.8030	25%	+40 m	Bank retreated 20 m in the last 4 weeks; latest pass shows a further 40 m (unconfirmed); Bank sits on an outer bend / in a recess
12	W-54100	West bank	24.3903, 89.7418	18%	-20 m	Little recent retreat, but the recent pattern still raises risk; Bank sits on an outer bend / in a recess
13	E-21300	East bank	24.6878, 89.7665	18%	+320 m	Bank retreated 100 m in the last 4 weeks; latest pass shows a further 320 m (unconfirmed); Bank sits on an outer bend / in a recess
14	W-54300	West bank	24.3886, 89.7410	18%	-20 m	Little recent retreat, but the recent pattern still raises risk; Bank sits on an outer bend / in a recess
15	W-48100	West bank	24.4381, 89.7193	18%	+350 m	Bank retreated 175 m in the last 4 weeks; latest pass shows a further 350 m (unconfirmed); River stage is typical of high-erosion periods
16	E-02100	East bank	24.8292, 89.6701	18%	+300 m	Bank retreated 150 m in the last 4 weeks; latest pass shows a further 300 m (unconfirmed); Bank sits on an outer bend / in a recess
17	E-21100	East bank	24.6888, 89.7648	18%	+190 m	Bank retreated 85 m in the last 4 weeks; latest pass shows a further 190 m (unconfirmed); Bank sits on an outer bend / in a recess
18	E-04100	East bank	24.8157, 89.6832	18%	+50 m	River stage is typical of high-erosion periods; latest pass shows a further 50 m (unconfirmed)
19	E-05100	East bank	24.8094, 89.6903	18%	-50 m	Little recent retreat, but the recent pattern still raises risk; River stage is typical of high-erosion periods
20	E-77700	East bank	24.2073, 89.8108	18%	+30 m	Bank sits on an outer bend / in a recess; latest pass shows a further 30 m (unconfirmed)



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.