


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2024-02-01**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	E-04700	East bank	24.8119, 89.6874	56%	+280 m	latest pass shows rising (more open water than 12 days ago)
2	E-46100	East bank	24.4846, 89.8335	56%	+1490 m	latest pass shows rising (more open water than 12 days ago)
3	E-28900	East bank	24.6361, 89.8072	50%	—	Little recent retreat; River is rising (more open water than 12 days ago)
4	E-45700	East bank	24.4882, 89.8340	41%	+2040 m	latest pass shows rising (more open water than 12 days ago)
5	E-45900	East bank	24.4864, 89.8337	38%	+1770 m	latest pass shows rising (more open water than 12 days ago)
6	E-71900	East bank	24.2580, 89.8021	38%	—	Little recent retreat; River is rising (more open water than 12 days ago)
7	E-72500	East bank	24.2526, 89.8026	38%	+50 m	latest pass shows rising (more open water than 12 days ago)
8	E-72100	East bank	24.2562, 89.8023	38%	—	Little recent retreat; River is rising (more open water than 12 days ago)
9	E-07100	East bank	24.7961, 89.7036	38%	+320 m	latest pass shows rising (more open water than 12 days ago)
10	E-74700	East bank	24.2328, 89.8020	38%	+90 m	latest pass shows a further 90 m (unconfirmed); River is rising (more open water than 12 days ago)
11	E-15500	East bank	24.7287, 89.7357	38%	+1020 m	latest pass shows a further 1,020 m (unconfirmed); River is rising (more open water than 12 days ago)
12	E-46300	East bank	24.4829, 89.8332	38%	+950 m	latest pass shows a further 950 m (unconfirmed); River is rising (more open water than 12 days ago)
13	W-83900	West bank	24.1332, 89.6713	38%	+1400 m	latest pass shows a further 1,400 m (unconfirmed); River is rising (more open water than 12 days ago)
14	W-84100	West bank	24.1314, 89.6709	38%	+1160 m	latest pass shows a further 1,160 m (unconfirmed); River is rising (more open water than 12 days ago)
15	W-83700	West bank	24.1349, 89.6717	38%	+1440 m	latest pass shows a further 1,440 m (unconfirmed); River is rising (more open water than 12 days ago)
16	E-07300	East bank	24.7947, 89.7048	38%	+450 m	latest pass shows a further 450 m (unconfirmed); River is rising (more open water than 12 days ago)
17	E-06700	East bank	24.7988, 89.7010	38%	-10 m	River is rising (more open water than 12 days ago); Bank sits on an outer bend / in a recess
18	E-75100	East bank	24.2292, 89.8021	38%	+10 m	River is rising (more open water than 12 days ago); Little recent retreat, but the recent pattern still raises risk
19	E-71500	East bank	24.2616, 89.8016	38%	+1520 m	latest pass shows a further 1,520 m (unconfirmed); River is rising (more open water than 12 days ago)
20	E-06900	East bank	24.7975, 89.7023	38%	+20 m	River is rising (more open water than 12 days ago); Bank sits on an outer bend / in a recess



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.