


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2024-02-25**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	E-79700	East bank	24.1918, 89.8208	38%	+170 m	latest pass shows falling after high water
2	E-79300	East bank	24.1949, 89.8188	38%	+230 m	River is falling after 230 m (unconfirmed)
3	E-75300	East bank	24.2274, 89.8023	30%	—	River is falling after recent pattern still
4	E-78900	East bank	24.1980, 89.8168	30%	-20 m	River is falling after
5	W-83700	West bank	24.1349, 89.6717	29%	+0 m	River is falling after in a recess
6	W-83900	West bank	24.1332, 89.6713	25%	-10 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
7	W-84100	West bank	24.1314, 89.6709	25%	-10 m	River is falling after in a recess
8	E-78700	East bank	24.1995, 89.8158	25%	—	River is falling after
9	W-84300	West bank	24.1296, 89.6705	25%	-20 m	River is falling after in a recess
10	E-72500	East bank	24.2526, 89.8026	18%	-1960 m	Past-year history raises risk; Bank sits on an outer bend / in a recess
11	E-72300	East bank	24.2544, 89.8024	18%	-2010 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
12	E-71900	East bank	24.2580, 89.8021	18%	-2000 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
13	W-84500	West bank	24.1278, 89.6702	18%	-20 m	River is falling after high water; Past-year history raises risk
14	W-11300	West bank	24.7505, 89.6150	18%	-650 m	River is falling after high water; Bank height about -5.7 m above the river (DEM)
15	E-58100	East bank	24.3806, 89.8073	18%	+10 m	River is falling after high water; Past-year history raises risk
16	E-73900	East bank	24.2400, 89.8023	18%	-1470 m	Past-year history raises risk; Bank sits on an outer bend / in a recess
17	W-72300	West bank	24.2320, 89.7072	18%	+30 m	latest pass shows a further 30 m (unconfirmed); Bank sits on an outer bend / in a recess
18	W-84900	West bank	24.1242, 89.6698	18%	+40 m	River is falling after high water; latest pass shows a further 40 m (unconfirmed)
19	E-73700	East bank	24.2418, 89.8024	18%	-1530 m	Past-year history raises risk; Bank sits on an outer bend / in a recess
20	E-71700	East bank	24.2598, 89.8018	18%	-1790 m	Past-year history raises risk; Bank sits on an outer bend / in a recess



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.