


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2024-08-11**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reasons)
1	E-60500	East bank	24.3590, 89.8093	29%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
2	E-60700	East bank	24.3572, 89.8094	29%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
3	W-09500	West bank	24.7663, 89.6111	29%	—	Monsoon season; Neighbouring segments retreated 282 m on average in 12 weeks
4	W-46900	West bank	24.4489, 89.7184	18%	—	River stage is typical of high-erosion periods
5	E-60900	East bank	24.3554, 89.8095	18%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
6	W-77700	West bank	24.1850, 89.6936	18%	—	Neighbouring segments retreated 68 m on average in 12 weeks
7	E-37900	East bank	24.5574, 89.8267	18%	—	Neighbouring segments retreated 65 m on average in 12 weeks
8	W-77300	West bank	24.1885, 89.6946	18%	—	Monsoon season; Neighbouring segments retreated 282 m on average in 12 weeks
9	E-60300	East bank	24.3608, 89.8092	18%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
10	E-71100	East bank	24.2652, 89.8012	18%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
11	W-77500	West bank	24.1868, 89.6941	18%	—	Monsoon season; Neighbouring segments retreated 282 m on average in 12 weeks
12	E-70900	East bank	24.2670, 89.8010	18%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
13	E-70700	East bank	24.2688, 89.8009	18%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
14	E-77900	East bank	24.2058, 89.8118	18%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
15	E-38100	East bank	24.5556, 89.8272	18%	—	Monsoon season; Neighbouring segments retreated 68 m on average in 12 weeks
16	E-86700	East bank	24.1452, 89.8670	11%	—	Bank sits on an outer bend / in a recess; River stage is typical of high-erosion periods
17	W-08900	West bank	24.7716, 89.6097	11%	—	Monsoon season; Neighbouring segments retreated 65 m on average in 12 weeks
18	E-61100	East bank	24.3536, 89.8096	11%	—	Nearby segments are active; Monsoon season
19	E-76100	East bank	24.2204, 89.8041	11%	—	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
20	E-55500	East bank	24.4038, 89.8063	11%	—	Bank sits on an outer bend / in a recess; A 632 m-wide channel runs along the bank



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.