


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2024-10-10**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	E-72300	East bank	24.2544, 89.8024	38%	+2020 m	River is rising (model on an outer bend)
2	W-53100	West bank	24.3991, 89.7428	30%	+2340 m	latest pass shows on an outer bend
3	W-48300	West bank	24.4364, 89.7196	29%	-1370 m	River is rising (model on an outer bend)
4	W-48500	West bank	24.4346, 89.7201	29%	-1370 m	River is rising (model on an outer bend)
5	W-48700	West bank	24.4329, 89.7207	29%	-1370 m	River is rising (model on an outer bend)
6	W-48900	West bank	24.4312, 89.7213	29%	-1370 m	River is rising (model on an outer bend)
7	E-73700	East bank	24.2418, 89.8024	25%	+1520 m	latest pass shows on an outer bend
8	W-54900	West bank	24.3840, 89.7380	25%	+10 m	River is rising (model on an outer bend)
9	W-48100	West bank	24.4381, 89.7193	25%	-1390 m	River is rising (model on an outer bend / in a recess)
10	E-73900	East bank	24.2400, 89.8023	18%	+1450 m	latest pass shows a further 1,450 m (unconfirmed); Bank sits on an outer bend / in a recess
11	W-47700	West bank	24.4417, 89.7187	18%	-1390 m	River is rising (more open water than 12 days ago); Bank height about -6.7 m above the river (DEM)
12	E-59500	East bank	24.3680, 89.8088	18%	+3740 m	latest pass shows a further 3,740 m (unconfirmed); Bank sits on an outer bend / in a recess
13	E-80100	East bank	24.1887, 89.8229	18%	+400 m	latest pass shows a further 400 m (unconfirmed); Bank sits on an outer bend / in a recess
14	W-47300	West bank	24.4453, 89.7185	18%	-1320 m	River is rising (more open water than 12 days ago); Bank height about 0.0 m above the river (DEM)
15	E-79900	East bank	24.1903, 89.8218	18%	+640 m	latest pass shows a further 640 m (unconfirmed); Bank sits on an outer bend / in a recess
16	W-47900	West bank	24.4399, 89.7190	18%	-1430 m	River is rising (more open water than 12 days ago); Bank height about -6.3 m above the river (DEM)
17	W-52700	West bank	24.4025, 89.7416	18%	+2650 m	latest pass shows a further 2,650 m (unconfirmed); Bank sits on an outer bend / in a recess
18	E-71900	East bank	24.2580, 89.8021	18%	+1970 m	Bank sits on an outer bend / in a recess; latest pass shows a further 1,970 m (unconfirmed)
19	W-47100	West bank	24.4471, 89.7184	18%	-1180 m	River is rising (more open water than 12 days ago); Bank height about 0.0 m above the river (DEM)
20	E-89300	East bank	24.1276, 89.8838	18%	+40 m	latest pass shows a further 40 m (unconfirmed); Bank sits on an outer bend / in a recess



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.