


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2024-11-03**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	W-54900	West bank	24.3840, 89.7380	56%	+300 m	Bank retreated 20 m; latest pass shows a further 300 m (unconfirmed); Past-year history raises risk
2	W-55100	West bank	24.3825, 89.7369	38%	+300 m	latest pass shows on an outer bend
3	W-48700	West bank	24.4329, 89.7207	29%	+1400 m	latest pass shows on an outer bend
4	W-48900	West bank	24.4312, 89.7213	29%	+1390 m	latest pass shows on an outer bend
5	E-71300	East bank	24.2634, 89.8014	29%	+340 m	Bank retreated 60 m; latest pass shows a further 340 m (unconfirmed); Past-year history raises risk
6	W-48500	West bank	24.4346, 89.7201	25%	+1400 m	latest pass shows on an outer bend
7	W-48300	West bank	24.4364, 89.7196	25%	+1420 m	latest pass shows on an outer bend
8	W-54700	West bank	24.3855, 89.7391	18%	-10 m	Little recent retreat; Bank sits on an outer bend / in a recess; River is falling after high water
9	W-48100	West bank	24.4381, 89.7193	18%	+1420 m	latest pass shows a further 1,420 m (unconfirmed); Past-year history raises risk
10	W-54500	West bank	24.3870, 89.7401	18%	-20 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
11	W-53100	West bank	24.3991, 89.7428	18%	+0 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
12	W-82900	West bank	24.1418, 89.6740	18%	-10 m	Bank sits on an outer bend / in a recess; River is falling after high water
13	W-47700	West bank	24.4417, 89.7187	18%	+1400 m	latest pass shows a further 1,400 m (unconfirmed); Past-year history raises risk
14	W-47300	West bank	24.4453, 89.7185	11%	+1330 m	latest pass shows a further 1,330 m (unconfirmed); Past-year history raises risk
15	E-56500	East bank	24.3949, 89.8053	11%	+90 m	latest pass shows a further 90 m (unconfirmed); River is falling after high water
16	W-47900	West bank	24.4399, 89.7190	11%	+1450 m	latest pass shows a further 1,450 m (unconfirmed); Past-year history raises risk
17	E-74700	East bank	24.2328, 89.8020	11%	+40 m	Bank retreated 30 m in the last 4 weeks; latest pass shows a further 40 m (unconfirmed); Nearby segments are active
18	W-47500	West bank	24.4435, 89.7186	11%	+1350 m	latest pass shows a further 1,350 m (unconfirmed); Past-year history raises risk
19	W-83100	West bank	24.1401, 89.6734	11%	-10 m	Bank sits on an outer bend / in a recess; River is falling after high water
20	W-47100	West bank	24.4471, 89.7184	11%	+1170 m	Bank retreated 10 m in the last 4 weeks; latest pass shows a further 1,170 m (unconfirmed); Past-year history raises risk



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.