


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2024-11-27**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reason)
1	W-54900	West bank	24.3840, 89.7380	38%	+100 m	Bank retreated 30 m; a further 100 m (unconfirmed) in a recess
2	E-72900	East bank	24.2490, 89.8027	29%	—	River is falling after recent pattern still
3	E-04300	East bank	24.8145, 89.6846	29%	+80 m	Bank retreated 30 m; a further 80 m (unconfirmed)
4	W-55100	West bank	24.3825, 89.7369	29%	+220 m	Bank retreated 25 m; a further 220 m (unconfirmed) above the river (D)
5	E-10500	East bank	24.7714, 89.7236	29%	+280 m	River is falling after 280 m (unconfirmed)
6	E-72300	East bank	24.2544, 89.8024	29%	+40 m	latest pass shows history raises risk
7	E-72700	East bank	24.2508, 89.8027	18%	—	River is falling after recent pattern still
8	E-12900	East bank	24.7520, 89.7338	18%	+100 m	latest pass shows history raises risk
9	E-02300	East bank	24.8277, 89.6713	18%	-220 m	River is falling after high water; Bank sits on an outer bend / in a recess
10	W-11300	West bank	24.7505, 89.6150	18%	+50 m	latest pass shows a further 50 m (unconfirmed); River is falling after high water
11	W-54700	West bank	24.3855, 89.7391	18%	+0 m	Bank retreated 10 m in the last 4 weeks; Bank sits on an outer bend / in a recess
12	E-73100	East bank	24.2472, 89.8027	18%	+0 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk
13	W-29300	West bank	24.5967, 89.6605	18%	+110 m	latest pass shows a further 110 m (unconfirmed); River is falling after high water
14	W-83100	West bank	24.1401, 89.6734	11%	-1510 m	River is falling after high water; Bank sits on an outer bend / in a recess
15	W-82900	West bank	24.1418, 89.6740	11%	-840 m	River is falling after high water; Bank sits on an outer bend / in a recess
16	E-34100	East bank	24.5903, 89.8164	11%	+70 m	latest pass shows a further 70 m (unconfirmed); River is falling after high water
17	W-71100	West bank	24.2429, 89.7076	11%	-630 m	River is falling after high water; Bank sits on an outer bend / in a recess
18	W-54500	West bank	24.3870, 89.7401	11%	+0 m	Bank sits on an outer bend / in a recess; Little recent retreat, but the recent pattern still raises risk
19	E-15100	East bank	24.7323, 89.7357	10%	-130 m	River is falling after high water; Bank sits on an outer bend / in a recess
20	E-46700	East bank	24.4793, 89.8327	10%	-20 m	River is falling after high water; Bank sits on an outer bend / in a recess



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.