


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2025-02-19**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reasons)
1	E-56900	East bank	24.3913, 89.8056	38%	+60 m	Bank retreated 1C further 60 m (unconfirmed)
2	W-83100	West bank	24.1401, 89.6734	38%	+50 m	Bank retreated 3C further 50 m (unconfirmed)
3	E-15900	East bank	24.7251, 89.7359	30%	+80 m	latest pass shows falling after high water
4	W-70300	West bank	24.2501, 89.7071	29%	+440 m	Bank retreated 1C further 440 m (unconfirmed); a recess
5	E-15500	East bank	24.7287, 89.7357	29%	-10 m	River is falling after high water in a recess
6	E-75700	East bank	24.2238, 89.8030	29%	—	River is falling after high water; recent pattern still raises risk
7	W-81500	West bank	24.1534, 89.6795	29%	+420 m	latest pass shows history raises risk
8	E-57300	East bank	24.3877, 89.8061	29%	+0 m	River is falling after high water in a recess
9	E-34700	East bank	24.5852, 89.8182	25%	+410 m	Bank retreated 1C in the last 4 weeks; latest pass shows a further 410 m (unconfirmed); Past-year history raises risk
10	W-82700	West bank	24.1435, 89.6747	18%	+10 m	Past-year history raises risk; Bank sits on an outer bend / in a recess
11	W-82900	West bank	24.1418, 89.6740	18%	-20 m	Past-year history raises risk; Bank sits on an outer bend / in a recess
12	E-29500	East bank	24.6307, 89.8072	18%	-90 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk
13	E-72100	East bank	24.2562, 89.8023	18%	-70 m	Past-year history raises risk; Bank sits on an outer bend / in a recess
14	W-29100	West bank	24.5985, 89.6603	18%	-30 m	River is falling after high water; Little recent retreat, but the recent pattern still raises risk
15	E-01900	East bank	24.8307, 89.6691	18%	+0 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
16	W-80100	West bank	24.1647, 89.6857	18%	+30 m	Bank retreated 40 m in the last 4 weeks; latest pass shows a further 30 m (unconfirmed); Past-year history raises risk
17	W-83500	West bank	24.1367, 89.6722	18%	+10 m	Past-year history raises risk; Bank height about -0.8 m above the river (DEM)
18	E-31300	East bank	24.6146, 89.8087	18%	-10 m	Past-year history raises risk; River is falling after high water
19	E-57100	East bank	24.3895, 89.8058	18%	+10 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
20	W-84500	West bank	24.1278, 89.6702	11%	+0 m	Past-year history raises risk; Bank sits on an outer bend / in a recess



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.