


NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2025-03-03**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.

#	Segment	Bank	Lat, Lon	Risk	Latest pass	Why (model reasons)
1	E-57100	East bank	24.3895, 89.8058	41%	+50 m	Bank retreated 10 m further 50 m (unconfirmed)
2	E-15700	East bank	24.7269, 89.7357	38%	+140 m	latest pass shows on an outer bend
3	E-29500	East bank	24.6307, 89.8072	38%	+120 m	latest pass shows rising (more open water)
4	E-57500	East bank	24.3859, 89.8064	38%	+500 m	latest pass shows on an outer bend
5	E-57300	East bank	24.3877, 89.8061	38%	+1030 m	latest pass shows rising (more open water)
6	E-79300	East bank	24.1949, 89.8188	38%	—	Past-year history raises risk
7	W-82700	West bank	24.1435, 89.6747	38%	+1510 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
8	E-29300	East bank	24.6325, 89.8072	32%	—	Bank retreated 10 m further 50 m (unconfirmed)
9	W-18500	West bank	24.6880, 89.6340	32%	+0 m	River is rising (more open water than 12 days ago); Past-year history raises risk
10	W-84900	West bank	24.1242, 89.6698	30%	+90 m	latest pass shows a further 90 m (unconfirmed); Bank height about -5.0 m above the river (DEM)
11	W-79900	West bank	24.1663, 89.6865	30%	+460 m	Bank retreated 30 m in the last 4 weeks; latest pass shows a further 460 m (unconfirmed); Past-year history raises risk
12	E-15500	East bank	24.7287, 89.7357	30%	+10 m	Bank sits on an outer bend / in a recess; Past-year history raises risk
13	E-75700	East bank	24.2238, 89.8030	30%	+20 m	Past-year history raises risk; latest pass shows a further 20 m (unconfirmed)
14	E-75300	East bank	24.2274, 89.8023	29%	+70 m	latest pass shows a further 70 m (unconfirmed); Past-year history raises risk
15	E-29700	East bank	24.6289, 89.8072	29%	+60 m	latest pass shows a further 60 m (unconfirmed); River is rising (more open water than 12 days ago)
16	E-79700	East bank	24.1918, 89.8208	29%	+100 m	latest pass shows a further 100 m (unconfirmed); River is rising (more open water than 12 days ago)
17	E-31300	East bank	24.6146, 89.8087	29%	-20 m	River is rising (more open water than 12 days ago); Bank sits on an outer bend / in a recess
18	W-83700	West bank	24.1349, 89.6717	29%	+1000 m	Past-year history raises risk; latest pass shows a further 1,000 m (unconfirmed)
19	W-29100	West bank	24.5985, 89.6603	29%	+110 m	latest pass shows a further 110 m (unconfirmed); Past-year history raises risk
20	E-78500	East bank	24.2011, 89.8148	29%	—	River is rising (more open water than 12 days ago); Past-year history raises risk



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.