


# NadiNet weekly risk brief — Jamuna, Kazipur to Chauhali reach

Issued after the Sentinel-1 pass of **2025-10-05**. Horizon: next 28 days. Risk = calibrated probability that a 200 m bank segment loses at least 40 m of land.

**Advisory decision support. The absence of an alert does not mean a bank is safe. Public warnings are issued under an official's authority.**

| #  | Segment | Bank      | Lat, Lon         | Risk | Latest pass | Why (model reason)                                                                                 |
|----|---------|-----------|------------------|------|-------------|----------------------------------------------------------------------------------------------------|
| 1  | E-20500 | East bank | 24.6918, 89.7599 | 18%  | —           | River is falling after high water; latest pass shows a further 30 m (unconfirmed)                  |
| 2  | E-20700 | East bank | 24.6908, 89.7615 | 18%  | —           | River is falling after high water; latest pass shows a further 30 m (unconfirmed)                  |
| 3  | E-04700 | East bank | 24.8119, 89.6874 | 11%  | —           | River is falling after high water; Little recent retreat, but the recent pattern still raises risk |
| 4  | E-55700 | East bank | 24.4021, 89.8059 | 11%  | -70 m       | River is falling after high water; Little recent retreat, but the recent pattern still raises risk |
| 5  | W-54700 | West bank | 24.3855, 89.7391 | 11%  | -10 m       | Bank sits on an outer bend / in a recess; Bank height about 0.2 m above the river (DEM)            |
| 6  | E-20300 | East bank | 24.6929, 89.7583 | 11%  | —           | Bank height about -6.7 m above the river (DEM); Bank sits on an outer bend / in a recess           |
| 7  | W-54500 | West bank | 24.3870, 89.7401 | 11%  | -10 m       | River is falling after high water; Little recent retreat, but the recent pattern still raises risk |
| 8  | E-56300 | East bank | 24.3967, 89.8053 | 10%  | -30 m       | River is falling after high water; Past-year history raises risk                                   |
| 9  | W-72700 | West bank | 24.2285, 89.7068 | 10%  | +30 m       | Past-year history raises risk; Bank height about -4.5 m above the river (DEM)                      |
| 10 | W-18300 | West bank | 24.6896, 89.6331 | 10%  | +30 m       | Bank height about -3.8 m above the river (DEM); Bank sits on an outer bend / in a recess           |
| 11 | W-28700 | West bank | 24.6021, 89.6602 | 9%   | -720 m      | Bank retreated 10 m in the last 4 weeks; Bank sits on an outer bend / in a recess                  |
| 12 | E-17500 | East bank | 24.7112, 89.7397 | 9%   | —           | Bank height about -6.2 m above the river (DEM); Bank sits on an outer bend / in a recess           |
| 13 | E-55500 | East bank | 24.4038, 89.8063 | 7%   | -30 m       | River is falling after high water; Little recent retreat, but the recent pattern still raises risk |
| 14 | E-12300 | East bank | 24.7572, 89.7320 | 7%   | —           | River is falling after high water; Past-year history raises risk                                   |
| 15 | W-73100 | West bank | 24.2249, 89.7061 | 7%   | -60 m       | Past-year history raises risk; Bank height about -4.5 m above the river (DEM)                      |
| 16 | E-56500 | East bank | 24.3949, 89.8053 | 7%   | -240 m      | Bank height about -3.8 m above the river (DEM); Bank sits on an outer bend / in a recess           |
| 17 | W-49700 | West bank | 24.4247, 89.7248 | 7%   | -1400 m     | Bank retreated 10 m in the last 4 weeks; Bank sits on an outer bend / in a recess                  |
| 18 | E-12900 | East bank | 24.7520, 89.7338 | 7%   | —           | Bank height about -6.2 m above the river (DEM); Bank sits on an outer bend / in a recess           |
| 19 | E-74900 | East bank | 24.2310, 89.8020 | 7%   | +0 m        | Bank retreated 10 m in the last 4 weeks; Bank sits on an outer bend / in a recess                  |
| 20 | E-12500 | East bank | 24.7555, 89.7326 | 7%   | —           | Bank height about -6.2 m above the river (DEM); Bank sits on an outer bend / in a recess           |



Measured on 2023–2025 hindcasts: on average 42% of the top 20 segments lost at least the threshold within 28 days, versus 4% for 'it eroded recently' (persistence); difference +38.2% (95% CI +30.6% to +46.7%).

Tiers: **Watch** = in this top-20 list. **Warning** = high risk plus retreat on the latest pass; it reaches households only after an official approves it on the dashboard. Raw risk maps stay with officials and partners; public views are aggregated to union level.

Data: Copernicus Sentinel-1 GRD (ESA), descending track 150, ~05:56 local time; banks traced on 10 m water masks. Reasons describe what the model used, not proven causes. Segments not seen on the latest pass carry no forecast.