Property Condition Report

تقرير حالة العقار

09 Oct 2026

8	47	18
Rooms inspected	Items rated	Photos captured

Good 45| Fair 2| Issues 0



09 Oct 2026, 05:14 AM

Property details

Type / النوع
Apartment

Building / المبنى
Marina Vista Residence — Sample

Unit / الوحدة
1807

Makani / مكاني
4523 7812 34

Area / المنطقة
Dubai Marina

City / المدينة
Dubai

Area (sqft) / المساحة
1285

Furnished / مفروش
Yes

Bedrooms / غرف النوم
2

Bathrooms / الحمامات
2

Tenancy details

Lease start / بداية الإيجار
10 Oct 2026

Lease end / نهاية الإيجار
09 Oct 2027

Contract / العقد
EJARI-SAMPLE-2026-10482

Inspection details

Inspector / المفتش
Layla Rahman (Sample Inspector)

Started (first photo) / وقت البدء (أول صورة)
09 Oct 2026, 05:14 AM

Inspection type / نوع الفحص
Move-in condition inspection (sample)

Landlord

Name / الاسم
Omar Hassan (Sample)

Phone / الهاتف
+971 50 555 0148

Email / البريد الإلكتروني
omar.hassan@example.test

Tenant

Name / الاسم
Sofia Bennett (Sample)

Phone / الهاتف
+971 55 555 0286

Email / البريد الإلكتروني
sofia.bennett@example.test


Rating legend دليل التقييم

Very Good / جيد جدا	No visible deterioration noted.
Good / جيد	Minor visible signs of use noted.
Fair / متوسط	Visible wear or deterioration noted.
Issue / مشكلة	A visible condition issue noted.

Inspection overview ملخص الفحص

Room	Items rated	Photos	Condition breakdown
Entrance & Hallway	5	0	Very Good 2 Good 3
Living & Dining Room	8	3	Very Good 3 Good 4 Fair 1
Kitchen	8	1	Very Good 3 Good 5
Primary Bedroom	6	1	Very Good 3 Good 3
Bedroom 2 / Study	5	0	Very Good 3 Good 2
Primary Bathroom	6	1	Very Good 3 Good 2 Fair 1
Guest Bathroom	5	0	Very Good 3 Good 2
Balcony	4	1	Very Good 1 Good 3
Property photos	—	5	—
Keys & Access Cards	—	3	—
Utility Meters	—	3	—
Total (all photos)	**47**	**18**	Very Good 21 Good 24 Fair 2

Fair / Issues items العناصر المتوسطة أو ذات المشكلات

Room	Item	Rating	Note	Photo
Living & Dining Room	Walls & paintwork	Fair / متوسط	Hairline crack approximately 55 cm long beside the balcony opening; no moisture staining observed.	
Primary Bathroom	Sealant & grout	Fair / متوسط	Light discolouration and wear at lower shower corner; renewal recommended.	—

Report Scope & Method

نطاق التقرير ومنهجيته

A. Purpose & Scope

أ. الغرض والنطاق

A1 This report records the visible condition of the property at the date and time of inspection shown in the report.

A1 يسجّل هذا التقرير الحالة المرئية للعقار في تاريخ ووقت الفحص المبيّنين فيه.

A2 This is not a snagging report, structural survey, engineering report, valuation or legal opinion.

A2 هذا التقرير ليس تقرير عيوب بناء ولا مسحاً إنشائياً ولا تقريراً هندسياً ولا تقييماً سعرياً ولا رأياً قانونياً.

A3 It does not assess build quality or hidden or latent defects.

A3 لا يقيّم هذا التقرير جودة البناء ولا العيوب المخفية أو الكامنة.

A4 It does not decide who is responsible for any condition, damage or cost, or whether anything is normal wear and tear.

A4 لا يحدد هذا التقرير الطرف المسؤول عن أي حالة أو ضرر أو تكلفة، ولا ما إذا كان أي أمر يُعدّ استهلاكاً عادياً.

A5 Furniture and belongings were not moved. Locked, concealed or inaccessible areas and items were not inspected, unless stated otherwise.

A5 لم يتم تحريك الأثاث أو الأغراض. ولم تُفحص المناطق والعناصر المغلقة أو المخفية أو التي يتعذّر الوصول إليها، ما لم يُذكر خلاف ذلك.

A6 The inspection is visual and non-invasive. Appliances, fittings and systems were not tested for function, safety or reliability, unless stated otherwise.

A6 الفحص بصري وغير تدخّلي. ولم تُختبر الأجهزة والتجهيزات والأنظمة من حيث التشغيل أو السلامة أو الموثوقية، ما لم يُذكر خلاف ذلك.

A7 Items that are not listed in this report were not assessed.

A7 العناصر غير المدرجة في هذا التقرير لم يتم تقييمها.

B. Photos

ب. الصور

B1 Photos were taken by the inspector using the MeInspect app during the inspection. Each photo shows the date and time it was captured.

B1 التقط المفتش الصور باستخدام تطبيق MeInspect أثناء الفحص، وتظهر كل صورة تاريخ ووقت التقاطها.

B2 Photos show only what is visible in the frame, and colours or brightness may differ from the real condition.

B2 تُظهر الصور ما هو مرئي في إطارها فقط، وقد تختلف الألوان أو الإضاءة عن الواقع.

B3 Photos are resized and compressed to keep the report file at a practical size.

B3 يتم تغيير حجم الصور وضغطها للحفاظ على حجم عملي لملف التقرير.

C. Ratings & Notes

ج. التقييمات والملاحظات

C1 Ratings are the inspector's visual assessment on the day, using the rating scale shown in this report. A rating is not a measurement and not a finding about cause or responsibility.

C1 التقييمات هي تقدير المفتش البصري في يوم الفحص وفق مقياس التقييم المبيّن في هذا التقرير. والتقييم ليس قياساً ولا حكماً بشأن السبب أو المسؤولية.

C2 Notes and descriptions are entered by the inspector. MeInspect does not verify them.

C2 يُدخل المفتش الملاحظات والأوصاف، ولا تتحقق MeInspect من صحتها.

D. Report Record

د. سجل التقرير

D1 Each report has a unique report ID and a generation date and time. The location (GPS) and IP address shown in the page footer were recorded by the app.

D1 لكل تقرير رقم تعريف فريد وتاريخ ووقت إنشاء. ويظهر في تذييل الصفحة الموقع (GPS) وعنوان IP اللذان سجّلهما التطبيق.

E. Parties, Tenancy & Signatures

هـ. الأطراف وعقد الإيجار والتوقيعات

E1 Property, party and tenancy details (including contract number and dates) were entered into the app. MeInspect has not verified them against any official record.

E1 أُدخلت بيانات العقار والأطراف وعقد الإيجار (بما في ذلك رقم العقد وتواريخه) في التطبيق، ولم تتحقق MeInspect منها مقابل أي سجل رسمي.

E2 Signatures were captured electronically in the app at the date and time shown.

E2 جرى التقاط التوقيعات إلكترونياً داخل التطبيق في التاريخ والوقت المبيّنين.

E3 By signing, a person confirms that they have reviewed this report and that, to the best of their knowledge, it reflects the condition of the property on the inspection date. Signing does not waive any right under the tenancy contract or the law. This report is not a tenancy contract and does not amend it.

E3 بالتوقيع، يؤكد الشخص أنه اطّلع على هذا التقرير وأنه، بحسب علمه، يعكس حالة العقار في تاريخ الفحص. ولا يُعدّ التوقيع تنازلاً عن أي حق بموجب عقد الإيجار أو القانون. وهذا التقرير ليس عقد إيجار ولا يعدّله.

E4 A party who did not sign has not confirmed this report. We recommend that such a party raises any disagreement in writing with the other parties within 7 days of receiving it. Not doing so does not by itself mean that the party accepts the report or affect any of their rights.

E4 الطرف الذي لم يوقّع لم يؤكد هذا التقرير. ونوصي هذا الطرف بإبلاغ الأطراف الأخرى كتابةً بأي اعتراض خلال 7 أيام من استلام التقرير. وعدم القيام بذلك لا يعني بحد ذاته قبول التقرير ولا يؤثر في أي من حقوقه.

F. Personal Data & Service Provider

و. البيانات الشخصية ومزوّد الخدمة

F1 This report contains personal data of the parties named in it, such as names, phone numbers, email addresses and signatures. Please store and share it carefully and only as needed.

F1 يتضمن هذا التقرير بيانات شخصية للأطراف المذكورة فيه، مثل الأسماء وأرقام الهاتف والبريد الإلكتروني والتوقيعات. يُرجى حفظه ومشاركته بعناية وبالقدر اللازم فقط.

F2 MeInspect provides the app used to prepare this report. It does not verify the observations recorded in it.

F2 توفّر MeInspect التطبيق المستخدم في إعداد هذا التقرير، ولا تتحقق من صحة الملاحظات المسجّلة فيه.

Keys & Access Cards المفاتيح وبطاقات الدخول

Keys

2 apartment keys — Both keys photographed and handed over.



09 Oct 2026, 06:14 AM

Access cards

2 building access cards — Generic sample cards; identifiers intentionally omitted.



09 Oct 2026, 06:14 AM

Parking remote

1 remote — Recorded with keys and access cards.



09 Oct 2026, 06:14 AM

Parking bay

B2-118 — Bay number supplied as dummy data; not independently verified.

Utility Meter Readings قراءات عدادات الخدمات

Electricity

DEWA sample reading: 018742 kWh



09 Oct 2026, 06:03 AM

Water

Sample reading: 00391 m³



09 Oct 2026, 06:06 AM

Gas / cooling

District cooling meter: 001284 RT-h



09 Oct 2026, 06:09 AM

Move-in comparison مقارنة بحالة الدخول

Move-in report attached: Sample Move-in Record.pdf. Reference retained with the inspection; contents not automatically interpreted.
Keys — at move-in: 2 apartment keys and 2 access cards; now: 2 apartment keys
Access cards — at move-in: 2 access cards and 1 parking remote; now: 2 building access cards
Pre-existing defects: Move-in reference noted minor paint marks in the hallway and light wear at the kitchen cabinet edge.
New defects identified by inspector: Hairline crack beside the living-room balcony opening and worn shower sealant were recorded during this sample inspection.

Entrance & Hallway المدخل

Entrance door & frame Good / جيد

Door opens and closes normally; light scuffing at lower edge.

Lock, handle & viewer Very Good / جيد جدا

Hardware secure with no visible damage.

Walls & paintwork Good / جيد

Small handling marks beside the console area.

Floor finish & skirting Very Good / جيد جدا

Tiles and skirting visually intact.

Lighting & switches Good / جيد *Fittings visually intact; function not electrically tested.*

Room Notes: Entrance was clear and accessible. Minor cosmetic wear only.

Living & Dining Room غرفة المعيشة

Walls & paintwork Fair / متوسط

Hairline crack approximately 55 cm long beside the balcony opening; no moisture staining observed.



09 Oct 2026, 05:16 AM


Ceiling & cornices Very Good / جيد جدا

No visible staining, sagging or open joints.

Flooring & skirting

Good / جيد

Minor normal-use marks near dining chairs.



09 Oct 2026, 05:14 AM

Windows & glazing

Very Good / جيد جدا[1]

Glazing intact and frames visibly clean.

Balcony door & track

Good / جيد

Track shows light dust and wear; glass intact.

Sockets, switches & lighting

Good / جيد

Covers secure; operational testing outside inspection scope.

Furniture & soft furnishings

Very Good / جيد جدا[1]

Sofa, dining set and TV console present without obvious damage.

Air-conditioning outlets

Good / جيد

Outlet covers clean; cooling performance not tested.



09 Oct 2026, 06:09 AM

Room Notes: Bright room with good overall presentation. One visible hairline crack requires monitoring.

Kitchen المطبخ

Cabinets, doors & handles Good / جيد

Minor rubbing to one lower cabinet edge; hinges visually aligned.



09 Oct 2026, 05:24 AM

Worktop & splashback Very Good / جيد جدا[1]

No chips or open joints observed.

Sink, tap & sealant Good / جيد

Light water spotting; sealant visually intact.

Hob & extractor Good / جيد

Clean appearance; appliances not function-tested.

Oven & microwave Very Good / جيد جدا[1]

Appliance fronts clean with no visible damage.

Refrigerator Good / جيد

Minor cosmetic mark on lower right door.

Flooring & skirting Very Good / جيد جدا[1]

Tiles intact and grout generally clean.

Sockets & isolators Good / جيد


Faceplates secure; electrical function not tested.

Room Notes: Kitchen was clean and serviceable in appearance. Appliances were recorded visually only.

Primary Bedroom غرفة النوم

Walls & paintwork Good / جيد

Two faint furniture rub marks behind bedside table.



09 Oct 2026, 05:35 AM

Ceiling Very Good / جيد جدا¹ *No visible staining or cracking.*

Flooring & skirting Good / جيد

Carpet clean with slight pile flattening at bedside.

Wardrobes & mirrors Very Good / جيد جدا¹

Doors aligned; mirrors free from cracks.

Window & blinds Good / جيد

Window frame clean; blinds show minor creasing.

Bed & furniture Very Good / جيد جدا¹

Bed frame and bedside units visually intact.

Room Notes: Room presented in good condition with normal signs of occupancy.

Bedroom 2 / Study غرفة النوم

Walls & paintwork Very Good / جيد جدا¹

Even finish with no obvious damage.

Flooring & skirting Good / جيد

Small surface mark close to desk position.

Wardrobe Very Good / جيد جدا¹

Interior shelves and sliding doors visually intact.

Window & blind Very Good / جيد جدا¹

No visible glass or frame damage.


Sockets, switches & lighting Good / جيد *Faceplates secure; function not tested.*

Room Notes: Used as a study and guest room; no significant defects noted.

Primary Bathroom الحمام

Vanity, basin & tap Very Good / جيد جدا

Surfaces clean and free from visible chips.



09 Oct 2026, 05:47 AM

Shower enclosure & fittings Good / جيد

Glass and metalwork intact.

Sealant & grout Fair / متوسط

Light discolouration and wear at lower shower corner; renewal recommended.

Toilet & flush plate Very Good / جيد جدا

No visible chips or cracks; function not tested.

Wall and floor tiles Very Good / جيد جدا

No cracked tiles observed.

Ventilation & lighting Good / جيد

Covers clean; extraction performance not tested.

Room Notes: Bathroom was clean. Localised wear to shower sealant should be renewed as routine maintenance.

Guest Bathroom الحمام

Vanity, basin & tap Good / جيد

Minor water spotting at tap base.

Shower enclosure Very Good / جيد جدا

Glass and hardware visibly intact.

Sealant & grout Good / جيد

Slight age-related colour variation.

Toilet Very Good / جيد جدا *No visible damage.*

Wall and floor tiles Very Good / جيد جدا *Tiles visually intact.*

Room Notes: Good visual condition with minor normal-use wear.

Balcony الشرفة

Floor tiles & drainage Good / جيد

Light outdoor dust and minor weathering; no standing water.



09 Oct 2026, 05:55 AM

Glass railing & handrail Very Good / جيد جدا[1]

Panels visibly intact and handrail secure in appearance.

Walls & soffit Good / جيد

Minor environmental dust; no significant staining.

External light Good / جيد

Fitting visually intact; function not tested.

Room Notes: Balcony accessible with clear drainage points and unobstructed view.


Additional property photos صور إضافية للعقار



09 Oct 2026, 05:14 AM



09 Oct 2026, 05:24 AM



09 Oct 2026, 05:35 AM



09 Oct 2026, 05:47 AM

General notes ملاحظات عامة

SAMPLE REPORT — All names, contact details, identifiers, readings and signatures are fictional. Stock images are used to emulate a realistic completed property condition inspection. This document is for website demonstration and upload testing only, and must not be relied upon for any real property or tenancy decision.

Legal Declaration

By digitally signing below, all signing parties confirm they have reviewed the complete MeInspect Property Condition Report and agree that, to the best of their knowledge, it reflects the condition of the property on the inspection date. Signing does not waive any right under the tenancy contract or the law.

إقرار

بالتوقيع الرقمي أدناه، يؤكد الأطراف الموقعون أنهم اطلعوا على تقرير حالة العقار الكامل من MeInspect، ويوافقون على أنه، بحسب علمهم، يعكس حالة العقار في تاريخ الفحص. ولا يُعدّ التوقيع تنازلاً عن أي حق بموجب عقد الإيجار أو القانون.

Landlord / المالك

Omar Hassan (Sample)

O. Hassan — sample

09 Oct 2026, 06:22 AM

IP: 192.0.2.41

Tenant / المستأجر

Sofia Bennett (Sample)

S. Bennett — sample

09 Oct 2026, 06:24 AM

IP: 198.51.100.27

Inspector / المفتش

Layla Rahman (Sample Inspector)

L. Rahman — sample

09 Oct 2026, 06:26 AM

IP: 203.0.113.18

Report ID: RPT-SAMPLE-2

Verification code: sample-20261009-dubai-60bfd115244013cd

SHA-256 content hash: 60bfd115244013cd6e405f9ac27e78d61f00edf7708c7dd305f81df4b69e9f22

https://app.meinspect.com/v/sample-20261009-dubai-60bfd115244013cd

The printed hash identifies the report content. Select the PDF on the verification page to check the final file.