COLLISION_REPORT Â· comprobaciÃ³n sistemÃ¡tica entre familias

VÃ³xeles de 0,20 m. Se distingue el contacto intencionado (apoyo, anclaje, plantaciÃ³n) de la interpenetraciÃ³n accidental.



familia A	familia B	vÃ³xeles	mÂ³	lectura
RIBBON	STRUCTURE	17119	136.95	intencionado
DETAIL	STRUCTURE	14460	115.68	REVISAR
DETAIL	RIBBON	13974	111.79	REVISAR
DETAIL	PLANTER	4173	33.38	REVISAR
DETAIL	VEGETATION	2417	19.34	REVISAR
PLANTER	VEGETATION	2210	17.68	intencionado
CANOPY	STRUCTURE	1598	12.78	intencionado
STRUCTURE	WATER	1089	8.71	intencionado
PLANTER	WATER	758	6.06	intencionado
DETAIL	WATER	661	5.29	REVISAR
STRUCTURE	VEGETATION	569	4.55	intencionado
CABLE	STRUCTURE	560	4.48	REVISAR
PODS	STRUCTURE	540	4.32	intencionado
CABLE	DETAIL	530	4.24	REVISAR
VEGETATION	WATER	378	3.02	intencionado
CABLE	CANOPY	349	2.79	REVISAR
PLANTER	STRUCTURE	325	2.60	intencionado
CANOPY	DETAIL	272	2.18	REVISAR
FURNITURE	VEGETATION	253	2.02	intencionado
DETAIL	FURNITURE	212	1.70	REVISAR
PODS	VEGETATION	160	1.28	REVISAR
CANOPY	PODS	142	1.14	REVISAR
CANOPY	WATER	88	0.70	intencionado
CABLE	WATER	82	0.66	REVISAR
PODS	WATER	78	0.62	REVISAR
DETAIL	PODS	49	0.39	REVISAR

par	objeto A	objeto B	x,y,z	vÃ³xeles	mÂ³
PODSÃ—VEGETATION	POD_TRAIN	VEGA_HELECHO_M	-58,12,0.2	7	0.056
PODSÃ—VEGETATION	POD_TRAIN	VEG2_HUERTO	-57,11,0.1	7	0.056
PLANTERÃ—RIBBON	MAST_2	RIB_SUP	8,25,0.3	7	0.056
DETAILÃ—VEGETATION	BENCH_CANTO_1_0	VEGA_HELECHO_H	-2,9,0.4	6	0.048
DETAILÃ—VEGETATION	LIFT_TOWER	VEGA_HELECHO_F	77,6,0.7	6	0.048
DETAILÃ—WATER	DECK_JUNTAS	BASIN_B-C1a	-56,9,6.0	6	0.048
CABLEÃ—STRUCTURE	LCBL	PRIMARY_C2-L2	18,5,8.9	6	0.048
CABLEÃ—STRUCTURE	LCBL	SAT_C3-L2	62,-2,8.2	6	0.048
PODSÃ—VEGETATION	POD_TRAIN	VEGA_GRAMINEA_M	-59,9,0.2	6	0.048
RIBBONÃ—WATER	RIBBON_DECK	BASIN_B-C1a	-56,9,6.0	6	0.048
DETAILÃ—STRUCTURE	LIFT_TOWER	PRIMARY_C1-L2	-69,3,7.8	5	0.040
DETAILÃ—STRUCTURE	LCBL_ANCLA	NODE	43,-1,10.0	5	0.040
DETAILÃ—RIBBON	LIFT_TOWER	RIBBON_DECK	-69,4,6.0	5	0.040
DETAILÃ—RIBBON	LIFT_TOWER	RIBBON_RAIL	-69,4,6.1	5	0.040
DETAILÃ—VEGETATION	BENCH_CANTO_3_0	VEGA_HELECHO_M	-63,3,0.4	5	0.040
CABLEÃ—STRUCTURE	LCBL	SAT_C2-L2	7,22,8.7	5	0.040
CABLEÃ—STRUCTURE	LCBL	NODE	43,-1,9.9	5	0.040
CABLEÃ—STRUCTURE	LCBL	SAT_C3-L2	61,-0,8.2	5	0.040
CABLEÃ—STRUCTURE	LCBL	PRIMARY_C3-L2	60,-3,8.5	5	0.040
CANOPYÃ—DETAIL	LEAF_M1	STAIR_SB	67,-6,4.5	5	0.040
PODSÃ—VEGETATION	POD_TRAIN	VEG2_HUERTO	-58,11,0.5	5	0.040

CONTACTOS INTENCIONADOS reconocidos: mÃ¡stilâ€”diana (anclaje), estructuraâ€”cinta (apoyo), jardineraâ€”vegetaciÃ³n (plantaciÃ³n), estructuraâ€”agua (bajantes y aros de balsa), estructuraâ€”cÃ¡psula (cunas y pies). El resto se marca para revisiÃ³n.