

Common Effluent Treatment Plants: A Case Study from Gujarat

Paryavaran Suraksha Samiti



CETP Ankleshwar Report - CPCB

Parameters	PH	TSS	TDS	BOD	COD	O & G	NH3-N	Phenol
Sampling Date	5.5 – 8.5	100 mg/l	2100 mg/l	30 mg/l	100 mg/l	10 mg/l	50 mg/l	1 mg/l
05/04/03	7.5	84	3476	9	174	6.3	50	
22/07/03	7.5	36	2546	11	112		35.3	
08/06/04	7.2	32	2184	12	645	2.1	200	4.04
26-7-2004 & 27-7-2004	7.7	22	2570	26	115	4	36	3.68
22-9-2004 & 23-9-2004	7.85	17	3221	5.3	157	7.6		
18-11-2004 & 19-11-2004	7.8	10	3032	11	153	6.2	56	
24/06/05	7.8	10	3032	11	153	6.2	56	
July 2006	7.4	221	20801	360	2268	26	386	

Paryavaran Suraksha Samiti

CPCB - CETP Panoli Report

Parameters	Permissible Limit	July 2006	November 2006
pH	5.5 – 8.5	7.4	7.4
TSS	100 mg/l	164	282
TDS	2100 mg/l	31341	23658
BOD	30 mg/l	820	1091
COD	100 mg/l	4104	7520
O & G	10 mg/l	45	
NH3-N	50 mg/l		1649

FETP REPORT, Ankleshwar- GPCB

Parameters	Permissible Limit	04/06/07
PH	5.5 – 8.5	7.3
TSS	100 mg/l	196
TDS	2100 mg/l	11352
BOD	30 mg/l	352
COD	100 mg/l	1527
O & G	10 mg/l	4.4
NH3-N	50 mg/l	717
S	0.5 mg/l	27.2
SO4	1000 mg/l	1125
Cl	600 mg/l	3999
Phenol	1 mg/l	3.25

Paryavaran Suraksha Samiti

Damanganga Water Quality in Vapi- Daman Region – A trend Analysis by CPCB

	Year	Parameters						
		PH	DO	TDS	BOD	COD	O & G	NH3 – N
Sampling Locations		5.5 – 8.5	4 – 6 mg/l	2100 mg/l	30 mg/l	100 mg/l	10 mg/l	50 mg/l
Damanganga River U/S of CETP Discharge	2004	8	7.7	217	BDL	7	1.2	0.7
	2005	7.81	6.92	240	1.2	5	BDL	0.56
	2006	7.07 – 7.93	7.1 – 7.6	178 – 194	1.2 – 2.2	12 – 24	--	BDL – 0.6
	2007	8.4	7.4	163	2.3	8.6	BDL	0.56
Damanganga River D/S of CETP Discharge	2004	7.07 – 7.93	BDL	5751	140	556	3.6	306.6
	2005	7.07 – 7.93	1.03	6126	28	110	0.8	8.4
	2006	6.41 – 6.63	3.0 – 4.4	1064 – 2706	16 – 19	80 – 93	--	14 – 21
	2007	7.4	1.1	2673	50	246	1.7	72
Damanganga River near mouth of Estuary	2004	7.7	2.5	59248	3	75	--	--
	2005	6.8	2.1	31832	5.6	106	--	6.4

Paryavaran Suraksha Samiti


Analysis of Water Near CETP, VAPI

- CPCB

Sampling Point		River Damanganga at U/S of CETP, Vapi Discharge	River Damanganga at 400m D/S of CETP, Vapi Discharge		
Sampling Date		12/10/06	10/05/07	12/10/06	10/05/07
PH	5.5 – 8.5	7.18	8.4	6.51	7.4
TSS	100 mg/l	2	27	24	80
TDS	2100 mg/l	194	168	2706	2673
BOD	30 mg/l	1.6	2.3	16	50
COD	100 mg/l	12	8.6	80	246
NH3-N	50 mg/l	BDL	0.56	14	72
SO4	1000 mg/l	11	10.5	398	1365
Cl	600 mg/l	13	17	298	1234

Paryavaran Suraksha Samiti

Effluent Channel Project Map - Vadodara



Paryavaran Suraksha Samiti

Unmonitored dumping of effluent in the ECP - Vadodara



Paryavaran Suraksha Samiti

Overflow of effluent from the ECP - Vadodara



Paryavaran Suraksha Samiti

& who does this



Paryavarana Suraksha Samiti

Various “utilities” of ECP in Vadodara



Paryavaran Suraksha Samiti

“Handling” of Haz Waste from ECP - Vadodara



Paryavaran Suraksha Samiti

**Block No. 364, Village Luna, Taluka Padra (In 2003)
Polluted water drawn from 200 ft. deep borehole**



Paryavaran Suraksha Samiti

ECP Final Outlet at 'J' Point Sarod



Paryavaran Suraksha Samiti

Unmonitored Dumping of Effluent into Mahi Estuary



Paryavaran Suraksha Samiti

Chemicals flowing into Mini river from Nandesari Industrial Estate - Vadodara



Paryavaran Suraksha Samiti

Illegal Effluent flowing in the open drain - Ankleshwar



Paryavaran Suraksha Samiti

Industrial effluent contaminating Amla Khadi by violating Guj. HC order - Ankleshwar



24/03/05 11:56

Paryavaran Suraksha Samiti

Industrial effluent contaminating Amla Khadi - Ankleshwar



Paryavaran Suraksha Samiti

Thank You

Paryavaran Suraksha Samiti