
Matched ordinary controls, noise repeat 0
Prior point is not a Bayes-optimal material image; known-wall arm reads only wall truth after nonoracle seals
Offline truth
Prior parameter-mean point
position 0.554; IoU 0.000
Wall-first fixed
position 0.031; IoU 0.573
Known-wall oracle (diagnostic)
position 0.038; IoU 0.520
Normal wall / circle
Boundary-connected air defect
(historical ID: blind_cavity)
position 0.217; IoU 0.028
position 0.004; IoU 0.780
position 0.014; IoU 0.830
Strong target / ellipse
position 0.267; IoU 0.000
position 0.077; IoU 0.477
position 0.049; IoU 0.597
y/λ_0
x/λ_0
Target real permittivity at f=1