




1. SPRING CURVE SHALL BE WITHIN THE  ZONE (CHART ON RIGHT).

2. AFTER DURABILITY TEST BELOW, SPRING CURVE SHALL BE WITHIN THE  ZONE.

RADIAL LOAD P1 650~6500 kg

AXIAL LOAD P2 0~5100 kg

FREQUENCY 1 Hz


NUMBER OF CYCLES 1.2×10^5

3. INNER SLEEVE (2) AND OUTER SLEEVE (3) SHALL BE CHEMICAL CONVERSION COATED.

4. NO DURABILITY PROBLEMS UNDER THE OPERATING CONDITIONS BELOW.

1) EXPOSED TO RAIN AND SUNLIGHT.

2) AMBIENT TEMPERATURE -50°C TO $+80^{\circ}\text{C}$



THIRD	2	INNER SLEEVE	1	STKM13A						
ANGLE	1	RUBBER	1	NR		3	OUTER SLEEVE	1	STKM11A	
PROJ.	NO.	DESCRIPTION	QTY	MATERIAL	REMARKS	NO.	DESCRIPTION	QTY	MATERIAL	REMARKS
4						 倉敷化工株式会社 INDUSTRIAL MACHINERY DIVISION				
3										
2										
1	DRAWING CONVERTED TO CAD; MATERIAL CORRECTED			'19.10.03	YOKOBE					
CODE	REVISION HISTORY / CHANGES			DATE	APPD	REV.	KOMATSU LTD.			
APPROVED		CHECKED	DRAWN	DATE CREATED		SCALE	NAME	CUSHION		
FUJITA		ARIMATSU	HOTO	YEAR MONTH DAY S61,11,25		1:1	PART NO.	154-01-21310		