





1. SPRING CURVE SHALL BE WITHIN THE ZONE (CHART ON RIGHT).
2. AFTER THE DURABILITY TEST BELOW, SPRING CURVE SHALL BE WITHIN THE ZONE.
- RADIAL LOAD P1 650~6500 kg
- AXIAL LOAD P2 0~5100 kg
- FREQUENCY 1 Hz
- NUMBER OF CYCLES 1.2×10^5
3. INNER SLEEVE (2) AND OUTER SLEEVE (3) SHALL BE CHEMICAL CONVERSION COATED.
4. NO DURABILITY PROBLEMS UNDER THE OPERATING CONDITIONS BELOW.
- 1) EXPOSED TO RAIN AND SUNLIGHT.
- 2) AMBIENT TEMPERATURE -50°C TO $+80^{\circ}\text{C}$



① STKM13A											
THIRD	2	INNER SLEEVE	1	STKM13A							
ANGLE	1	RUBBER	1	NR		3	OUTER SLEEVE	1	STKM11A		
PROJ.	NO.	DESCRIPTION	QTY	MATERIAL	REMARKS	NO.	DESCRIPTION	QTY	MATERIAL	REMARKS	
④							 倉敷化工株式会社 INDUSTRIAL MACHINERY DIVISION				
③											
②											
①	DRAWING CONVERTED TO CAD; MATERIAL CORRECTED			'19.10.03	YOKOBE	TATANO	KOMATSU LTD.				
CODE	REVISION HISTORY / CHANGES			DATE	APPD	REV.					
APPROVED		CHECKED	DRAWN	DATE CREATED		SCALE	NAME	CUSHION			
FUJITA		ARIMATSU	HOTO	YEAR MONTH DAY S61,11,25		1:1	PART NO.				
								154-01-21310			