
Auditoría

campusyformacion.es

El plugin wordpress-seo está desactualizado.

```
[+] wordpress-seo
| Location: http://campusyformacion.es/wp-content/plugins/wordpress-seo/
| Last Updated: 2021-06-15T06:39:00.000Z
| [!] The version is out of date, the latest version is 16.5
| Found By: Comment (Passive Detection)
| Version: 16.3 (60% confidence)
| Found By: Comment (Passive Detection)
| - https://campusyformacion.es/, Match: 'optimized with the Yoast SEO plugin v16.3 -'
```

La página de acceso a Worpress es fácilmente accesible desde /wp-admin



Se han identificado los siguientes usuarios de Wordpress:

```
[i] User(s) Identified:
[+] admin admin
  Found By: Rss Generator (Passive Detection)
  Confirmed By: Rss Generator (Aggressive Detection) Productos
[+] admin
  Found By: Wp Json Api (Aggressive Detection)
    https://campusyformacion.es/wp-json/wp/v2/users/?per_page=100&page=1
[+] becarios_mkd
  Found By: Wp Json Api (Aggressive Detection)
    - https://campusyformacion.es/wp-json/wp/v2/users/?per_page=100&page=1
  Confirmed By: Author Id Brute Forcing - Author Pattern (Aggressive Detection)
[+] irene-barroso
  Found By: Wp Json Api (Aggressive Detection)
    - https://campusyformacion.es/wp-json/wp/v2/users/?per_page=100&page=1
  Confirmed By: Author Id Brute Forcing - Author Pattern (Aggressive Detection)
[+] soporte_n66×1595
  Found By: Wp Json Api (Aggressive Detection)
    https://campusyformacion.es/wp-json/wp/v2/users/?per_page=100&page=1
  Confirmed By: Author Id Brute Forcing - Author Pattern (Aggressive Detection)
[+] beatriz
 | Found By: Author Id Brute Forcing - Author Pattern (Aggressive Detection)
[+] paco
 | Found By: Author Id Brute Forcing - Author Pattern (Aggressive Detection)
[+] alvarolucena
 | Found By: Author Id Brute Forcing - Author Pattern (Aggressive Detection)
```

No se ha configurado el header X-Frame-Options y las cookies no han sido aseguradas.

