

DI62W-01

Power window switch circuit

WIRING DIAGRAM





INSPECTION PROCEDURE

1 | Check[the[power[window[switch.[See[page[BE-109]]

NG□

Replace[the[power[window[switch.

OK

2 Check wireharness and connector between power window switch and body ECU.

NG□

Repair or replace wireharness or connector.

OK

3 Check wireharness and connector between power window switch and body ground.

NG[]

Repair or replace wireharness or connector.

OK

Proceed to next circuit inspection shown on problem symptoms table (See page DI-554).