

# **TEST REPORT**

報告號碼: HC30221A/2018

頁數: 1 of 11

日期: April 25, 2018

薩摩亞商先豐科技股份有限公司 台北市松山區民權東路三段 178 號 7 樓

以下產品由客戶提供並確認規格如下:

產品名稱: Data Collection Station 資料採集器

產品型號/編號: DCS V1.1/S18030001, S18030002;

DCS V2.1/S18030002, S18030004

生產或供應廠商: 薩摩亞商先豐科技股份有限公司

 原產國:
 台灣

 數量:
 共4件

測試執行日期: Mar. 29, 2018 to Apr. 3, 2018

我們依照客戶要求,根據客戶送交之樣品進行測試,結果如下:

委託測試要求:(依照客戶提供之測試規格進行試驗,詳細內容請參照附頁。)

- 1. 冷熱衝擊試驗
- 2. 温濕度循環試驗
- 3. 振動試驗

測試結果: -如附頁所示-

\*於 2018 年 4 月 10 日簽發之報告(報告號碼: HC30221/2018)在此宣告作廢並由本報告(報告號碼: HC30221A/2018)取代。

Signed for and on behalf of SGS TAIWAN Ltd.

偉誠

曾偉誠 技術經理

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/terms.and\_conditions.htm">www.sgs.com/terms.and\_conditions.htm</a> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sgs.com/terms.ac/edocument.htm">www.sgs.com/terms.ac/edocument.htm</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.35, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號 SGS Taiwan Ltd.

No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號



# TEST REPORT

報告號碼: HC30221A/2018

頁數: 2 of 11

# 1. 冷熱衝擊試驗:

試驗設備:

名稱	<b>廠</b> 牌	型號	序號
溫度循環試驗機	ESPEC	EGNX28-15CW	1737004

實驗室環境條件:


環境溫度:

 $(25 \pm 3)$  °C

環境濕度:

 $(55 \pm 20)$  % RH

#### 試驗方法/規格:



- 樣品狀態: 非操作狀態
- 試驗中,溫度轉換 20K/ 分鐘
- 試驗後以目視方式檢查樣品外觀及功能檢查。
- 功能檢查:將樣品連接額定電源,確認樣品開機功能是否正常。

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sus.com/terms">www.sus.com/terms</a> and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sus.com/terms">www.sus.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.

No.31, No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, New Taipei City, Taiwan/新北市五股工業區五權路 31 號, 33 號, 35 號

台灣檢驗科技股份有限公司\_

t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sgs.com



報告號碼: HC30221A/2018

頁數: 3 of 11

代測樣品:

DCS V1.1/S18030001; 型號/編號:

DCS V2.1/S18030002

共2件 數量:

測試結果:

<b>檢查項目</b> 樣品型號/編號	外觀檢查 (目視檢查)	功能檢查
DCS V1.1/ S18030001	無損壞	正常
DCS V2.1/ S18030002	無損壞	正常

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/terms">www.sgs.com/terms</a> and conditions, htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sgs.com/terms">www.sgs.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司

t (886-2) 2299-3279 f (886-2) 2299-9558



報告號碼: HC30221A/2018

頁數: of 11

# 2. 温濕度循環試驗:

#### 試驗設備:

名稱	廠牌	型號	序號
可程式型恆溫恆濕試驗機	KSON	THS-D6TS-150+LN2	A0559

#### 實驗室環境條件:

環境溫度:

 $(25 \pm 3)$  °C

環境濕度:

 $(55 \pm 20)$  % RH

#### 試驗方法/規格:

順序	溫度 (℃)	濕度 (% RH)	時間(小時)
1	25→0	50→-	
2	0	-	6
3	0→40	-→75	-
4	40	75	4
5	40→60	75→95	-
6	60	95	6
7	60→25	95→50	-

樣品狀態: 操作狀態

試驗後以目視方式檢查樣品外觀及功能檢查。

功能檢查:將樣品連接額定電源,確認樣品開機功能是否正常。

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責;同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/terms">www.sgs.com/terms</a> and conditions, htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sgs.com/terms">www.sgs.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.



報告號碼: HC30221A/2018

頁數: 5 of 11

代測樣品:

DCS V1.1/S18030001, S18030002; 型號/編號:

DCS V2.1/S18030002, S18030004

數量: 共4件

測試結果:

檢查項目 樣品型號/編號	外觀檢查 (目視檢查)	功能檢查
DCS V1.1/ S18030001	無損壞	正常
DCS V1.1/ S18030002	無損壞	正常
DCS V2.1/ S18030002	無損壞	正常
DCS V2.1/ S18030004	無損壞	正常



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/terms">www.sgs.com/terms</a> and conditions, htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sgs.com/terms">www.sgs.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.



# TEST REPORT

報告號碼: HC30221A/2018

頁數: of 11

# 3. 振動試驗:

#### 試驗設備:

名稱	廠牌	型號	序號
電磁式高頻振動試驗機	King Design	EM-800F2K-50N120	RU104080389
控制器	Dactron	COMET 200	10539718
控制加速規	PCB	353B34	143550
電磁式高頻振動試驗機	King Design	EM-5000F2K-75N600	10923742
控制器	Crystal	spider	1001664
控制加速規	WR	793-6	A4632
控制加速規	PCB	356A24	162319

實驗室環境條件:

環境溫度:  $(25 \pm 3)$  °C  $(55 \pm 20) \% RH$ 環境濕度:

試驗方法/ 規格:

樣品狀態: 操作狀態 振動波形: 正弦波

振動頻率範圍:  $(5 \sim 33) \text{ Hz}$ 位移量(D<sub>0-p</sub>): 0.19 mm

掃描速率: 1 octave/ minute

振動方向: X, Y, Z 軸 (如照片 9~20)

試驗時間: 3 分鐘/ 軸

於樣品指定位置上黏貼加速規並記錄是否有共振頻率產生。 (如照片 9~11, 15~17 所示)

試驗後以目視方式檢查樣品外觀及功能檢查。

功能檢查:將樣品連接額定電源,確認樣品開機功能是否正常。

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sgs.com/terms">www.sgs.com/terms</a> and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sgs.com/terms">www.sgs.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, New Taipei City, Taiwan/新北市五股工業區五權路 31 號, 33 號, 35 號 SGS Taiwan Ltd.

台灣檢驗科技股份有限公司\_



報告號碼: HC30221A/2018

頁數: 7 of 11

代測樣品:

DCS V1.1/S18030001, S18030002; 型號/編號:

DCS V2.1/S18030002, S18030004

數量: 共4件

測試結果:

1. 共振搜尋結果:

Check Item			DE /
Strate //torre No	X axis	Y axis	單位: Hz Z axis
Style/Item No.  DCS V1.1/ S18030001		無共振	無共振
DCS V1.1/ S18030002	無共振	無共振	無共振
DCS V2.1/ S18030002	無共振	無共振	無共振
DCS V2.1/ S18030004	無共振	無共振	無共振

#### 2. 外觀檢查 (目視檢查) & 功能檢查:

檢查項目 樣品型號/編號	外觀檢查 (目視檢查)	功能檢查
DCS V1.1/ S18030001	無損壞	正常
DCS V1.1/ S18030002	無損壞	正常
DCS V2.1/ S18030002	無損壞	正常
DCS V2.1/ S18030004	無損壞	正常

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sus.com/terms">www.sus.com/terms</a> and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sus.com/terms">www.sus.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.

t (886-2) 2299-3279

No.31, No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, New Taipei City, Taiwan/新北市五股工業區五權路 31 號, 33 號, 35 號

台灣檢驗科技股份有限公司


f (886-2) 2299-9558



報告號碼: HC30221A/2018

頁數: 8 of 11

#### 試驗照片:



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sus.com/terms">www.sus.com/terms</a> and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sus.com/terms">www.sus.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.




# **TEST REPORT**

報告號碼: HC30221A/2018

頁數: of 11

#### 試驗照片--續:



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sus.com/terms">www.sus.com/terms</a> and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sus.com/terms">www.sus.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.

No.31, No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, New Taipei City, Taiwan/新北市五股工業區五權路 31 號, 33 號, 35 號

11. 加速規黏貼位置: Z軸 DCS V1.1/S18030001

12. 振動試驗: X 軸

DCS V1.1/S18030001, S18030002



報告號碼: HC30221A/2018

頁數: 10 of 11

#### 試驗照片--續



13. 振動試驗: Y 軸 DCS V1.1/S18030001, S18030002



14. 振動試驗: Z 軸 DCS V1.1/S18030001, S18030002



加速規黏貼位置:X軸 DCS V2.1/S18030002



16. 加速規黏貼位置: Y 軸 DCS V2.1/S18030002



17. 加速規黏貼位置: Z軸 DCS V2.1/S18030002



18. 振動試驗: X 軸 DCS V2.1/S18030002, S18030004

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sos.com/terms">www.sos.com/terms</a> and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sos.com/terms">www.sos.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.



報告號碼: HC30221A/2018

頁數: 11 of 11

試驗照片--續:



19. 振動試驗: Y 軸 DCS V2.1/S18030002, S18030004



20. 振動試驗: Z 軸 DCS V2.1/S18030002, S18030004

以下空白

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="https://www.sus.com/terms">www.sus.com/terms</a> and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="https://www.sus.com/terms">www.sus.com/terms</a> e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.

No.31, No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, New Taipei City, Taiwan/新北市五股工業區五權路 31 號, 33 號, 35 號

台灣檢驗科技股份有限公司

t (886-2) 2299-3279 f (886-2) 2299-9558 www.tw.sgs.com