

Report No.: HC30221B/2018

Page: of

April 25, 2018 Date:

SAMOA MTM+ TECHNOLOGY CORPORATION TAIWAN BRANCH 7F, NO.178, MINQUAN EAST ROAD SECTION 3, SONGSHAN DISTRICT, TAIPEI, TAIWAN, R.O.C.

The following merchandise was submitted and identified by the vendor as:

Product Description: **Data Collection Station**

Style/ Item No.: DCS V1.1/S18030001, S18030002;

DCS V2.1/S18030002, S18030004

Manufacturer/ Vendor: Samoa MtM+ Technology Corporation Taiwan Branch

Country of Origin: Taiwan

Total 4 pieces Quantity:

Testing Period: Mar. 29, 2018 to Apr. 3, 2018

We have tested the submitted sample(s) as requested and the following results were obtained:

(According to client's test specification, please see following sheets in detail.) Test Required:

1. Thermal Shock Test

2. Temperature / Humidity Cycling Test

3. Vibration Test

Test Results: - PLEASE SEE ATTACHED SHEETS -

Signed for and on behalf of SGS TAIWAN Ltd.

Winson Tseng Technical Manager

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sus.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sus.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, foregy or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

No.31, No.33, No.35, Wu Chyuan Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五權路 31 號, 33 號, 35 號

No.134, Wu Kung Road, New Taipei Industrial Park, Wuku District, New Taipei City, Taiwan/新北市五股區新北產業園區五工路 134 號



Report No.: HC30221B/2018

Page: 2 of 11

1. Thermal Shock Test:

Test Equipment:


Name	Brand	Model	Serial No.
Thermal Shock Testing Chamber	ESPEC	EGNX28-15CW	1737004

Lab Environmental Conditions:

Ambient temperature: (25 ± 3) °C

Ambient humidity: (55 ± 20) % RH

Test Method/ Specification:



Sample condition: Non-Operating.

- The temperature transition time shall be 20K/ minute.
- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Connect specimen(s) with rated power 110 V_{AC}, then examine whether the booting function could be work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sos.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sos.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.



Report No.: HC30221B/2018

Page: 3 of 11

Specimen:

Style/ Item No.: DCS V1.1/S18030001;

DCS V2.1/ S18030002

Total 2 pieces Quantity:

Test Result:

Check Item Style/ Item No.	Appearance Check (visual check)	Functional check
DCS V1.1/ S18030001	No visible damage	Normal
DCS V2.1/ S18030002	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com/terms and conditions, htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Report No.: HC30221B/2018

Page: of 11

2. Temperature / Humidity Cycling Test:

Test Equipment:

Name	Brand	Model	Serial No.
Programmable Temperature & Humidity Chamber	KSON	THS-D6TS-150+LN2	A0559

Lab Environmental Conditions:

Ambient temperature:

Ambient humidity: (55 ± 20) % RH

Test Method/ Specification:

Step	Temperature (℃)	Humidity (%RH)	Time (hours)
1	25→0	50→-	- 8
2	0	-	6
3	0→40	-→75	0
4	40	75	4
5	40→60	75→95	-
6	60	95	6
7	60→25	95→50	-
otal cycl	e: Total 1 cycle		

- Sample condition: Operating.
- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Connect specimen(s) with rated power 110 V_{AC}, then examine whether the booting function could be work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sos.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sos.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.



Report No.: HC30221B/2018

Page: of 11

Specimen:

Style/ Item No.: DCS V1.1/S18030001, S18030002;

DCS V2.1/S18030002, S18030004

Quantity: Total 4 pieces

Test Result:

Check Item Style/ Item No.	Appearance Check (Visual check)	Functional check
DCS V1.1/ S18030001	No visible damage	Normal
DCS V1.1/ S18030002	No visible damage	Normal
DCS V2.1/ S18030002	No visible damage	Normal
DCS V2.1/ S18030004	No visible damage	Normal





Report No.: HC30221B/2018

Page: of 11

3. Vibration Test:

Test Equipment:

Name	Brand	Model	Serial No.	
Vibration Test System	King Design	EM-800F2K-50N120	RU104080389	
Controller	Dactron	COMET 200	10539718	
Control Accelerometer	PCB	353B34	143550	
Vibration Test System	King Design	EM-5000F2K-75N600	10923742	
Controller	Crystal	spider	1001664	
Control Accelerometer	WR	793-6	A4632	
ICP Accelerometer	PCB	356A24	162319	

Lab Environmental Conditions:

Ambient temperature: (25 ± 3) °C $(55 \pm 20) \% RH$ Ambient humidity:

Test Method/ Specification:

Sample condition: Non-Operating

Wave form: Sinusoidal Frequency: $(5 \sim 33) \text{ Hz}$ Amplitude (D_{p-p}): 0.19mm

Sweep Rate: 1 octave/ minute

Direction: X, Y, Z axes (As show in photo $9 \sim 20$)

3 minutes/axis Test duration:

- Measuring accelerometer is attached on the designated position of specimen in each axis for Resonance search. (As show in photo $9 \sim 11$, $15 \sim 17$)
- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Connect specimen(s) with rated power 110 V_{AC}, then examine whether the booting function could be work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

台灣檢驗科技股份有限公司



Report No.: HC30221B/2018

Page: of 11

Specimen:

Style/ Item No.: DCS V1.1/S18030001, S18030002;

DCS V2.1/S18030002, S18030004

Quantity: Total 4 pieces

Test Result:

1. Resonance Search Result:

Check Item	Major Resonance Frequency Unit: Hz		
Style/Item No.	X axis	Y axis	Z axis
DCS V1.1/ S18030001	No resonance	No resonance	No resonance
DCS V1.1/ S18030002	No resonance	No resonance	No resonance
DCS V2.1/ S18030002	No resonance	No resonance	No resonance
DCS V2.1/ S18030004	No resonance	No resonance	No resonance

2. Examination of Product (Appearance check) & Functional check:

Check Item Style/ Item No.	Appearance Check (Visual check)	Functional check
DCS V1.1/ S18030001	No visible damage	Normal
DCS V1.1/ S18030002	No visible damage	Normal
DCS V2.1/ S18030002	No visible damage	Normal
DCS V2.1/ S18030004	No visible damage	Normal

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sus.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sus.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

t (886-2) 2299-3279

www.tw.sgs.com

No.31, No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, New Taipei City, Taiwan/新北市五股工業區五權路 31 號, 33 號, 35 號

SGS Taiwan Ltd.



Report No.: HC30221B/2018

Page: of 11

Test Photos:



Appearance of specimen: DCS V1.1/S18030001



Appearance of specimen: DCS V1.1/S18030002



Appearance of specimen: DCS V2.1/S1803002



Appearance of specimen: DCS V2.1/S1803004



Thermal Shock Test



6. Thermal Shock Test

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sus.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sus.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.



Report No.: HC30221B/2018

Page: of 11

Test Photos--Continued:



Temperature / Humidity Cycling Test



Temperature / Humidity Cycling Test



Location of measuring accelerometer attached (X axis): DCS V1.1/S18030001



10. Location of measuring accelerometer attached (Y axis): DCS V1.1/S18030001



11. Location of measuring accelerometer attached (X axis): DCS V1.1/S18030001



12. Vibration Test: X axis DCS V1.1/S18030001, S18030002

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sus.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sus.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Report No.: HC30221B/2018

Page: 10 of 11

Test Photos--Continued:



13. Vibration Test: Y axis DCS V1.1/S18030001, S18030002



14. Vibration Test: Z axis DCS V1.1/S18030001, S18030002



15. Location of measuring accelerometer attached 16. Location of measuring accelerometer attached (X axis): DCS V2.1/S18030002



(Y axis): DCS V2.1/S18030002



17. Location of measuring accelerometer attached (Z axis): DCS V2.1/S18030002



18. Vibration Test: X axis DCS V2.1/S18030002, S18030004

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sus.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sus.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.



Report No.: HC30221B/2018

Page: 11 of 11

Test Photos--Continued:



19. Vibration Test: Y axis DCS V2.1/S18030002, S18030004



20. Vibration Test: Z axis DCS V2.1/S18030002, S18030004

-The End of Test Report

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明,此報告結果僅對測試之樣品負責,同時此樣品僅保留 90 天。本報告未經本公司書面許可,不可部份複製。 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sus.com/terms and conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sus.com/terms e-document.htm, Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.

No.31, No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, New Taipei City, Taiwan/新北市五股工業區五權路 31 號, 33 號, 35 號

台灣檢驗科技股份有限公司

t (886-2) 2299-3279 f (886-2) 2299-9558

www.tw.sgs.com

Member of SGS Group