Normal

Unit ID: **1230**

Asset ID: **51782513**

Description: **982m**

Account Information

ID: **402009**

Name: **Greer Lime**

Address: **1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US**

Parent Account: **MATTHEWS LUBRICANTS, INC.**

Sample Information

Sample ID: **25286131063**

Service Level: **Essential**

Bottle ID: **a037041084**

Tested Lubricant: **MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50**

Equipment Information

Asset Class: **Final Drive**

Position: **REAR RIGHT**

Manufacturer: **CATERPILLAR**

Model:

Lubricant: **MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50**

Sample Data & Trends

Sample Info	Report Status	Alert	Normal	Alert	Normal
	Sample ID	**23075470061**	**23205380057**	**25059439033**	**25286131063**
	Service Level	Essential	Essential	Essential	Essential
	Bottle ID	a022170779	a006231468	a033563053	a037041084
	Tested Lubricant	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50
	Sampled	**08 Mar 2023**	**18 Jul 2023**	**03 Feb 2025**	**10 Sep 2025**
	Reported	20 Mar 2023	25 Jul 2023	04 Mar 2025	15 Oct 2025
	Equipment Age	12462	12922	16301	17417
	Equipment UOM	Hours	Hours	Hours	Hours
	Oil Age				
	Make-up Volume				
	Oil Changed	No	No	Yes	No
	Filter Changed	No	No	Yes	No
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal
	Equipment Rating	Alert	Normal	Alert	Normal
	Lubricant Rating	Alert	Normal	Normal	Normal
	Visc@100C (cSt)	10.5	16.6	16.7	16.7
	Oxidation (Ab/cm)	4	0	0	0
	Water (Vol.%)	NotDetected	NotDetected	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	0	0	0	0
	Al (Aluminum)	17	2	7	4
	Cr (Chromium)	1	0	0	0
	Cu (Copper)	169	16	63	0
	Fe (Iron)	173	16	266	29
	Mo (Molybdenum)	3	1	3	0
	Ni (Nickel)	1	0	0	1
	Pb (Lead)	0	0	0	0
	Sn (Tin)	0	0	1	0
Contaminant (ppm)	K (Potassium)	0	0	3	2
	Na (Sodium)	3	0	1	1
	Si (Silicon)	7	4	13	16
Additive (ppm)	B (Boron)	13	1	3	129
	Ba (Barium)	0	0	0	0
	Ca (Calcium)	2604	2614	3345	16
	Mg (Magnesium)	30	12	20	3
	P (Phosphorus)	998	771	929	1027
	Zn (Zinc)	1067	854	1083	11







Normal	
Unit ID: **1230**	Asset ID: **51782513**
Description: **982m**	

Account Information

ID: **402009**

Name: **Greer Lime**

Address: **1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US**

Parent Account: **MATTHEWS LUBRICANTS, INC.**

Sample Information

Sample ID: **25286131063**

Service Level: **Essential**

Bottle ID: **a037041084**

Tested Lubricant: **MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50**

Equipment Information

Asset Class: **Final Drive**

Position: **REAR RIGHT**

Manufacturer: **CATERPILLAR**

Model:

Lubricant: **MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50**

Continued



Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 10 Sep 2025 3:17 PM UTC - Josh Simmons - In Service Oil Sample   Comments: Photo: