





## Sample Data & Trends

| Sample Info              | Report Status    | Caution              | Alert        | Alert        | Alert        | Caution      |
|--------------------------|------------------|----------------------|--------------|--------------|--------------|--------------|
|                          | Sample ID        | 24145418052          | 24240194012  | 24312210013  | 25069424013  | 25154217074  |
|                          | Service Level    | Essential            | Essential    | Essential    | Essential    | Essential    |
|                          | Bottle ID        | a012561168           | a029568154   | a033577348   | a003623639   | a003624013   |
|                          | Tested Lubricant | MOBIL DTE BB         | MOBIL DTE BB | MOBIL DTE BB | MOBIL DTE BB | MOBIL DTE BB |
|                          | Sampled          | 14 May 2024          | 09 Aug 2024  | 25 Oct 2024  | 04 Mar 2025  | 21 May 2025  |
|                          | Reported         | 06 Jun 2024          | 05 Sep 2024  | 11 Nov 2024  | 12 Mar 2025  | 05 Jun 2025  |
|                          | Equipment Age    |                      |              |              |              |              |
|                          | Oil Age          |                      |              |              |              |              |
|                          | Make-up Volume   |                      |              |              |              |              |
|                          | Oil Changed      |                      |              |              |              |              |
|                          | Filter Changed   |                      |              |              |              |              |
|                          | Lubricant        | Contamination Rating | Normal       | Normal       | Normal       | Normal       |
| Equipment Rating         |                  | Caution              | Alert        | Alert        | Alert        | Caution      |
| Lubricant Rating         |                  | Normal               | Normal       | Normal       | Normal       | Normal       |
| Visc@40C (cSt)           |                  | 230.4                | 235.1        | 234.0        | 235.3        | 230.0        |
| Oxidation (Abs/cm) D7414 |                  | 3                    | 3            | 6            | 3            | 3            |
| Water (Hot Plate)        |                  | NotDetected          | NotDetected  | NotDetected  | NotDetected  | NotDetected  |
| Wear (ppm)               | Ag (Silver)      | 0                    | 0            | 0            | 0            | 0            |
|                          | Al (Aluminum)    | 1                    | 0            | 0            | 0            | 0            |
|                          | Cr (Chromium)    | 0                    | 1            | 1            | 0            | 0            |
|                          | Cu (Copper)      | 12                   | 16           | 21           | 22           | 12           |
|                          | Fe (Iron)        | 45                   | 51           | 73           | 72           | 47           |
|                          | Mo (Molybdenum)  | 2                    | 2            | 1            | 2            | 2            |
|                          | Ni (Nickel)      | 0                    | 0            | 0            | 0            | 0            |
|                          | Pb (Lead)        | 0                    | 1            | 1            | 2            | 2            |
|                          | Sn (Tin)         | 0                    | 1            | 1            | 2            | 1            |
| Contaminant (ppm)        | K (Potassium)    | 1                    | 1            | 1            | 0            | 1            |
|                          | Na (Sodium)      | 0                    | 0            | 0            | 0            | 0            |
|                          | Si (Silicon)     | 9                    | 12           | 8            | 8            | 11           |
| Additive (ppm)           | B (Boron)        | 0                    | 0            | 0            | 0            | 1            |
|                          | Ba (Barium)      | 0                    | 0            | 0            | 0            | 0            |
|                          | Ca (Calcium)     | 138                  | 109          | 130          | 123          | 45           |
|                          | Mg (Magnesium)   | 1                    | 1            | 1            | 1            | 0            |
|                          | P (Phosphorus)   | 424                  | 400          | 360          | 417          | 487          |
|                          | Zn (Zinc)        | 10                   | 10           | 9            | 10           | 6            |

### Viscosity

| Date        | Visc@40C (cSt) |
|-------------|----------------|
| 14 May 2024 | 230.5          |
| 09 Aug 2024 | 235.5          |
| 25 Oct 2024 | 234.0          |
| 04 Mar 2025 | 235.5          |
| 21 May 2025 | 230.0          |



**Wear**

100


50

0

14 May 2024 09 Aug 2024 25 Oct 2024 04 Mar 2025 21 May 2025

Ag (Silver)  
Al (Aluminum)  
Cr (Chromium)  
Cu (Copper)  
Fe (Iron)  
Ni (Nickel)  
Pb (Lead)  
Sn (Tin)


| Date        | Ag (Silver) | Al (Aluminum) | Cr (Chromium) | Cu (Copper) | Fe (Iron) | Ni (Nickel) | Pb (Lead) | Sn (Tin) |
|-------------|-------------|---------------|---------------|-------------|-----------|-------------|-----------|----------|
| 14 May 2024 | 0           | 0             | 0             | 15          | 45        | 0           | 0         | 0        |
| 09 Aug 2024 | 0           | 0             | 0             | 18          | 52        | 0           | 0         | 0        |
| 25 Oct 2024 | 0           | 0             | 0             | 22          | 75        | 0           | 0         | 0        |
| 04 Mar 2025 | 0           | 0             | 0             | 24          | 74        | 0           | 0         | 0        |
| 21 May 2025 | 0           | 0             | 0             | 14          | 48        | 0           | 0         | 0        |



### Contaminants

The chart displays the concentration of three contaminants (Na, K, and Si) in mg/L over time. The y-axis ranges from 0 to 15 mg/L. The x-axis shows dates from May 2024 to May 2025. Si (Silicon) is the most prominent contaminant, with concentrations ranging from approximately 8 to 12.5 mg/L. Na (Sodium) and K (Potassium) concentrations are generally low, mostly below 1 mg/L, with a slight increase in May 2025.


| Date        | Na (Sodium) (mg/L) | K (Potassium) (mg/L) | Si (Silicon) (mg/L) |
|-------------|--------------------|----------------------|---------------------|
| 14 May 2024 | 0.3                | 1.2                  | 9.2                 |
| 09 Aug 2024 | 0.3                | 1.2                  | 12.5                |
| 25 Oct 2024 | 0.3                | 1.2                  | 8.2                 |
| 04 Mar 2025 | 0.3                | 0.3                  | 8.2                 |
| 21 May 2025 | 0.3                | 1.2                  | 11.2                |



### Physical Properties

The graph displays two data series over time. The 'Water (Hot Plate)' series is a flat line at 0. The 'Oxidation (Abs/cm)– no Ref' series shows a peak in oxidation at 25 Oct 2024.

| Date        | Water (Hot Plate) | Oxidation (Abs/cm)– no Ref |
|-------------|-------------------|----------------------------|
| 14 May 2024 | 0                 | 3.0                        |
| 09 Aug 2024 | 0                 | 3.0                        |
| 25 Oct 2024 | 0                 | 6.0                        |
| 04 Mar 2025 | 0                 | 3.0                        |
| 21 May 2025 | 0                 | 3.0                        |



|                                                                                                                                                        |                                                                                                               |                                                                                       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|                                                                         | Caution                                                                                                       |                                                                                       |
|                                                                                                                                                        | Unit ID: 2-vs-1 lower                                                                                         | Asset ID: 50090471                                                                    |
|                                                                                                                                                        | Description: 2-vs-1 lower                                                                                     |                                                                                       |
| Account Information                                                                                                                                    | Sample Information                                                                                            | Equipment Information                                                                 |
| ID: 402009<br>Name: Greer Lime<br>Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US<br>Parent Account: MATTHEWS LUBRICANTS, INC. | Sample ID: 25154217074<br>Service Level: Essential<br>Bottle ID: a003624013<br>Tested Lubricant: MOBIL DTE BB | Asset Class: Circulating System<br>Manufacturer:<br>Model:<br>Lubricant: MOBIL DTE BB |

Continued

Recommendation/Comments

ACTION REQUIRED - ELEVATED IRON LEVEL. Determine source of Iron (Fe) and take corrective action. If the iron level is elevated for the first time with no history of an increasing trend, then resample immediately to confirm condition. Possible sources of iron include: a. Machinery component wear; b. Metal-to-metal contact; c. Corrosion; d. Abrasive dirt contamination. The oil may be unfit for continued use and should be closely monitored for further condition regressions. Inspect the equipment for signs of damage. Change the oil after corrective measures have been implemented. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 21 May 2025 8:54 AM UTC - Brad Roy - In Service Oil Sample    Comments:    Photo: