








Sample Data & Trends

Sample Info	Report Status	Normal	Normal	Normal	Normal	Normal
	Sample ID	22124148032	23044400036	23163399068	24010131040	25296320028
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a023860255	a022174969	a022174265	a030128869	a037298205
	Tested Lubricant	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50
	Sampled	21 Apr 2022	08 Feb 2023	26 Apr 2023	27 Dec 2023	13 Oct 2025
	Reported	12 May 2022	16 Feb 2023	14 Jun 2023	15 Jan 2024	24 Oct 2025
	Equipment Age	24967	26248	26966	28106	31400
	Equipment UOM	Hours	Hours	Hours	Hours	Hours
	Oil Age					
	Make-up Volume					
	Oil Changed	No	No	No	Yes	No
Filter Changed	No	No	No	Yes	No	
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Normal	Normal
	Lubricant Rating	Normal	Normal	Normal	Normal	Normal
	Visc@100C (cSt)	16.4	16.5	16.3	16.3	16.8
	Oxidation (Ab/cm)	0	0	0	0	1
	Water (Vol.%)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	1	1	1	1	1
	Cr (Chromium)	0	0	0	0	0
	Cu (Copper)	2	3	3	6	1
	Fe (Iron)	8	9	8	14	7
	Mo (Molybdenum)	1	1	1	2	1
	Ni (Nickel)	0	0	1	1	0
	Pb (Lead)	0	1	1	0	0
	Sn (Tin)	0	0	0	0	0
Contaminant (ppm)	K (Potassium)	0	2	0	2	1
	Na (Sodium)	2	3	1	2	1
	Si (Silicon)	5	5	4	5	17
Additive (ppm)	B (Boron)	1	1	1	1	8
	Ba (Barium)	0	0	0	0	0
	Ca (Calcium)	2875	2571	2371	3023	3752
	Mg (Magnesium)	14	13	12	15	23
	P (Phosphorus)	972	935	967	995	1005
	Zn (Zinc)	1103	932	995	1110	1151



	Normal	
	Unit ID: 1112	Asset ID: 50203173
	Description: Cat 775F Diff	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25296320028 Service Level: Essential Bottle ID: a037298205 Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50	Asset Class: Differential Manufacturer: Model: Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 13 Oct 2025 3:10 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: