

MobilTM

Unit ID: 1230

Asset ID: 51782503

Description: 982 m loader

Normal

Account Information

ID: 402009

Name: Greer Lime

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample Information

Sample ID: 25286289071

Service Level: Essential

Bottle ID: a037063414

Tested Lubricant: MOBIL DELVAC 1 TRANS FLUID 50

Equipment Information

Asset Class: Differential

Position: FRONT




Manufacturer: CATERPILLAR

Model:


Lubricant: MOBIL DELVAC 1 TRANS FLUID 50

Sample Data & Trends

Sample Info	Report Status	Alert	Normal	Normal	Normal	Normal
	Sample ID	23075470059	23205380059	23313169002	25059439023	25286289071
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a022174224	a006487331	a026530217	a033594053	a037063414
	Tested Lubricant	MOBIL DELVAC 1 TRANS FLUID 50	MOBIL DELVAC 1 TRANS FLUID 50	MOBIL DELVAC 1 TRANS FLUID 50	MOBIL DELVAC 1 TRANS FLUID 50	MOBIL DELVAC 1 TRANS FLUID 50
	Sampled	08 Mar 2023	18 Jul 2023	04 Oct 2023	03 Feb 2025	10 Sep 2025
	Reported	20 Mar 2023	25 Jul 2023	11 Nov 2023	04 Mar 2025	14 Oct 2025
	Equipment Age	12462	12922	13222	16304	17417
	Equipment UOM	Hours	Hours	Hours	Hours	Hours
	Oil Age					
	Make-up Volume					
	Oil Changed	No	No	No	Yes	No
	Filter Changed	No	No	No	Yes	No
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Normal	Normal
	Lubricant Rating	Alert	Normal	Normal	Normal	Normal
	Visc@100C (cSt)	10.5	16.6	16.6	16.7	16.5
	TAN (mg KOH/g)	0.96	1.42	1.06	1.40	1.28
	Water (Vol.%)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	5	1	2	2	1
	Cr (Chromium)	1	0	0	0	0
	Cu (Copper)	29	2	4	4	2
	Fe (Iron)	121	12	17	29	14
	Mo (Molybdenum)	2	1	1	2	1
	Ni (Nickel)	0	0	0	0	0
	Pb (Lead)	0	0	0	0	0
	Sn (Tin)	1	0	0	2	0
Contaminant (ppm)	K (Potassium)	0	0	0	2	1
	Na (Sodium)	2	0	1	1	1
	Si (Silicon)	17	6	7	13	16
Additive (ppm)	B (Boron)	9	1	3	2	3
	Ba (Barium)	0	0	0	0	0
	Ca (Calcium)	2513	2617	3520	3540	3516
	Mg (Magnesium)	32	13	16	21	14
	P (Phosphorus)	952	777	971	977	938
	Zn (Zinc)	1026	874	1116	1136	1127



MobilTM	Normal	
	Unit ID: 1230	Asset ID: 51782503
	Description: 982 m loader	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25286289071 Service Level: Essential Bottle ID: a037063414 Tested Lubricant: MOBIL DELVAC 1 TRANS FLUID 50	Asset Class: Differential Position: FRONT Manufacturer: CATERPILLAR Model: Lubricant: MOBIL DELVAC 1 TRANS FLUID 50
Continued		



Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 10 Sep 2025 3:04 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: