





Sample Data & Trends

Sample Info	Report Status	Normal	Normal	Normal	Normal	Normal
	Sample ID	23075470058	23205380060	23313169011	25059439026	25286289073
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a022168595	a006487365	a026561490	a033583218	a037043480
	Tested Lubricant	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBILTRANS HD 30	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30
	Sampled	08 Mar 2023	18 Jul 2023	04 Oct 2023	03 Feb 2025	10 Sep 2025
	Reported	20 Mar 2023	25 Jul 2023	11 Nov 2023	04 Mar 2025	14 Oct 2025
	Equipment Age	12462	12922	13222	16304	
	Equipment UOM	Hours	Hours	Hours	Hours	
	Oil Age					1000
	Oil UOM					Hours
	Make-up Volume					
Lubricant	Oil Changed	Yes	No	No	Yes	Yes
	Filter Changed	Yes	Yes	No	Yes	Yes
	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Normal	Normal
	Lubricant Rating	Normal	Normal	Normal	Normal	Normal
	Visc@100C (cSt)	10.1	9.8	9.9	10.5	10.6
Wear (ppm)	Oxidation (Ab/cm)	3	3	3	2	3
	Water (Vol.%)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	2	3	2	1	1
	Cr (Chromium)	0	0	0	0	0
	Cu (Copper)	10	8	10	4	2
	Fe (Iron)	58	49	59	24	13
	Mo (Molybdenum)	2	2	3	2	2
	Ni (Nickel)	0	0	0	0	0
Contaminant (ppm)	Pb (Lead)	1	1	1	0	0
	Sn (Tin)	0	0	0	2	0
	K (Potassium)	1	2	1	2	0
Additive (ppm)	Na (Sodium)	3	2	4	2	2
	Si (Silicon)	4	5	4	4	5
	B (Boron)	11	10	13	6	5
	Ba (Barium)	1	0	0	0	0
	Ca (Calcium)	2505	2290	2800	3039	3453
	Mg (Magnesium)	35	35	41	25	21
	P (Phosphorus)	932	839	974	927	960
	Zn (Zinc)	1026	956	1109	1073	1143



	Normal	
	Unit ID: 1230	Asset ID: 51782506
	Description: 982 m	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25286289073 Service Level: Essential Bottle ID: a037043480 Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30	Asset Class: Transmission Manufacturer: CATERPILLAR Model: Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 30

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 10 Sep 2025 3:05 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: