

Mobil™

Unit ID: 1230

Asset ID: 51782509

Description: 982 m

Normal

Account Information

Sample Information

Equipment Information

ID: 402009

Name: Greer Lime

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample ID: 25286276020

Service Level: Essential

Bottle ID: a037064766

Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50

Asset Class: Differential

Position: REAR




Manufacturer:

Model:


Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50

Sample Data & Trends

Sample Info	Report Status	Alert	Normal	Normal	Normal	Normal
	Sample ID	23075470056	23205380056	23313169008	25059466032	25286276020
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a022170310	a006106173	a026564419	a033559154	a037064766
	Tested Lubricant	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50
	Sampled	08 Mar 2023	18 Jul 2023	04 Oct 2023	03 Feb 2025	10 Sep 2025
	Reported	20 Mar 2023	25 Jul 2023	11 Nov 2023	04 Mar 2025	15 Oct 2025
	Equipment Age	12462	12922	13222	16304	17417
	Equipment UOM	Hours	Hours	Hours	Hours	Hours
	Oil Age					
	Make-up Volume					
	Oil Changed	No	No	No	Yes	No
	Filter Changed	No	No	No	Yes	No
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Alert	Normal	Normal	Normal	Normal
	Lubricant Rating	Alert	Normal	Normal	Normal	Normal
	Visc@100C (cSt)	10.4	16.6	16.6	16.6	16.7
	Oxidation (Ab/cm)	4	0	0	0	1
	Water (Vol.%)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	18	2	4	2	5
	Cr (Chromium)	1	0	0	0	0
	Cu (Copper)	179	14	26	27	39
	Fe (Iron)	176	15	28	55	202
	Mo (Molybdenum)	3	1	1	2	1
	Ni (Nickel)	1	0	0	0	1
	Pb (Lead)	0	0	0	2	0
	Sn (Tin)	0	0	1	0	1
Contaminant (ppm)	K (Potassium)	0	1	0	4	0
	Na (Sodium)	4	0	1	1	1
	Si (Silicon)	7	4	6	6	17
Additive (ppm)	B (Boron)	15	2	3	3	5
	Ba (Barium)	0	0	0	0	0
	Ca (Calcium)	2632	2619	3479	2863	3332
	Mg (Magnesium)	31	13	16	17	14
	P (Phosphorus)	997	769	986	802	893
	Zn (Zinc)	1071	870	1107	928	1052



Mobil™	Normal	
	Unit ID: 1230	Asset ID: 51782509
	Description: 982 m	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25286276020 Service Level: Essential Bottle ID: a037064766 Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50	Asset Class: Differential Position: REAR Manufacturer: Model: Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50
Continued		



Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 10 Sep 2025 3:03 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: