

Mobil™

Unit ID: 1230

Asset ID: 51782512

Description: 982m

Normal

Account Information

ID: 402009
Name: Greer Lime
Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US
Parent Account: MATTHEWS LUBRICANTS, INC.

Sample Information




Sample ID: 25286289076
Service Level: Essential
Bottle ID: a037064873
Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50

Equipment Information

Asset Class: Final Drive
Position: FRONT LEFT
Manufacturer: CATERPILLAR
Model:
Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50


Sample Data & Trends

Sample Info	Report Status	Alert	Normal	Normal	Normal
	Sample ID	23075470050	23205189003	25059466036	25286289076
	Service Level	Essential	Essential	Essential	Essential
	Bottle ID	a022174434	a006229899	a033593801	a037064873
	Tested Lubricant	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBILTRANS HD 50	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50
	Sampled	08 Mar 2023	18 Jul 2023	03 Feb 2025	10 Sep 2025
	Reported	20 Mar 2023	26 Jul 2023	04 Mar 2025	14 Oct 2025
	Equipment Age	12462	12922	16302	17417
	Equipment UOM	Hours	Hours	Hours	Hours
	Oil Age				
	Make-up Volume				
	Oil Changed	No	No	Yes	No
Lubricant	Filter Changed	No	No	Yes	No
	Contamination Rating	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Normal
	Lubricant Rating	Alert	Normal	Normal	Normal
	Visc@100C (cSt)	10.6	16.6	16.7	16.5
	Oxidation (Ab/cm)	1	0	0	0
Wear (ppm)	Water (Vol.%)	NotDetected	NotDetected	NotDetected	NotDetected
	Ag (Silver)	0	1	0	0
	Al (Aluminum)	5	1	1	2
	Cr (Chromium)	1	0	0	0
	Cu (Copper)	28	4	4	2
	Fe (Iron)	114	15	25	17
	Mo (Molybdenum)	2	1	2	1
	Ni (Nickel)	0	0	0	0
	Pb (Lead)	0	0	0	0
Contaminant (ppm)	Sn (Tin)	0	0	0	0
	K (Potassium)	0	0	4	0
	Na (Sodium)	2	1	1	1
	Si (Silicon)	16	8	10	17
Additive (ppm)	B (Boron)	8	2	3	3
	Ba (Barium)	0	0	0	0
	Ca (Calcium)	2510	3243	2977	3613
	Mg (Magnesium)	32	15	21	14
	P (Phosphorus)	944	901	807	979
	Zn (Zinc)	1022	1017	939	1165



	Normal	
	Unit ID: 1230	Asset ID: 51782512
	Description: 982m	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25286289076 Service Level: Essential Bottle ID: a037064873 Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50	Asset Class: Final Drive Position: FRONT LEFT Manufacturer: CATERPILLAR Model: Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50
Continued		

Physical Properties



Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 10 Sep 2025 3:18 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: