





Sample Data & Trends

Sample Info	Report Status	Normal	Normal	Normal	Normal	Normal
	Sample ID	24039222031	24330195067	25059466034	25111107066	25286289074
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a030127797	a033570666	a033569982	A033679853	a037055014
	Tested Lubricant	MOBILTRANS HD 10W	MOBILTRANS HD 10W	MOBILTRANS HD 10W	MOBILTRANS HD 10W	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W
	Sampled	30 Jan 2024	29 Oct 2024	20 Jan 2025	01 Apr 2025	10 Sep 2025
	Reported	12 Feb 2024	26 Nov 2024	04 Mar 2025	22 Apr 2025	14 Oct 2025
	Equipment Age	57117	58702	5394	60106	61231
	Equipment UOM	Hours	Hours	Hours	Hours	Hours
	Oil Age					
	Make-up Volume					
	Oil Changed	Yes	No	Yes	Yes	Yes
	Filter Changed	Yes	No	Yes	Yes	Yes
Lubricant	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Normal	Normal
	Lubricant Rating	Normal	Normal	Normal	Normal	Normal
	Visc@100C (cSt)	6.3	6.2	6.2	6.0	6.0
	Oxidation (Ab/cm)	1	2	2		3
	Water (Vol.%)	NotDetected	NotDetected	NotDetected		NotDetected
Wear (ppm)	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	3	3	3	6	3
	Cr (Chromium)	1	1	1	0	0
	Cu (Copper)	1	2	2	1	1
	Fe (Iron)	7	7	10	7	6
	Mo (Molybdenum)	1	1	1	1	2
	Ni (Nickel)	0	0	0	0	0
	Pb (Lead)	0	1	1	1	1
	Sn (Tin)	0	0	0	0	0
Contaminant (ppm)	K (Potassium)	2	2	3	2	2
	Na (Sodium)	1	1	1	1	1
	Si (Silicon)	7	8	10	13	10
Additive (ppm)	B (Boron)	2	2	2	2	3
	Ba (Barium)	0	0	0	0	0
	Ca (Calcium)	2178	2920	2929	3181	3484
	Mg (Magnesium)	11	16	19	17	18
	P (Phosphorus)	682	863	798	884	928
	Zn (Zinc)	815	937	950	988	1101



	Normal	
	Unit ID: 772	Asset ID: 51852112
	Description: 980g loader	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25286289074 Service Level: Essential Bottle ID: a037055014 Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W	Asset Class: Hydraulic Manufacturer: CATERPILLAR Model: Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 10 Sep 2025 3:10 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: