





## Sample Data & Trends

|                   |                  |                      |                                                |
|-------------------|------------------|----------------------|------------------------------------------------|
| Sample Info       | Report Status    | Normal               | Alert                                          |
|                   | Sample ID        | 24330195077          | 25286131070                                    |
|                   | Service Level    | Essential            | Essential                                      |
|                   | Bottle ID        | a033567245           | a037066311                                     |
|                   | Tested Lubricant | MOBILTRANS HD 50     | MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50 |
|                   | Sampled          | 14 Nov 2024          | 10 Sep 2025                                    |
|                   | Reported         | 26 Nov 2024          | 15 Oct 2025                                    |
|                   | Equipment Age    | 9310                 |                                                |
|                   | Equipment UOM    | Hours                |                                                |
|                   | Oil Age          |                      |                                                |
|                   | Make-up Volume   |                      |                                                |
|                   | Oil Changed      | Yes                  | Yes                                            |
|                   | Filter Changed   | No                   |                                                |
|                   | Lubricant        | Contamination Rating | Normal                                         |
| Equipment Rating  |                  | Normal               | Normal                                         |
| Lubricant Rating  |                  | Normal               | Normal                                         |
| Visc@100C (cSt)   |                  | 17.4                 | 16.8                                           |
| Oxidation (Ab/cm) |                  | 0                    | 1                                              |
| Water (Vol.%)     |                  | NotDetected          | NotDetected                                    |
| Wear (ppm)        | Ag (Silver)      | 0                    | 0                                              |
|                   | Al (Aluminum)    | 4                    | 54                                             |
|                   | Cr (Chromium)    | 2                    | 3                                              |
|                   | Cu (Copper)      | 1                    | 1                                              |
|                   | Fe (Iron)        | 373                  | 349                                            |
|                   | Mo (Molybdenum)  | 0                    | 0                                              |
|                   | Ni (Nickel)      | 0                    | 3                                              |
|                   | Pb (Lead)        | 0                    | 0                                              |
| Contaminant (ppm) | Sn (Tin)         | 0                    | 0                                              |
|                   | K (Potassium)    | 2                    | 12                                             |
|                   | Na (Sodium)      | 1                    | 8                                              |
|                   | Si (Silicon)     | 24                   | 194                                            |
| Additive (ppm)    | B (Boron)        | 2                    | 60                                             |
|                   | Ba (Barium)      | 0                    | 0                                              |
|                   | Ca (Calcium)     | 3383                 | 133                                            |
|                   | Mg (Magnesium)   | 13                   | 6                                              |
|                   | P (Phosphorus)   | 959                  | 791                                            |
|                   | Zn (Zinc)        | 1015                 | 46                                             |



| <div>Mobil™</div>                                                                                                                                      | Alert                                                                                                                                           |                                                                                                                                                       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|
|                                                                                                                                                        | Unit ID: 1196                                                                                                                                   | Asset ID: 52051922                                                                                                                                    |
|                                                                                                                                                        | Description: 336 cat                                                                                                                            |                                                                                                                                                       |
| Account Information                                                                                                                                    | Sample Information                                                                                                                              | Equipment Information                                                                                                                                 |
| ID: 402009<br>Name: Greer Lime<br>Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US<br>Parent Account: MATTHEWS LUBRICANTS, INC. | Sample ID: 25286131070<br>Service Level: Essential<br>Bottle ID: a037066311<br>Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50 | Asset Class: Final Drive<br>Position: FRONT RIGHT<br>Manufacturer: CATERPILLAR<br>Model:<br>Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 50 |
| Continued                                                                                                                                              |                                                                                                                                                 |                                                                                                                                                       |

Physical Properties



Recommendation/Comments

ACTION REQUIRED - EXCESSIVE SILICON LEVEL. Determine source of excessive Silicon (Si) and take corrective action. Because wear metals levels are not also elevated, the silicon most likely exists in a non-abrasive form. Possible sources of non-abrasive silicone include: a. Defoamants, gasket or sealing compounds; b. Improper sampling / handling procedures (i.e. sample container contaminated with dirt, sample taken under conditions of high wind in a situation where dust is present, sample caps left-off the sample bottles for an extended length of time); c. Engine fuel gas that contains a non-abrasive siloxane. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 10 Sep 2025 3:25 PM UTC - Josh Simmons - In Service Oil Sample    Comments: Photo: