





Mobil™	Normal	
	Unit ID: 1246	Asset ID: 52106537
	Description: 988K LOADER	
Account Information		Equipment Information
ID: 402009		Asset Class: Hydraulic
Name: Greer Lime		Manufacturer: CATERPILLAR
Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US		Model:
Parent Account: MATTHEWS LUBRICANTS, INC.		Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W
Sample Information		
Sample ID: 25296320034		
Service Level: Essential		
Bottle ID: a037068566		
Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W		

Sample Data & Trends

Sample Info	Report Status	Normal	Normal
	Sample ID	25111107063	25296320034
	Service Level	Essential	Essential
	Bottle ID	A035388028	a037068566
	Tested Lubricant	MOBILTRANS HD 10W	MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W
	Sampled	19 Mar 2025	13 Oct 2025
	Reported	23 Apr 2025	24 Oct 2025
	Equipment Age	8978	
	Equipment UOM	Hours	
	Oil Age		
	Make-up Volume		
	Oil Changed	No	
	Filter Changed	Yes	
Lubricant	Contamination Rating	Normal	Normal
	Equipment Rating	Normal	Normal
	Lubricant Rating	Normal	Normal
	Visc@100C (cSt)	6.3	6.1
	Oxidation (Ab/cm)	2	3
	Water (Vol.%)	NotDetected	NotDetected
Wear (ppm)	Ag (Silver)	0	0
	Al (Aluminum)	2	6
	Cr (Chromium)	0	0
	Cu (Copper)	5	4
	Fe (Iron)	24	31
	Mo (Molybdenum)	1	1
	Ni (Nickel)	0	0
	Pb (Lead)	0	1
	Sn (Tin)	0	0
Contaminant (ppm)	K (Potassium)	3	3
	Na (Sodium)	1	1
	Si (Silicon)	6	11
Additive (ppm)	B (Boron)	10	6
	Ba (Barium)	0	0
	Ca (Calcium)	1563	2957
	Mg (Magnesium)	15	15
	P (Phosphorus)	838	1005
	Zn (Zinc)	974	1158



	Normal	
	Unit ID: 1246	Asset ID: 52106537
	Description: 988K LOADER	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25296320034 Service Level: Essential Bottle ID: a037068566 Tested Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W	Asset Class: Hydraulic Manufacturer: CATERPILLAR Model: Lubricant: MOBIL DELVAC MODERN OFF-HIGHWAY TRANS FLUID 10W

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 13 Oct 2025 3:40 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: