

Mobil<sup>TM</sup>

Unit ID: 4-RK-2

Asset ID: 50074745

Description: Kiln 1 Drive Trunion Bearing 2

Normal

Account Information

ID: 402009

Name: Greer Lime

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample Information

Sample ID: 25343187043

Service Level: Essential

Bottle ID: a037321944

Tested Lubricant: MOBIL SHC 636

Equipment Information

Asset Class: Circulating System





Manufacturer:

Model:

Lubricant: MOBIL SHC 636

Sample Data & Trends

|                   |                      |               |               |               |               |               |
|-------------------|----------------------|---------------|---------------|---------------|---------------|---------------|
| Sample Info       | Report Status        | Alert         | Alert         | Normal        | Caution       | Normal        |
|                   | Sample ID            | 24162579024   | 24205294022   | 24330183014   | 25147288004   | 25343187043   |
|                   | Service Level        | Essential     | Essential     | Essential     | Essential     | Essential     |
|                   | Bottle ID            | a003622387    | a003617644    | a033579090    | a003620081    | a037321944    |
|                   | Tested Lubricant     | MOBIL SHC 636 | MOBIL SHC 636 | MOBIL SHC 636 | MOBIL SHC 636 | MOBIL SHC 636 |
|                   | Sampled              | 03 Jun 2024   | 16 Jul 2024   | 13 Nov 2024   | 18 May 2025   | 03 Dec 2025   |
|                   | Reported             | 18 Jun 2024   | 29 Jul 2024   | 27 Nov 2024   | 29 May 2025   | 11 Dec 2025   |
|                   | Equipment Age        |               |               |               |               |               |
|                   | Oil Age              |               |               |               |               |               |
|                   | Make-up Volume       |               |               |               |               |               |
|                   | Oil Changed          |               | Yes           |               |               |               |
|                   | Filter Changed       |               |               |               |               |               |
| Lubricant         | Contamination Rating | Normal        | Normal        | Normal        | Normal        | Normal        |
|                   | Equipment Rating     | Normal        | Normal        | Normal        | Normal        | Normal        |
|                   | Lubricant Rating     | Alert         | Alert         | Normal        | Caution       | Normal        |
|                   | Visc@40C (cSt)       | 786.6         | 790.2         | 741.0         | 755.4         | 703.2         |
|                   | TAN (mg KOH/g)       | 0.40          | 0.39          | 0.41          | 0.40          | 0.41          |
|                   | Water (Hot Plate)    | NotDetected   | NotDetected   | NotDetected   | NotDetected   | NotDetected   |
| Wear (ppm)        | Ag (Silver)          | 0             | 0             | 0             | 0             | 0             |
|                   | Al (Aluminum)        | 0             | 0             | 0             | 0             | 0             |
|                   | Cr (Chromium)        | 0             | 0             | 0             | 0             | 0             |
|                   | Cu (Copper)          | 10            | 17            | 5             | 10            | 8             |
|                   | Fe (Iron)            | 2             | 3             | 1             | 3             | 8             |
|                   | Mo (Molybdenum)      | 2             | 0             | 0             | 0             | 0             |
|                   | Ni (Nickel)          | 0             | 0             | 0             | 0             | 0             |
|                   | Pb (Lead)            | 3             | 4             | 1             | 3             | 2             |
|                   | Sn (Tin)             | 0             | 0             | 0             | 1             | 1             |
| Contaminant (ppm) | K (Potassium)        | 1             | 0             | 0             | 0             | 0             |
|                   | Na (Sodium)          | 0             | 1             | 0             | 0             | 0             |
|                   | Si (Silicon)         | 2             | 3             | 3             | 4             | 11            |
|                   | B (Boron)            | 1             | 0             | 0             | 2             | 0             |
| Additive (ppm)    | Ba (Barium)          | 0             | 0             | 0             | 0             | 0             |
|                   | Ca (Calcium)         | 7             | 10            | 3             | 8             | 16            |
|                   | Mg (Magnesium)       | 0             | 0             | 0             | 0             | 1             |
|                   | P (Phosphorus)       | 327           | 347           | 344           | 372           | 491           |
|                   | Zn (Zinc)            | 1             | 0             | 1             | 1             | 1             |
|                   |                      |               |               |               |               |               |



|                                                                         | Normal                                                                                                         |                                                                                        |
|--------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------|
|                                                                                                                                                        | Unit ID: 4-RK-2                                                                                                | Asset ID: 50074745                                                                     |
|                                                                                                                                                        | Description: Kiln 1 Drive Trunion Bearing 2                                                                    |                                                                                        |
| Account Information                                                                                                                                    | Sample Information                                                                                             | Equipment Information                                                                  |
| ID: 402009<br>Name: Greer Lime<br>Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US<br>Parent Account: MATTHEWS LUBRICANTS, INC. | Sample ID: 25343187043<br>Service Level: Essential<br>Bottle ID: a037321944<br>Tested Lubricant: MOBIL SHC 636 | Asset Class: Circulating System<br>Manufacturer:<br>Model:<br>Lubricant: MOBIL SHC 636 |

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- [03 Dec 2025 10:03 PM UTC - Shawn Turner - In Service Oil Sample](#)    Comments:    Photo: