



Normal

Description: **Hyd pump**

Description: **Hyd pump**

Description: **Hyd pump**

Account Information

ID: **402009**
Name: **Greer Lime**
Address: **1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US**
Parent Account: **MATTHEWS LUBRICANTS, INC.**

ID: **402009**
Name: **Greer Lime**
Address: **1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US**
Parent Account: **MATTHEWS LUBRICANTS, INC.**

ID: **402009**
Name: **Greer Lime**
Address: **1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US**
Parent Account: **MATTHEWS LUBRICANTS, INC.**

ID: **402009**
Name: **Greer Lime**
Address: **1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US**
Parent Account: **MATTHEWS LUBRICANTS, INC.**

Sample ID: 25342194031

Service Level: **Essential**

Bottle ID: a003618789

Tested Lubricant: **QUAKER QUINTOLUBRIC 888-46**

Sample ID: 25342194031

Service Level: **Essential**

Bottle ID: a003618789

Tested Lubricant: **QUAKER QUINTOLUBRIC 888-46**

Sample ID: 25342194031

Service Level: **Essential**

Bottle ID: a003618789

Tested Lubricant: **QUAKER QUINTOLUBRIC 888-46**

Sample ID: 25342194031

Service Level: **Essential**

Bottle ID: a003618789

Tested Lubricant: **QUAKER QUINTOLUBRIC 888-46**

Asset Class: **Hydraulic**
Manufacturer:
Model:
Lubricant: **QUAKER QUINTOLUBRIC 888-46**





Asset Class: **Hydraulic**
Manufacturer:
Model:
Lubricant: **QUAKER QUINTOLUBRIC 888-46**

Asset Class: **Hydraulic**
Manufacturer:
Model:
Lubricant: **QUAKER QUINTOLUBRIC 888-46**

Asset Class: **Hydraulic**
Manufacturer:
Model:
Lubricant: **QUAKER QUINTOLUBRIC 888-46**

Sample Data & Trends

Sample Info	Report Status	Alert	Caution	Alert	Alert	Normal
	Sample ID	23321203011	24162569028	24330410035	25147427031	25342194031
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a030116715	a029201556	a033578997	a033685875	a003618789
	Tested Lubricant	QUAKER QUINTOLUBRIC 888-46	QUAKER QUINTOLUBRIC 888-46	QUAKER QUINTOLUBRIC 888-46	QUAKER QUINTOLUBRIC 888-46	QUAKER QUINTOLUBRIC 888-46
	Sampled	09 Nov 2023	03 Jun 2024	13 Nov 2024	18 May 2025	03 Dec 2025
	Reported	21 Nov 2023	19 Jun 2024	27 Nov 2024	29 May 2025	10 Dec 2025
	Equipment Age					
	Oil Age					
	Make-up Volume					
Lubricant	Oil Changed					
	Filter Changed					
	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Normal	Normal
	Lubricant Rating	Alert	Caution	Alert	Alert	Normal
	Visc@40C (cSt)	64.1	55.5	58.0	58.8	50.8
Wear (ppm)	TAN (mg KOH/g)	1.64	1.27	1.42	1.34	0.86
	Water (Hot Plate)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	0	0	0	0	0
	Cr (Chromium)	0	1	0	0	0
	Cu (Copper)	1	1	3	3	6
	Fe (Iron)	28	13	12	11	35
	Mo (Molybdenum)	0	0	0	0	0
	Ni (Nickel)	0	1	0	0	0
Contaminant (ppm)	Pb (Lead)	0	0	1	1	0
	Sn (Tin)	327	281	277	268	233
	K (Potassium)	0	2	2	3	0
Additive (ppm)	Na (Sodium)	2	2	2	1	2
	Si (Silicon)	3	2	2	2	1
	B (Boron)	1	1	1	2	0
	Ba (Barium)	0	0	0	0	0
	Ca (Calcium)	8	6	7	65	71
	Mg (Magnesium)	0	0	0	1	2
	P (Phosphorus)	112	109	134	116	216
	Zn (Zinc)	11	6	41	38	171



	Normal	
	Unit ID: 4-phu-1	Asset ID: 50326099
	Description: Hyd pump	

Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25342194031 Service Level: Essential Bottle ID: a003618789 Tested Lubricant: QUAKER QUINTOLUBRIC 888-46	Asset Class: Hydraulic Manufacturer: Model: Lubricant: QUAKER QUINTOLUBRIC 888-46

Continued

Recommendation/Comments

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 03 Dec 2025 10:26 PM UTC - Shawn Turner - In Service Oil Sample Comments: Photo: