

MobilTM

Unit ID: 1-VS-1 lower

Asset ID: 50074729

Description: Primary Crushing Diester Screen

Account Information

Sample Information

Equipment Information

ID: 402009

Name: Greer Lime

Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US

Parent Account: MATTHEWS LUBRICANTS, INC.

Sample ID: 25296247001

Service Level: Essential

Bottle ID: a037318531

Tested Lubricant: MOBIL SHC 630

Asset Class: Circulating System





Manufacturer: Diester

Model:

Lubricant: MOBIL SHC 630

Sample Data & Trends

Sample Info	Report Status	Alert	Alert	Normal	Alert	Normal
	Sample ID	23075409006	23075409007	23205239009	25062410052	25296247001
	Service Level	Essential	Essential	Essential	Essential	Essential
	Bottle ID	a023847149	a022173908	a006105518	a033568699	a037318531
	Tested Lubricant	MOBIL DTE BB	MOBIL DTE BB	MOBIL DTE BB	MOBIL DTE PM 220	MOBIL SHC 630
	Sampled	10 Mar 2023	10 Mar 2023	13 Jul 2023	05 Feb 2025	27 Aug 2025
	Reported	20 Mar 2023	20 Mar 2023	26 Jul 2023	05 Mar 2025	25 Oct 2025
	Equipment Age					
	Oil Age				6	
	Oil UOM				Months	
	Make-up Volume					
	Oil Changed			Yes	Yes	
Lubricant	Filter Changed				Yes	
	Contamination Rating	Normal	Normal	Normal	Normal	Normal
	Equipment Rating	Normal	Normal	Normal	Alert	Normal
	Lubricant Rating	Alert	Alert	Normal	Normal	Normal
	Visc@40C (cSt)	318.0	316.1	223.1	230.2	220.6
	Oxidation (Abs/cm) D7414	4	4	3	4	
	TAN (mg KOH/g)					0.44
Wear (ppm)	Water (Hot Plate)	NotDetected	NotDetected	NotDetected	NotDetected	NotDetected
	Ag (Silver)	0	0	0	0	0
	Al (Aluminum)	1	1	0	1	0
	Cr (Chromium)	0	0	0	0	0
	Cu (Copper)	36	30	6	76	10
	Fe (Iron)	38	20	6	43	24
	Mo (Molybdenum)	0	0	1	0	0
	Ni (Nickel)	0	0	0	0	0
	Pb (Lead)	5	0	1	4	2
Contaminant (ppm)	Sn (Tin)	0	0	0	0	1
	K (Potassium)	1	1	0	0	1
	Na (Sodium)	0	0	0	0	0
	Si (Silicon)	2	2	9	8	9
Additive (ppm)	B (Boron)	16	7	0	2	2
	Ba (Barium)	1	12	0	0	0
	Ca (Calcium)	88	6	34	21	7
	Mg (Magnesium)	2	2	0	0	0
	P (Phosphorus)	242	224	435	352	461
	Zn (Zinc)	27	22	6	74	2



	Normal	
	Unit ID: 1-VS-1 lower	Asset ID: 50074729
	Description: Primary Crushing Diester Screen	
Account Information	Sample Information	Equipment Information
ID: 402009 Name: Greer Lime Address: 1088 Germany Valley Limestone Road, Riverton, WV 26814-0000 US Parent Account: MATTHEWS LUBRICANTS, INC.	Sample ID: 25296247001 Service Level: Essential Bottle ID: a037318531 Tested Lubricant: MOBIL SHC 630	Asset Class: Circulating System Manufacturer: Diester Model: Lubricant: MOBIL SHC 630
Continued		
Recommendation/Comments		

NO ACTION REQUIRED ON OIL OR EQUIPMENT. Results indicate that all levels are within acceptable ranges. Examine progressive changes and monitor results for changing trends. Sample at next scheduled interval. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 13 Oct 2025 3:36 PM UTC - Josh Simmons - In Service Oil Sample Comments: Photo: